

Appendix C

Field Notes



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
↳ NO ACCESS
↳ NO PICS
↳ NO GPS

Station # 1-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keene, K. Clayton
 Date June 22/12 Time _____
 Weather conditions in previous 24 hrs hot & humid ~32°C +
 GPS Coordinates (Zone) 17T E N Datum NAD83
 Descriptive Location Not Rail line and Greenlane, west of Andrews Court

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 25°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 0.3 (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 2 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use orchard

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations no access

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. no access, seen from distance

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Stantec

Station # 2-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Greene, K. Clayton
 Date June 22/12 Time 10:35
 Weather conditions in previous 24 hrs hot humid ~32°C+
 GPS Coordinates (Zone) 17T E 621730 N 4781286 Datum Nad83
 Descriptive Location off of Kings Street, East of Thirty Rd

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 25°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 3.5 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock 40 Cobble _____ Sand 40 Silt _____ Muck _____
20 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

75% trees, mature
residential, bushlot, roads

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations

spawning, nursery, foraging
dry - perched culvert

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

channel is defined - has boulders &
cobble, overhanging veg is sumac, walnut, sugar maple, manitoba
maple, grape

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

outside Project Loch Aug 26 mp.

REA X

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Station # 2-2 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keene, K. Clayton
 Date June 22/12 Time 10:46
 Weather conditions in previous 24 hrs hot & humid, ~32°C+
 GPS Coordinates (Zone) 17T E 622067 N 4781132 Datum Nad83
 Descriptive Location _____

Water Quality

Dissolved Oxygen (mg/L) 8.00 pH 8.70 Conductivity (µS/cm) 835
 Water Temperature (°C) 20.10 Air Temperature (°C) 25°C
 Time *in situ* measurements taken 10:46

Watercourse Dimensions & Morphology

Mean Watercourse Width 1 (m) Maximum Pool Depth 0.20 (cm)
 Mean Bankfull Width 2.5 (m) Mean Water Depth 0.15 (cm)
50 % Riffle 30 % Pool 20 % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock 50 Cobble _____ Sand 20 Silt _____ Muck _____
20 Boulder 10 Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other algae

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

a little trickle of water in channel
defined channel in lots of gravel & cobble
shaded by jewelweed, walnuts & sugar maple
East side of Road is more open
with rock piles along bank
with soil falling on
shaded by willow
 Field Notes Authored by K. Clayton Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA²⁷

Stantec

Station # 2-3
 Watercourse Name unknown
 Photos _____
 Date June 22/12

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, K. Clayton
 Time 10:55

Weather conditions in previous 24 hrs hot & humid, ~32°C
 GPS Coordinates (Zone) 17T E 622300 N 4781050 Datum NAD83
 Descriptive Location off of King Street, east of 2-2

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 25°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width dry (m) _____ Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 2 (m) _____ Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock 50 Cobble _____ Sand 40 Silt _____ Muck _____
10 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks _____ Deep Pool _____ Watercress _____ Aquatic Veg _____
 Overhanging Vegetation _____ Woody Debris _____ Boulder _____ Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 75%, trees, mature

Adjacent Land Use

residential, Road

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) spawning, nursery, foraging

Migratory Obstructions (seasonal, permanent) dry

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

channel well defined in cobble & boulders, shaded by sumac, grape, virginia creeper, maple

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Stantec

Station # 3-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Regne, K. Clayton
 Date June 20/12 Time 1:19
 Weather conditions in previous 24 hrs hot & humid, ~32°C
 GPS Coordinates (Zone) 17T E 622156 N 4780325 Datum NAD83
 Descriptive Location off of Mainview Road, North of McLeod Rd

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 25°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.5 (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 4 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

REA has deep defined channel along Road, dominated by Typha & Phragmites, on west side of Mainview channel flows into forest. Shaded by willow, maple, grape etc.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Stantec

Station # 3-2 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos see photo log Field Staff J. Keene, K. Clayton
 Date June 22/12 Time 11:33
 Weather conditions in previous 24 hrs hot & humid ~32°C+
 GPS Coordinates (Zone) 17T E 622170 N 4779879 Datum NAD83
 Descriptive Location off of Mainview Rd, NW of McCleod Street

Water Quality

Dissolved Oxygen (mg/L) dry pH dry Conductivity (µS/cm) dry
 Water Temperature (°C) dry Air Temperature (°C) 25°C
 Time *in situ* measurements taken dry

Watercourse Dimensions & Morphology

Mean Watercourse Width 3 (m) Maximum Pool Depth dry (cm)
 Mean Bankfull Width 2 (m) Mean Water Depth dry (cm)
 % Riffle dry % Pool dry % Run dry % Flat dry
 Evidence of eroding banks, Comments on bank stability dry

Substrate (% cover)

Bedrock dry Cobble 20 Sand 50 Silt dry Muck dry
 Boulder dry Gravel 10 Clay dry Marl 20 Detritus dry

In-water Cover

Cover Types Present (circle): Undercut Banks dry Deep Pool dry Watercress dry Aquatic Veg dry
 Overhanging Vegetation dry Woody Debris dry Boulder dry Other dry

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 100% trees, mature

Adjacent Land Use

backlot, Road

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) dry

Migratory Obstructions (seasonal, permanent)

dry - perched culvert - extreme slope

Note any fish observations dry


Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel dry Grassed Swale dry Buried Tile dry
 Surficial Drainage (i.e. furrows) dry Dugout Pond dry Dominated by Aquatic Veg dry Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. channel is shallow, w/ grass, maple, sumac surrounding it.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME





WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Stantec

Station # 3-3 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos see photo log Field Staff J. Keene, K. Clayton
 Date June 22/12 Time 12:00
 Weather conditions in previous 24 hrs Hot & humid, ~32°C +
 GPS Coordinates (Zone) 17T E 622189 N 4779381 Datum NAD83
 Descriptive Location off of Mountain view Rd south of 2-2

Water Quality

No water
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 25°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 50 Silt _____ Muck _____
 Boulder 10 Gravel 30 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____ Typha
hasetail

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

95% Typha, early
Residential, Road, garden nursery

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ✓ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ✓ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

channel is defined however
possibly due to garden center next door creating a berm next
to it. Dominated by Typha. On East side it's a potential REA,
on west side it's not.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
on west side
non-REA on east side
1/9/15
on east side

Station # 4-1

Watercourse Name unknown

Photos see photo log

Date June 22/12

Weather conditions in previous 24 hrs hot & humid

GPS Coordinates (Zone) 17T E 6222 08

Project Name Niagara Wind

Project # 160958269

Field Staff J. Keene, K. Clayton

Time 12:12

Descriptive Location off of Mainview Rd. south of 3-3

Water Quality

Dissolved Oxygen (mg/L) _____ pH Dry Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) 25°C

Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.5 (m) Maximum Pool Depth _____ (cm)

Mean Bankfull Width 2 (m) Mean Water Depth _____ (cm)

_____ % Riffle _____ % Pool _____ % Run _____ % Flat

Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 80 Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl 20 Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg

Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use 15% typha, early

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel ✓ Grassed Swale ✓ Buried Tile _____

Surficial Drainage (i.e. furrows) ✓ Dugout Pond _____ Dominated by Aquatic Veg ✓ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

Small, shallow channel w aquatic veg (Typha). - Water flowing on west side, wet dry on east. West side is in a bush lot w Virginia creeper, sumac, Walnut & grape.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

No longer in Project Loc'n map.

REA X

Station # 5-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keene, K. Clayton
 Date June 22/12 Time 10:15
 Weather conditions in previous 24 hrs Hot humid, ~32°C+
 GPS Coordinates (Zone) 17T E 620602 N 4780419 Datum NAD83
 Descriptive Location off of Ridge Road East, west of Thirty Rd.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 25°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 10 (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 10 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

100 Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

45% RCG, early
Residential, Road

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

deep, defined channel
Bedrock on South side of Rd.
cobble/boulder on North side of Road & completely forested (100%
shaded) - South side open
↳ North side has summer Virginia Creeper, walnuts, river bank
grape

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

No longer in Project Locin MP

X

Station # 5-2 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff Joanne K. Clay
 Date June 22/12 Time 10:21
 Weather conditions in previous 24 hrs hot & humid ~32°C
 GPS Coordinates (Zone) 17T E 620937 N 4780534 Datum NAD83
 Descriptive Location off of Thirty Rd, N of Elm tree Rd & Valentino Rd

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 25
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 2 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock 50 Cobble _____ Sand 40 Silt _____ Muck _____
 Boulder 10 Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg TVPha
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

deep, defined channel
TVPha has cobble & boulders as substrate in underlying silt
channel goes through grape vine orchard & flows in bushlot
portion of channel that goes through bushlot - surrounded by Barr wood, walnut,
Junco, river bank grape etc - very steep on bedrock
 Field Notes Authored by K. Clayton Field Notes QA/QCed by WIS



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

*SD on West side of Thirty/Nov
*RA on east side

Station # 6-1

Watercourse Name unknown

Photos _____

Date June 22/12

Weather conditions in previous 24 hrs Hot & humid, ~32°C

GPS Coordinates (Zone) 17T E 620348

Descriptive Location off of Thirty Rd, North of Kemp Rd East

Project Name Niagara Wind

Project # 160958269

Field Staff J. Keene, K. Clayton

Time 9:48

Datum NAD83

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) 25°C

Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)

Mean Bankfull Width 10 (m) Mean Water Depth _____ (cm)

_____ % Riffle _____ % Pool _____ % Run _____ % Flat

Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____

Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg

Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

soy, pasture, grape vines

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale ✓ Buried Tile _____

Surficial Drainage (i.e. furrows) ✓ Dugout Pond _____ Dominated by Aquatic Veg ✓ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. Reed canopy grass corridor

*no real connection in culvert - lawn cut

*East side doesn't have much channel definition but RCG

has a distinct corridor. ↳ other than @ culvert

Field Notes Authored by K. Clayton

Field Notes QA/QCed by MF



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 8-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keene, K. Clayton
 Date June 22/12 Time 9:14
 Weather conditions in previous 24 hrs hot & humid ~32°C
 GPS Coordinates (Zone) 17T E 622015 N 4769769 Datum NAD83
 Descriptive Location off of Thirty Rd. ~800m N of Youngs earth of Mud Street

Water Quality

no water
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 25°C
 Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 3 (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 1.5 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt _____ Muck _____
 Boulder 10 Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

100% trees, mature
 Adjacent Land Use soy, woodlot

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawning, nursery, foraging
 Migratory Obstructions (seasonal, permanent)

dry
 Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. REA waterbody that follows the woodlot defined channel, undercut banks & dominated by aquatic vegetation

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME

Bushlot

✓ REA
8-1

— Thirty Rd —

N →



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
• More naturalized
on west side
of Rd
• Channelized
• dam by
tupelo

Station # 9-1
Watercourse Name unknown
Photos 1
Date June 20/12
Weather conditions in previous 24 hrs hot & humid
GPS Coordinates (Zone) 17T E 619250 N 4775456 Datum NAD83
Descriptive Location off of Rd 14, north of Smithville, north of Young Street
(1st crossing north of Young)

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 13:20

Water Quality

Dissolved Oxygen (mg/L) Dry pH 7.5 Conductivity (μ S/cm) 300
Water Temperature ($^{\circ}$ C) 30 Air Temperature ($^{\circ}$ C) 30
Time in situ measurements taken 13:20

Watercourse Dimensions & Morphology

Mean Watercourse Width 5-7 (m) Maximum Pool Depth 0 (cm)
Mean Bankfull Width 5-7 (m) Mean Water Depth 0 (cm)
% Riffle 0 % Pool 0 % Run 100 % Flat 0
Evidence of eroding banks, Comments on bank stability None

Substrate (% cover)

Bedrock 0 Cobble 0 Sand 0 Silt 0 Muck 0
Boulder 0 Gravel 0 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Overhanging Vegetation Undercut Banks 0 Deep Pool 0 Watercress 0 Aquatic Veg 0
Woody Debris Boulder 0 Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 100%, typha, early

Adjacent Land Use

farmland, soy

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) potential spawning in spring

Migratory Obstructions (seasonal, permanent) dry

Note any fish observations None

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel 0 Grassed Swale 0 Buried Tile 0
Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg 0 Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. None

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Non-REA²
ml-

Station # 11-1
Watercourse Name unknown
Photos _____
Date June 20/12
Weather conditions in previous 24 hrs hot & humid
GPS Coordinates (Zone) 17T E 617710
Descriptive Location off South Grimsby Rd, North of Rail Line

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 13:50
Datum NAD83

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 30°C
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 2.5 (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
100%, typha, early
Adjacent Land Use Say

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

does not qualify as intermittent stream

Field Notes Authored by K Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 11-2
 Watercourse Name trib of Pomile Creek
 Photos _____
 Date June 20/12
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 617614
 Descriptive Location off of S. Grimsky Rd, south of Rail Rd tracks
- no access

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Vonne, K. Clayton
 Time 13:55

Water Quality

Dissolved Oxygen (mg/L) 7.21 pH 8.58 Conductivity (µS/cm) 1253
 Water Temperature (°C) 28.30 Air Temperature (°C) 30 °C
 Time *in situ* measurements taken 14:07

Watercourse Dimensions & Morphology

Mean Watercourse Width 10 (m) Maximum Pool Depth 150 (cm)
 Mean Bankfull Width ~15 (m) Mean Water Depth 0.8-1.00 (cm)
 _____ % Riffle _____ % Pool 100 % Run _____ % Flat

Evidence of eroding banks, Comments on bank stability a few undercuts, looks mostly stable - vegetated banks

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 50 Silt _____ Muck _____
 Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus yellow water lilies, duckweed

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

40% trees, mature

Adjacent Land Use

forest

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawning, nursery, foraging

Migratory Obstructions (seasonal, permanent)

permanent ml.

Note any fish observations

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

turbid, slow moving
Giant floater mussle
leopard frog Killdeer

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Non
REA

Station # 12-1
Watercourse Name unknown
Photos _____
Date June 20/12
Weather conditions in previous 24 hrs hot & humid
GPS Coordinates (Zone) 17T E 616608
Descriptive Location off of S. Grimby Rd 6, south of 20 mile
Creek.

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 14:20
Datum NAD83

Water Quality

-dry
Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 30°C
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 2 (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

say, wheat

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) ✓ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 13-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos / Field Staff J. Keene, K. Clayton
 Date June 20/12 Time 14:30
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 616302 N 4772029 Datum NAD83
 Descriptive Location off of S. Grimby Rd 6, N of Smithville Rd

Water Quality

- dry
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 30°C +
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 25 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other RCG Marsh marigold

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

100%, grasses, early
 Adjacent Land Use Cropland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

in spring - potential spawning
 Migratory Obstructions (seasonal, permanent)

dry
 Note any fish observations _____

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by K. Clayton Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

NONREA
*Shallow depression full of Aquatic veg. no defined banks.

Station # 13-2
Watercourse Name unknown
Photos /
Date June 20/12
Weather conditions in previous 24 hrs hot + humid
GPS Coordinates (Zone) 17T E 617082 N 477895 Datum Nad83
Descriptive Location off of Tober Road, South of Smithville Rd

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 14:48

Water Quality

- no water
Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 30
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width ~3m (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg willow, sedges, RCG, typha
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use 100%, typha, early
Residential, say, woodlot to N

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse MP Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by K. Clayton Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

RBA

Station # 13-3
 Watercourse Name unknown
 Photos /
 Date June 20/12
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 617095
 Descriptive Location off of Tober Rd, South of Smithville Road, South of 13-2

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, K. Clayton
 Time 14:50
 Datum Nad 83

Water Quality

Dissolved Oxygen (mg/L) 13.04 pH 8.45 Conductivity (μ S/cm) 2884
 Water Temperature ($^{\circ}$ C) 23.06 Air Temperature ($^{\circ}$ C) 30.0
 Time in situ measurements taken 15:00

Watercourse Dimensions & Morphology

Mean Watercourse Width 3 (m) Maximum Pool Depth 0.50 (cm)
 Mean Bankfull Width 12 (m) Mean Water Depth 0.30 (cm)
 % Riffle _____ % Pool 100 % Run _____ % Flat _____
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt _____ Muck _____
 Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg tupha, cattails, duckweed
 Overhanging Vegetation Woody Debris Boulder Other _____ RCG

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

15%, tupha, early
 Adjacent Land Use soy

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawning, nursery, foraging

Migratory Obstructions (seasonal, permanent)

permanent

Note any fish observations unknown 'pin-head' 404/5

Waterbody Notes

Natural Watercourse / Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg / Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

Red wing BB
frogs green

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

Now
REA
LSD

Stantec

Station # 14-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos / Field Staff J. Keene & K. Clayton
 Date June 21/12 Time 9:04
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 617914 N4771492 Datum NAD83
 Descriptive Location off of Port Davidson Rd, south of Smithville Rd

Water Quality

- no water
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 30°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand ☒ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay ☒ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) _____

Adjacent Land Use

Say

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

Non-REA

-driven through

Stantec

Station # 15-1
 Watercourse Name unknown
 Photos _____
 Date June 20/12
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 617109 N 4770819 Datum Nad83
 Descriptive Location South of 13-3 on Tober Road, South of Smithville Road

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, K. Clayton
 Time 15:19

Water Quality — no water

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 30°C+
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use no shading - crops
hay field, crops

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale ✓ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

Non
REA

Stantec

Station # 15-2
Watercourse Name unknown
Photos /
Date June 20/12

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 15:27

Weather conditions in previous 24 hrs _____
GPS Coordinates (Zone) 17T E 617130 N 4769931 Datum NAD83
Descriptive Location off of Tober Rd, N. of Sitten Road

Water Quality

- no water
Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 30°C+
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
- crops

Adjacent Land Use

crops

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations dry _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel m.p. Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by K. Clayton Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

No longer in Proj. loc'n m.p.

REA

X

Station # 16-1
Watercourse Name unknown
Photos _____
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 9:34

Weather conditions in previous 24 hrs _____
GPS Coordinates (Zone) 17T E 617924 N 4770895 Datum NAD83
Descriptive Location facing West looking @ REA, off of Pnt Davidson Rd

Water Quality

Dissolved Oxygen (mg/L) 5.89 pH 7.95 Conductivity (µS/cm) 3236
Water Temperature (°C) 23.3 Air Temperature (°C) 30°C
Time in situ measurements taken 9:39

Watercourse Dimensions & Morphology

Mean Watercourse Width 6 (m) Maximum Pool Depth <1m (cm)
Mean Bankfull Width 10 (m) Mean Water Depth 0.50 (cm)
% Riffle _____ % Pool 100 % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability all vegetated - fairly stable

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt _____ Muck _____
Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other tupha RCG hornwort

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

5% RCG, early
Adjacent Land Use Corn

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawning, nursery, foraging

Migratory Obstructions (seasonal, permanent)

permanent

Note any fish observations lots of carp! - 6 big individuals

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. Heron

Field Notes Authored by K Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

No longer in Proj. Lock up

X REA 3m East side Non RE West side

Station # 16-2
Watercourse Name unknown
Photos _____
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 9:47

Weather conditions in previous 24 hrs _____
GPS Coordinates (Zone) 17T E 617938 N 4770529 Datum Nad83
Descriptive Location off of Port Davidson Rd, south of Smithville Rd, south of 16-1

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 30°C
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 1.5 (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt _____ Muck _____
Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
0% on west side 20% on east side, RCG, early
Adjacent Land Use farmland, say

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. SD on west side of P.D. Road
is no over - could be played through. On east side it's questionable
REA (couldn't drive through, has aquatic veg, defined channel).

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

No longer in Proj. Lochm

REA

X

Station # 16-3
 Watercourse Name unknown
 Photos _____
 Date June 21/12
 Weather conditions in previous 24 hrs _____
 GPS Coordinates (Zone) 17T E 617946 N 4769975 Datum NAD83
 Descriptive Location off of Port Davidson Road, south of 16-2,
North of Sixteen Rd.

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, Kelly Clayton
 Time 9:54

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 30°C
 Time *in situ* measurements taken _____

-no water

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 3 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 20 Sand 40 Silt _____ Muck _____
 Boulder _____ Gravel 40 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg RCG
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

100%, RCG, early
 Adjacent Land Use residential, farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

narrow channel full of
reed canopy grass & a little typha - no water

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

West side
of PDR
↳ SD^{no}
East side
↳ REA

Station # 18-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keene, K. Clayton
 Date June 21/12 Time 10:00
 Weather conditions in previous 24 hrs _____
 GPS Coordinates (Zone) 17T E 617954 N 4769752 Datum Nad83
 Descriptive Location off of Port Davidson Rd, South of Sixteen Rd

Water Quality

-no water
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 30
 Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 2 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt _____ Muck _____
 Boulder _____ Gravel 40 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____ tupha

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

50% (east) tupha 10% (west) terrestrial scrub, early

Adjacent Land Use

soy

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) ✓ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

on east side
east side is dominated by aquatic veg, defined channel - not played through. on the west side of PDR it's more of a SD - could drain through & more terrestrial plants than aquatic.
*small section along Port Davidson Rd by culvert on west side could be REA.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Nat
REA
m.p.

Station # 19-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keane, K. Clayton
 Date June 20/12 Time 15:46
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 616727 N 476842 Datum NAD83
 Descriptive Location off of McCallum Rd. South of Sixteen Rd, N of
conc. 4.

Water Quality

-dry
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 30°C+
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 40 Sand 10 Silt _____ Muck _____
 Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

hay field

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel m.p. Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

defined channel m.p. see photo's
no aquatic veg. large array of surficial
could be driven through drainage

Field Notes Authored by K. Clayton Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Non
REA

Station # 19-2 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keene, K. Clayton
 Date June 20/12 Time 15:59
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 617179 N 4767651 Datum NAD83
 Descriptive Location off of Conc. 4, east of McCollum Road

Water Quality

~~- no water~~
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 30°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

_____ Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck
 _____ Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus

In-water Cover

Cover Types Present (circle): _____ Undercut Banks _____ Deep Pool _____ Watercress _____ Aquatic Veg
Overhanging Vegetation _____ Woody Debris _____ Boulder _____ Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
100%, forest (trees), mature (on southside), early on northside of road
 Adjacent Land Use forest, farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations _____

Waterbody Notes

Natural Watercourse W.P. Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 19-3 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keene, K. Clayton
 Date June 20/12 Time 4:22 pm
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 616640 N 4767627 Datum NAD83
 Descriptive Location off of conc 4, west of port Davidson

Water Quality - no water
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 32°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 2.5-3 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 10 ✓ Sand 40 ✓ Silt _____ Muck _____
 Boulder _____ Gravel 50 ✓ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

85% typha, grasses, early
 Adjacent Land Use farm land

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

- on south side of conc 4 channel is deeply incised - eroded banks. on north side of Road it is heavily vegetated

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 19-4 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keener, K. Clayton
 Date June 20/12 Time 4:31 pm
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 616320 N 4767608 Datum NAD83
 Descriptive Location off of conc 4, west of McCollum Road

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 32°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 2 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg typha
Overhanging Vegetation Woody Debris Boulder Other _____ REA

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

100%, typha, early
 Adjacent Land Use residential, farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

deeply incised channel

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Stantec

Station # 19-S
 Watercourse Name unknown
 Photos _____
 Date June 20/12
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 617476 N 4767658 Datum Nad83
 Descriptive Location off of conc 4

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, K. Clayton
 Time 4:46

Water Quality - a little water pooled @ culvert - no y/s
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 32°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt _____ Muck _____
 Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg typha
Overhanging Vegetation Woody Debris Boulder Other algae RCG

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

leopard frogs on North side of road there is an
green frogs online pond, on South side it is pooled @
culvert & then becomes dry
breaks off into side channel.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

reaches are REA³ on

East side

- Non on west side

Station # 20-1
Watercourse Name unknown
Photos ✓
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 1:00

Weather conditions in previous 24 hrs clear
GPS Coordinates (Zone) 17T E 618005 N 4768086 Datum NAD83
Descriptive Location off of Port Davidson Rd South of 16 Road
South of 18-1

Water Quality - no water
Dissolved Oxygen (mg/L) pH Conductivity (µS/cm)
Water Temperature (°C) Air Temperature (°C) 30
Time in situ measurements taken

Watercourse Dimensions & Morphology
Mean Watercourse Width (m) Maximum Pool Depth (cm)
Mean Bankfull Width (m) Mean Water Depth (cm)
 % Riffle % Pool % Run % Flat
Evidence of eroding banks, Comments on bank stability

Substrate (% cover)
 Bedrock Cobble 10 Sand 40 Silt Muck
 Boulder Gravel 50 Clay Marl Detritus

In-water Cover
Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone
Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 100%, typha, early
Adjacent Land Use hayfield

Fish Habitat Potential
Critical Habitat (spawning or nursery areas, groundwater upwellings)
Migratory Obstructions (seasonal, permanent) dry
Note any fish observations

Waterbody Notes on east side
Natural Watercourse ✓ Trapezoidal Channel Grassed Swale Buried Tile
Surficial Drainage (i.e. furrows) ✓ Dugout Pond Dominated by Aquatic Veg Dry ✓
on west side of rd

Other Habitat Notes, Incidental Wildlife Observations, etc. East side has a defined channel
with aquatic veg, can't drive through it. on the west side there
is a portion near the culvert that is channelized however the channel
disappears & the farmer has been driving through it - lots of typha
throughout.

Field Notes Authored by K. Clayton Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA.

Station # 20-2

Watercourse Name unknown

Photos

Date June 21/12

Weather conditions in previous 24 hrs hot & humid

GPS Coordinates (Zone) 17T E 618771

Descriptive Location off of Conc 4, East of Port David Rd, East of old Rail bed

Project Name Niagara Wind

Project # 160958269

Field Staff J. Keene, K. Clayton

Time 10:47

Datum Nad83

Water Quality

Dissolved Oxygen (mg/L)

pH Conductivity (µS/cm)

Water Temperature (°C)

Air Temperature (°C) 30°C

Time *in situ* measurements taken

Watercourse Dimensions & Morphology

Mean Watercourse Width (m)

Maximum Pool Depth (cm)

Mean Bankfull Width 2 (m)

Mean Water Depth (cm)

 % Riffle % Pool

 % Run % Flat

Evidence of eroding banks, Comments on bank stability

Substrate (% cover)

Bedrock Cobble Sand Silt Muck
Boulder Gravel Clay Marl Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 100%, RCG, partly

Adjacent Land Use Oats, hay

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent) dry

Note any fish observations

Waterbody Notes

Natural Watercourse Trapezoidal Channel ✓ Grassed Swale Buried Tile

Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

on south side of Conc 4 it is channelized by RCG in channel called a REA. on opposite side of Rd channel is not there even though mapped by MNR.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 22-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos / Field Staff J. Keene, K. Clayton
 Date June 21/12 Time 13:27
 Weather conditions in previous 24 hrs Hot & humid
 GPS Coordinates (Zone) 17T E 617747 N 4765865 Datum NAD83
 Descriptive Location off of Port Davidson Road, just south of Silver Rd

Water Quality

Dissolved Oxygen (mg/L) 1.50 pH 8.19 Conductivity (μ S/cm) 547
 Water Temperature ($^{\circ}$ C) 24.25 Air Temperature ($^{\circ}$ C) 32.0
 Time in situ measurements taken 13:30

Watercourse Dimensions & Morphology

Mean Watercourse Width 4 (m) Maximum Pool Depth 0.20 (cm)
 Mean Bankfull Width 8 (m) Mean Water Depth 0.10 (cm)
 % Riffle 100 % Pool 0 % Run 0 % Flat 0
 Evidence of eroding banks, Comments on bank stability stable - vegetated

Substrate (% cover)

Bedrock 0 Cobble 10 Sand 50 Silt 0 Muck 0
 Boulder 0 Gravel 40 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

West Side = 5%, RCG, early East = 35%, RCG, early

Adjacent Land Use

farmland - wheat

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawning, nursery & foraging

Migratory Obstructions (seasonal, permanent)

permanent

Note any fish observations fish coming to surface for air

Waterbody Notes

Natural Watercourse / Trapezoidal Channel 0 Grassed Swale 0 Buried Tile 0
 Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg 0 Dry 0

Other Habitat Notes, Incidental Wildlife Observations, etc.

heron
water very murky! lots of duckweed on East side of PD Road

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Non-REA³m

Station # 24-1
Watercourse Name unknown
Photos _____
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 13:42

Weather conditions in previous 24 hrs Hot & humid, 32°C +
GPS Coordinates (Zone) 17T E 617763 N 4764866 Datum Nad83
Descriptive Location off of Vaughn Rd at Port Davidson Intersect
south of 22-1

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 32°C
Time *in situ* measurements taken _____

no water

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 1m (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

100% RCG, early
Adjacent Land Use Say, road, residential

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

- dominated by RCG
* - shallow channel, but defined only for short reach m.p.
* - channel at Port Davidson Road is indistinct - RCG & typha corridor
↳ channel that 24-1 flows into

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

BEA 27.1

Station # 23-1
 Watercourse Name unknown
 Photos _____
 Date June 21/12
 Weather conditions in previous 24 hrs Hot & humid
 GPS Coordinates (Zone) 17T E 616013 N 4764798 Datum Nad83
 Descriptive Location off of Vaughn Road, west of 24-1

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, K. Clayton
 Time 14:05

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 32°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use forest

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

Reed canary grass right by road to a little channel
definition, further on no channel (≈ 10m)

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

• REA on south side
• Non REA on N side of conc.

Station # 23-2
Watercourse Name unknown
Photos _____
Date June 21/12
Weather conditions in previous 24 hrs Hot & humid
GPS Coordinates (Zone) 17T E 6014945 N 4765288 Datum Nad83
Descriptive Location off of Concession #3

Project Name Niagara Wind
Project # 160958269
Field Staff J. Keene, K. Clayton
Time 14:19

Water Quality

Dissolved Oxygen (mg/L) 4.10 pH 8.18 Conductivity (µS/cm) 674
Water Temperature (°C) 23.82 Air Temperature (°C) 30°C
Time *in situ* measurements taken 14:22

Watercourse Dimensions & Morphology

Mean Watercourse Width 0.5 (m) Maximum Pool Depth 0.15 (cm)
Mean Bankfull Width 1.5 (m) Mean Water Depth 0.10 (cm)
_____ % Riffle 5 % Pool 100 % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability stable

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt _____ Muck _____
Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other algae

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

95-100%, RCG, early

Adjacent Land Use

say

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

potential spawning

Migratory Obstructions (seasonal, permanent)

probably dries up in midsummer

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

on N side of conc. 3 it's a Non REA - SD
on S side it's a REA in defined channel, aquatic veg.
• hybrid water.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 26-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160950269
 Photos See photo log Field Staff ME, MF
 Date 2012 06 18 Time 14:07
 Weather conditions in previous 24 hrs Minor precip
 GPS Coordinates (Zone) 17S E 0617964 N 4763459 Datum NAD83
 Descriptive Location On Elcho Rd ~ 70m east of Port Davidson Rd.

Water Quality

Dissolved Oxygen (mg/L) 6.74 pH 8.03 Conductivity (µS/cm) 436
 Water Temperature (°C) 22.93 Air Temperature (°C) 30°C
 Time in situ measurements taken 14:11

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.5 (m) Maximum Pool Depth ~1.65 (cm)
 Mean Bankfull Width ~25 (m) Mean Water Depth ~30 (cm)
 % Riffle 100 % Pool 0 % Run 0 % Flat 0
 Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock 0 Cobble 0 Sand 40 Silt 40 Muck 0
 Boulder 0 Gravel 20 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation 0 Woody Debris 0 Boulder 0 Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

5% grasses
 Adjacent Land Use Farm buildings, meadow fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Spawning habitat
 Migratory Obstructions (seasonal, permanent)

dry @ times
 Note any fish observations none

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel 0 Grassed Swale 0 Buried Tile 0
 Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg ✓ Dry 0

Other Habitat Notes, Incidental Wildlife Observations, etc. Jumping fish sp

Field Notes Authored by MF

Field Notes QA/QCed by WFE



FARM

Meadow

ELCHO RD

KIRK

OPEN WATER

OPEN WATER

OPEN WATER

OPEN WATER
POOL

reed canopy

reed canopy



= algae/duckweed

oo = pond weed



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 27-1
Watercourse Name unknown
Photos see photo log
Date 2012 06 18

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 14:00

Weather conditions in previous 24 hrs Minor Precip
GPS Coordinates (Zone) 17T E 0618419 N 4763474 Datum NAD83
Descriptive Location on Elcho Rd ~ 450m west of Kirk Rd on south side. No access, rd side Sully

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
25% ash sp, shrub sp

Adjacent Land Use

houses, rd

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
N/A

Migratory Obstructions (seasonal, permanent)
N/A

Note any fish observations
N/A

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. song bird sp.

Field Notes Authored by ME

Field Notes QA/QCed by MEE

(K W)



arrow head

photo

ELCHO Rd



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA d/s but partial REA ups near culvert only.

REA

Station # 28-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160950269
 Photos see photo log Field Staff ME, ME
 Date 2012 06 19 Time 09:34
 Weather conditions in previous 24 hrs minor precip
 GPS Coordinates (Zone) 17T E 0617877 N 4762295 Datum NAD83
 Descriptive Location On Post Davidson Rd ~ 400 m north of Zumstein Rd.

Water Quality

Dissolved Oxygen (mg/L) 2.47 pH 7.78 Conductivity (µS/cm) 1005
 Water Temperature (°C) 23.82 Air Temperature (°C) _____
 Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth 15.0 (cm)
 Mean Bankfull Width 2.5 (m) Mean Water Depth 7.0 (cm)
 _____ % Riffle 100 % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock _____ Cobble 20 Sand 40 Silt 30 Muck _____
 Boulder _____ Gravel 10 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
30% cattail

Adjacent Land Use

ag. rd.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
possible spawn

Migratory Obstructions (seasonal, permanent)
dry @ times

Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale ☒ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. green frogs, hoppers

Field Notes Authored by ME

Field Notes QA/QCed by MEE



AS

Swale

Meadow sp

STAND
H₂O

Meadow sp

PORT DAVIDSON RD.

Meadow sp

OPEN WATER
STANDING

Meadow sp.

Cattail

AS

AS



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA 32

Road side access only.

Station # 29-1

Watercourse Name unknown

Photos See photo log

Date 2012 06 19

Weather conditions in previous 24 hrs minor precip

GPS Coordinates (Zone) 17T E 0617859

Descriptive Location On Port Davidson Rd ~700m north of Carborough Rd.

Project Name Niagara Wind

Project # 160950269

Field Staff ME, MF

Time 09:23

Datum NAD83

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) _____

Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 0.40 (m) Maximum Pool Depth dry (cm)

Mean Bankfull Width 1.5 (m) Mean Water Depth dry (cm)

_____ % Riffle _____ % Pool _____ % Run _____ % Flat

Evidence of eroding banks, Comments on bank stability minor undercutts

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 30 Silt 40 Muck

Boulder _____ Gravel 30 Clay _____ Marl _____ Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg

Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

2% reed canopy grass

Adjacent Land Use _____

ag. rds.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

none?

Migratory Obstructions (seasonal, permanent)

dry

Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale ☒ Buried Tile _____

Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MF

Field Notes QA/QCed by MEE



= choked w reed canes, grass

As

As

Port Davidson Rd

As

As

No access, Rd side view



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Stantec

Station # 30-1 Project Name Niagara Wind
Watercourse Name Trib of Welland Rv. Project # 160950269
Photos See photo log Field Staff ME, MF
Date 2012 06 09 Time 08:45
Weather conditions in previous 24 hrs minor precip.
GPS Coordinates (Zone) 17T E 0620075 N 4761299 Datum NAD83
Descriptive Location On Canborough Rd ~1km east of Kirk Rd

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (μ S/cm) _____
Water Temperature ($^{\circ}$ C) _____ Air Temperature ($^{\circ}$ C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 3.05 (m) Maximum Pool Depth 0.20 (cm)
Mean Bankfull Width 6.0 (m) Mean Water Depth 0.10 (cm)
_____ % Riffle 100 % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability minor undercut banks near bridge

Substrate (% cover)

Bedrock 20 Cobble _____ Sand 30 Silt 30 Muck _____
Boulder _____ Gravel 20 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

10% mature/immature tree sp. seed canopy grass
Adjacent Land Use agr. rds.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn.
Migratory Obstructions (seasonal, permanent) lack of water
Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

Song birds


Field Notes Authored by ME

Field Notes QA/QCed by ME

* = bullhead/arrowhead

= emerg. veg sp (thick)

// = sedge/meadow sp.



shrub

standing water



boulder
rip/rap


Wetland 01

reed canopy
veg




manicured
grass

Cabotrough rd.



open field



open field



AG



Stantec

Could not properly assess as area is off row.
Row = Non REA

Non REA
OFF ROW

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Station # 31-1

Watercourse Name unknown

Photos See photo log

Date June 20/12

Project Name Niagara Wind

Project # 160958269

Field Staff ME, MF

Time 10:31

Weather conditions in previous 24 hrs hot + humid

GPS Coordinates (Zone) 17T E 0622345 N 4761279 Datum NAD83

Descriptive Location On Creek Rd ~ 2km east of Erick Rd

Day
off Row

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (μ S/cm) _____

Water Temperature ($^{\circ}$ C) _____ Air Temperature ($^{\circ}$ C) _____

Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)

Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)

_____ % Riffle _____ % Pool _____ % Run _____ % Flat

Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use _____

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes


Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____

Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. Dry - none

Field Notes Authored by MF

Field Notes QA/QCed by MEE





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
DRY

- defined channel o/s + d/s

Station # 31-2
Watercourse Name unknown
Photos See photo log
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 10:44

Weather conditions in previous 24 hrs no precipitation
GPS Coordinates (Zone) 17T E 0622462 N 4761306 Datum Nad83
Descriptive Location On Creek Rd ~ 2.4 km east of Krik Rd on Hardy
Property

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 0.25 (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 2.0 (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability some undercut banks + scour

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 30 Silt 30 Muck _____
Boulder _____ Gravel 30 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
30% = d/s + 2% = u/s mature trees + shrubs d/s, reed canopy u/s.

Adjacent Land Use

ag fields, house, rd

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
possible spawn at high water times

Migratory Obstructions (seasonal, permanent)
dry now.

Note any fish observations none

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel ✓ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. bobolink

Field Notes Authored by MF

Field Notes QA/QCed by MEF

WELAND
R.V.

31-2

N ↑

HOUSE ↑

FARM

REDWOOD

Creek Rd

CORN

CORN

31-2
↓



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

STANDING WATER ONLY / STAGNANT

Station # 32-1
 Watercourse Name unknown
 Photos See photo log
 Date 2012 06 19
 Weather conditions in previous 24 hrs minor precip
 GPS Coordinates (Zone) 17T E 0623589 N 4761722 Datum NAD83
 Descriptive Location On Creek Rd ~ 250 m west of Wellandport Rd

Project Name Niagara Wind
 Project # 160950269
 Field Staff MEINE
 Time 10:15

Too shallow
Standing water

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) _____
 Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.2 (m) Maximum Pool Depth 5 (cm)
 Mean Bankfull Width 2.5 (m) Mean Water Depth 2 (cm)
 _____ % Riffle 100 % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 30 Silt 40 Muck _____
 Boulder _____ Gravel 20 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
50% mainly @ v/s location w/ trees + shrubs

Adjacent Land Use

farm, pasture, rds

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
possible spawning

Migratory Obstructions (seasonal, permanent)
back of water

Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale ☒ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____


Field Notes Authored by ME

Field Notes QA/QCed by MEE



Holse
pasture.

mature
trees.




CREEK RD.

** = patches of emerg.
aquatic veg. sp.

meadow
sp.

Welland Rv.
150 m





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 34-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos See photo log Field Staff ME, MF
 Date June 20/12 Time 09:10
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 0621197 N 4762726 Datum NAD83
 Descriptive Location On un-maintained rd of Baldwin ~ 800m

Water Quality

Dissolved Oxygen (mg/L) 2.40 → 0.35 pH 7.70 Conductivity (µS/cm) 401
 Water Temperature (°C) 23.14 Air Temperature (°C) 29.06
 Time in situ measurements taken 09:15

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth ~150.0 (cm)
 Mean Bankfull Width 3.5 (m) Mean Water Depth ~150.0 (cm)
 % Riffle 100 % Pool 0 % Run 0 % Flat 0
 Evidence of eroding banks, Comments on bank stability Minor scour along edges

Substrate (% cover)

Bedrock 0 Cobble 0 Sand 50 Silt 50 Muck 0
 Boulder 0 Gravel 0 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
10% mature trees/shrubs. Snags.

Adjacent Land Use

meadow, woodlot

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
forage, spawning, nursery

Migratory Obstructions (seasonal, permanent)
lack of flows/water

Note any fish observations Many fish caught in pool near old cement bridge. No water in stream w/s of d/s. 4 carp carcasses.

Waterbody Notes


Natural Watercourse ✓ Trapezoidal Channel 0 Grassed Swale 0 Buried Tile 0
 Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg ✓ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. Water @ bridge only.

Fish appear to be breaking surface and gulping air.
Many green frogs, leopard frogs.

Field Notes Authored by MF

Field Notes QA/QCed by MEE



-  = 100% duckweed
-  = other emerg aquatic veg
-  = reed canopy grass
-  = standing water with frogs/aquatic veg



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Non
REA

Station # 34-2

Watercourse Name unknown

Photos See photo log

Date June 20/12

Weather conditions in previous 24 hrs no precip

GPS Coordinates (Zone) 17T E

0621159 N 4762268 Datum Nad83

Descriptive Location On unmaintained Rd of Baldwin ~ 400 m north of
Canborough Rd

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) _____

Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use _____

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. Meadow lark, eastern king
bird.

Field Notes Authored by MP


Field Notes QA/QCed by MEE



Canborough Rd ↑
~400 m

FARM

34-1 ↑




HEDGEROW

BALDWIN RD
(unmaintained)

fence line

recently
disturbed

graze / cows



POND

graze / cows



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA on east only

Station # 35-1

Watercourse Name unknown

Photos See photo log

Date 2012 06 18

Weather conditions in previous 24 hrs mmw precip

GPS Coordinates (Zone) 17T E 0623624

Descriptive Location On Collier Rd ~30m south of Frevie Rd

Project Name Niagara Wind

Project # 160950269

Field Staff ME, ME

Time 16:06

Datum NAD83

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) 30°C

Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 3.0 (m)

Maximum Pool Depth 30 (cm)

Mean Bankfull Width 4.0 (m)

Mean Water Depth 15 (cm)

% Riffle 100 % Pool _____ % Run _____ % Flat _____

Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 50 Silt 50 Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 30% willow sp

Adjacent Land Use

houses, ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) spawn, forage, nursery

Migratory Obstructions (seasonal, permanent) lack of water

Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale ☒ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____


Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MEE

Field Notes QA/QCed by MEE




manicured
grass



Freyre Rd

Collins Rd





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 35-2 Project Name Niagara Wind
 Watercourse Name Trib of Welland Rv. Project # 160950269
 Photos See photo log Field Staff ME, MF
 Date 2012 06 18 Time 16:30
 Weather conditions in previous 24 hrs minor precip.
 GPS Coordinates (Zone) 17T E 0623682 N 4762560 Datum NAD83
 Descriptive Location On R.R. 27 ~ 40m north of Carleton Place Rd.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 30°C
 Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 3.0 (m) Maximum Pool Depth 7.100 (cm)
 Mean Bankfull Width 4.0 (m) Mean Water Depth ~50 (cm)
 _____ % Riffle 100 % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability none observed.

Substrate (% cover)

Bedrock 20 Cobble _____ Sand 40 Silt 20 Muck _____
 Boulder _____ Gravel 20 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

30% ash sp, willow sp.

Adjacent Land Use

business, house, rds.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn, nursery, forage

Migratory Obstructions (seasonal, permanent)

none observed

Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.


rose breasted goose hawk, frog sp.

Field Notes Authored by MF


Field Notes QA/QCed by AME



Carborough Rd.



R.D. #27





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
Welland Rv.

Station # 35-3
Watercourse Name Welland Rv.
Photos See photo log
Date 2012 06 18
Weather conditions in previous 24 hrs mmHg precip
GPS Coordinates (Zone) 17T E 0623724 N 4762460 Datum NAD83
Descriptive Location On Riverside Dr. ~ 40m South of Carborough Rd.

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 16:46

No access
Road to shut
from bridge

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (μS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 30 (m) Maximum Pool Depth 2100 (cm)
Mean Bankfull Width 40 (m) Mean Water Depth 750 (cm) >100
% Riffle 100 % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 30? Silt 50? Muck _____
Boulder _____ Gravel 20? Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
20% tree sp, reed canopy grass, willow sp.

Adjacent Land Use

Houses, rds

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
spawning, nursery, forage

Migratory Obstructions (seasonal, permanent)
none observed

Note any fish observations none


Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ✓ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by ME

Field Notes QA/QCed by MEE





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

RE A

Station # 36-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160950269
 Photos See photo log Field Staff ME ME
 Date 2012-06-18 Time 12:51
 Weather conditions in previous 24 hrs minor precip
 GPS Coordinates (Zone) 17T E 0621414 N 4763625 Datum NAD83
 Descriptive Location On Elcho Rd ~ 2km west of Roy Rd 27.

Water Quality

Dissolved Oxygen (mg/L) 7.13 pH 7.98 Conductivity (μ S/cm) 481
 Water Temperature ($^{\circ}$ C) 23.14 Air Temperature ($^{\circ}$ C) 28.0
 Time in situ measurements taken 13:00

Watercourse Dimensions & Morphology

Mean Watercourse Width 4.0 (m) Maximum Pool Depth ~80 (cm)
 Mean Bankfull Width 5.5 (m) Mean Water Depth ~50 (cm)
 % Riffle 100 % Pool 0 % Run 0 % Flat 0
 Evidence of eroding banks, Comments on bank stability none

Substrate (% cover)

Bedrock 0 Cobble 0 Sand 40 Silt 30 Muck 0
 Boulder 0 Gravel 30 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

20% reed canary grass

Adjacent Land Use

Ag

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawning forage, overstory

Migratory Obstructions (seasonal, permanent)

none observed

Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☐ Grassed Swale ☐ Buried Tile ☐
 Surficial Drainage (i.e. furrows) ☐ Dugout Pond ☐ Dominated by Aquatic Veg ☒ Dry ☐

Other Habitat Notes, Incidental Wildlife Observations, etc. Barn Swallow

Field Notes Authored by ME

Field Notes QA/QCed by ME



Ag

algae/duckweed

POOL

ECHO Rd

POOL

algae/duckweed

wheat



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 36-2

Project Name Niagara Wind

Watercourse Name unknown

Project # 160950269

Photos see photo log

Field Staff ME, MF

Date 2012 06 18

Time 13:30

Weather conditions in previous 24 hrs hot & humid

GPS Coordinates (Zone) 17T E 0621701 N 4764279 Datum NAD83

Descriptive Location ~600m north in field from Fliche Rd

Water Quality

Dissolved Oxygen (mg/L) pH Conductivity (µS/cm)

Water Temperature (°C) Air Temperature (°C)

Time *in situ* measurements taken

Damp

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth N/A (cm)

Mean Bankfull Width 3.0 (m) Mean Water Depth N/A (cm)

 % Riffle % Pool % Run % Flat

Evidence of eroding banks, Comments on bank stability

DRY

DRY

Substrate (% cover)

Bedrock Cobble Sand 30 Silt 70 Muck
Boulder Gravel Clay Marl Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

DRY

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

30% reed canopy grass.

Adjacent Land Use ag, small woodlot.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possible spawn

Migratory Obstructions (seasonal, permanent)

Dry

Note any fish observations None - Dry

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel Grassed Swale Buried Tile

Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. None

Field Notes Authored by mf

Field Notes QA/QCed by MEE

N →

Small
mixed
woodlo

reed canary
grass

Ag

ELCHO RD
660 m





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 36-3
 Watercourse Name unknown
 Photos See photo log
 Date 2012 06-18
 Weather conditions in previous 24 hrs minor precip
 GPS Coordinates (Zone) 17T E 01020399 N 4763566 Datum NAD83
 Descriptive Location On Elcho Rd ~ 3km west of R.R. 27.

Water Quality

Dissolved Oxygen (mg/L) 7.68 pH 8.09 Conductivity (µS/cm) 675
 Water Temperature (°C) 22.65 Air Temperature (°C) 30.2
 Time *in situ* measurements taken 13:49

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.0 (m) Maximum Pool Depth ~ 70 (cm)
 Mean Bankfull Width ~ 10 (m) *Flood plane* Mean Water Depth (cm)
 % Riffle 100 % Pool % Run % Flat
 Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock Cobble Sand 40 Silt 40 Muck
 Boulder Gravel 20 Clay Marl Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
5% reed canopy grass

Adjacent Land Use

ag. farm, rd

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
spawn

Migratory Obstructions (seasonal, permanent)
lack of water

Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel Grassed Swale Buried Tile
 Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg ☒ Dry


Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by MF

Field Notes QA/QCed by ME




grazing



meadow

ECHO RD

Ag



scat tail

thick w algae / duckweed

reed canary grass



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 37-1
 Watercourse Name Unknown
 Photos See photo log
 Date 2012 06 18
 Weather conditions in previous 24 hrs Minor precipitation
 GPS Coordinates (Zone) 17T E 0622571 N 4763682 Datum NAD83
 Descriptive Location ~60m west of Regional Rd 27 on Elcho Rd.
Crosses under Elcho Rd.

Water Quality

Dissolved Oxygen (mg/L) 3.73 pH 7.57 Conductivity (µS/cm) 1534
 Water Temperature (°C) 21.80 Air Temperature (°C) 28°C
 Time in situ measurements taken 12:45

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.0 (m) Maximum Pool Depth ~70 (cm)
 Mean Bankfull Width ~30 (m) Mean Water Depth ~30 (cm)
 % Riffle 30 % Pool % Run 70 % Flat
 Evidence of eroding banks, Comments on bank stability none, well vegetated

Substrate (% cover)

Bedrock Cobble Sand 40 Silt 40 Muck
 Boulder Gravel 20 Clay Marl Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

5% reed canary grass

Adjacent Land Use

Houses, Rds

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Spawning, nursery

Migratory Obstructions (seasonal, permanent)

None observed

Note any fish observations Fish sp.

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel Grassed Swale Buried Tile
 Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg ☒ Dry

Other Habitat Notes, Incidental Wildlife Observations, etc.

Frog sp.

Field Notes Authored by MF

Field Notes QA/QCed by MEE



manicured
grass

ELCHO Rd



 = duckweed

|||| = reed canary grass



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Station # 37-2

Watercourse Name unknown

Photos See photo log

Date June 21/12

Weather conditions in previous 24 hrs no precipitation

GPS Coordinates (Zone) 17T E 0622266

Descriptive Location On R.R. 27 ~ 600 m north of Elcho Rd.

Project Name Niagara Wind

Project # 160958269

Field Staff ME, MF

Time 11:23

Non-REA @ east
Side of Row
only (4m long)
Non-REA on
west side

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) 30°C

Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 0.40 (m) Maximum Pool Depth 20 (cm)

Mean Bankfull Width 1.0 (m) Mean Water Depth 20 (cm)

% Riffle _____ % Pool _____ % Run _____ % Flat _____

Evidence of eroding banks, Comments on bank stability minor undercut

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt 30 Muck _____

Boulder _____ Gravel 30 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress _____ Aquatic Veg _____

Overhanging Vegetation _____ Woody Debris _____ Boulder _____ Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

0% seed canopy grass

Adjacent Land Use ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

none

Migratory Obstructions (seasonal, permanent)

dry through plowed fields on both sides

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale ☒ Buried Tile _____

Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. leopard frog & green Frog

Field Notes Authored by ME

Field Notes QA/QCed by MGE



wheat

NON-
REA

Row
Meadow

R.R. 27

Row
Meadow

wheat

NON-
REA

REA

standing water
traps



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Stantec

Station # 38-1Watercourse Name unknownPhotos See photo logDate 2012 06 18Weather conditions in previous 24 hrs Minor precipGPS Coordinates (Zone) 17T E 0623841Descriptive Location On Elcho Rd ~800m east of RR #27Project Name Niagara WindProject # 160950269Field Staff ME, MFTime 14:32Datum NAD83

Water Quality

Dissolved Oxygen (mg/L) 11.83 pH 8.16 Conductivity (μ S/cm) 2926Water Temperature ($^{\circ}$ C) 22.43 Air Temperature ($^{\circ}$ C) 30 $^{\circ}$ CTime in situ measurements taken 14:45

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.0 (m) Maximum Pool Depth 15 (cm)Mean Bankfull Width 3.0 (m) Mean Water Depth 10 (cm)% Riffle 100 % Pool 0 % Run 0 % Flat 0Evidence of eroding banks, Comments on bank stability minor undercut

Substrate (% cover)

Bedrock 0 Cobble 0 Sand 40 Silt 40 Muck 0
Boulder 0 Gravel 20 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic VegOverhanging Vegetation Woody Debris Boulder Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

50% seed canopy grassAdjacent Land Use ag, houses, rds

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

foraging

Migratory Obstructions (seasonal, permanent)

lack of waterNote any fish observations Fish sp

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☐ Grassed Swale ☐ Buried Tile ☐Surficial Drainage (i.e. furrows) ☐ Dugout Pond ☐ Dominated by Aquatic Veg ☐ Dry ☐Other Habitat Notes, Incidental Wildlife Observations, etc. Frog spField Notes Authored by MFField Notes QA/QCed by MEE




Manicured
grass

ELCH RD

DRIVEWAY

Previously
assessed



Standing
H₂O



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 38-2
Watercourse Name unknown
Photos See photo log
Date 2012 06 18
Weather conditions in previous 24 hrs minor precip
GPS Coordinates (Zone) 17T E 0624426 N 4763788 Datum NAD83
Descriptive Location On Elcho Rd ~ 650m east of Colver Rd

Water Quality

Dissolved Oxygen (mg/L) 5.18 pH 8.13 Conductivity (µS/cm) 1798
Water Temperature (°C) 18.59 Air Temperature (°C) 30.0
Time in situ measurements taken 14:55

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.0 (m) Maximum Pool Depth 30 (cm)
Mean Bankfull Width 2.0 (m) Mean Water Depth 15 (cm)
% Riffle 100 % Pool 0 % Run 0 % Flat 0
Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock 0 Cobble 10 Sand 30 Silt 30 Muck 0
Boulder 0 Gravel 30 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

30% mature + immature oak sp, manitoba maple

Adjacent Land Use

ag land

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn, nursery, forage

Migratory Obstructions (seasonal, permanent)

may dry up

Note any fish observations Species observed

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☐ Grassed Swale ☐ Buried Tile ☐
Surficial Drainage (i.e. furrows) ☐ Dugout Pond ☐ Dominated by Aquatic Veg ☒ Dry ☐

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by ME

Field Notes QA/QCed by MEF



ELCH RD.



POOL



Mixed
woodlot





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 39-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160950269
 Photos See photo log Field Staff ME, ME
 Date 2012 06 15 Time 15:08
 Weather conditions in previous 24 hrs minor precip
 GPS Coordinates (Zone) 17T E 06260022 N 4763874 Datum NAD 83
 Descriptive Location On Elcho Rd ~ 100m east of Heaslip Rd.

Water Quality
 Dissolved Oxygen (mg/L) 14.64 pH 8.73 Conductivity (µS/cm) 1401
 Water Temperature (°C) 27.75 Air Temperature (°C) 30%
 Time *in situ* measurements taken 15:15

Watercourse Dimensions & Morphology
 Mean Watercourse Width 2.5 (m) Maximum Pool Depth 30 (cm)
 Mean Bankfull Width 3.0 (m) Mean Water Depth 10 (cm)
 % Riffle 20 % Pool 80 % Run 80 % Flat
 Evidence of eroding banks, Comments on bank stability minor scour.

Substrate (% cover)
 Bedrock Cobble Sand 30 Silt 40 Muck
 Boulder Gravel 30 Clay Marl Detritus

In-water Cover
 Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other


Riparian Zone
 Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
5% seed canopy grass
 Adjacent Land Use ag fields

Fish Habitat Potential
 Critical Habitat (spawning or nursery areas, groundwater upwellings)
spawn
 Migratory Obstructions (seasonal, permanent)
may dry up
 Note any fish observations none

Waterbody Notes
 Natural Watercourse ☒ Trapezoidal Channel Grassed Swale Buried Tile
 Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg Dry

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by ME Field Notes QA/QCed by MEE





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 40-1

Watercourse Name unknown

Photos see photo log

Date 2012 06 18

Weather conditions in previous 24 hrs minor precip.

GPS Coordinates (Zone) 17T E 0626874

Descriptive Location On Elcho Rd ~ 100 m west of Gee Rd.

Project Name Niagara Wind

Project # 160950269

Field Staff ME, MF

Time 15:22

Datum NAD83

Water Quality

Dissolved Oxygen (mg/L)

pH

Conductivity (µS/cm)

Water Temperature (°C)

Air Temperature (°C) 30°C

Time in situ measurements taken

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.0 (m)

Maximum Pool Depth 15 (cm)

Mean Bankfull Width 2.5 (m)

Mean Water Depth 8 (cm)

 % Riffle 100 % Pool

 % Run

 % Flat

Evidence of eroding banks, Comments on bank stability none observed.

Substrate (% cover)

 Bedrock

 Cobble

 Sand 30

 Silt 40

 Muck

 Boulder

 Gravel 30

 Clay

 Marl

 Detritus

In-water Cover

Cover Types Present (circle):

Undercut Banks

Deep Pool

Watercress

Aquatic Veg

Overhanging Vegetation

Woody Debris

Boulder

Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

25% seed carrying grass, immature / mature mixed woodlot.

Adjacent Land Use woodlot, rd, diag.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn?

Migratory Obstructions (seasonal, permanent)

none

man dig up completely

Note any fish observations none

Waterbody Notes

Natural Watercourse ✓

Trapezoidal Channel

Grassed Swale

Buried Tile

Surficial Drainage (i.e. furrows)

Dugout Pond


Dominated by Aquatic Veg ✓

Dry


Other Habitat Notes, Incidental Wildlife Observations, etc. frog sp.

Field Notes Authored by MF

Field Notes QA/QCed by MEE



ELUHO RA





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 421 Project Name Niagara Wind
 Watercourse Name Unknown Project # 160950269
 Photos see photo log Field Staff ME, MF
 Date 2012 06 09 Time 15:34
 Weather conditions in previous 24 hrs minor precip.
 GPS Coordinates (Zone) 17T E 629310 N 4764069 Datum NAD83
 Descriptive Location On Boyle Rd ~ 20 m south of Canborough Rd.
Channel on west side

Water Quality

Dissolved Oxygen (mg/L) 6.83 pH 8.37 Conductivity (μ S/cm) 819
 Water Temperature ($^{\circ}$ C) 24.04 Air Temperature ($^{\circ}$ C) 30.0
 Time in situ measurements taken 15:40

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.2 (m) Maximum Pool Depth 10 (cm)
 Mean Bankfull Width 2.5 (m) Mean Water Depth 5 (cm)
 % Riffle 30 % Pool 70 % Run 0 % Flat 0
 Evidence of eroding banks, Comments on bank stability minor scour

Substrate (% cover)

Bedrock 0 Cobble 20 Sand 30 Silt 20 Muck
 Boulder 0 Gravel 30 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

3% red canopy grass.
pasture, houses, rds.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn?
 Migratory Obstructions (seasonal, permanent)

maybe
 Note any fish observations None

Waterbody Notes


Natural Watercourse ☒ Trapezoidal Channel ☐ Grassed Swale ☐ Buried Tile ☐
 Surficial Drainage (i.e. furrows) ☐ Dugout Pond ☐ Dominated by Aquatic Veg ☒ Dry ☐

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by MF

Field Notes QA/QCed by MEF

22





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
10/1/12

Station # 43-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos ✓ Field Staff J. Keener, K. Clayton
 Date June 21/12 Time 8:51
 Weather conditions in previous 24 hrs Hot & humid 32°C
 GPS Coordinates (Zone) 17T E 620492 N 4764984 Datum NAD83
 Descriptive Location off of Vaughn Rd, East of Regional Rd 27

Water Quality

Dissolved Oxygen (mg/L) 1.10 pH 7.5 Conductivity (µS/cm) 443
 Water Temperature (°C) 22.85 Air Temperature (°C) 30°C
 Time *in situ* measurements taken 8:56

Watercourse Dimensions & Morphology

Mean Watercourse Width 1-3 (m) Maximum Pool Depth 0.30 (cm)
 Mean Bankfull Width 5 (m) Mean Water Depth 0.15 (cm)
 % Riffle 100 % Pool 0 % Run 100 % Flat 0
 Evidence of eroding banks, Comments on bank stability Vegetated - Stable

Substrate (% cover)

Bedrock 0 Cobble 10 Sand 40 Silt 0 Muck 0
 Boulder 0 Gravel 50 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks 0 Deep Pool 0 Watercress 0 Aquatic Veg algae
 Overhanging Vegetation 0 Woody Debris 0 Boulder 0 Other algae

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 15% Reed, Canary grass, early

Adjacent Land Use Cropland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) pot. spawning, nursery, foraging in spring

Migratory Obstructions (seasonal, permanent) permanent

Note any fish observations —

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel 0 Grassed Swale 0 Buried Tile 0
 Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg 0 Dry 0

Other Habitat Notes, Incidental Wildlife Observations, etc.

Leopard frogs very turbid water w/ lots of algae Northside
green frogs of REA flows through cropland # Southside

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME

Reed
Canary
grass



Vaughn Road





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 44-1

Watercourse Name unknown

Photos _____

Date June 20/12

Weather conditions in previous 24 hrs hot + humid

GPS Coordinates (Zone) 17T E 622021

Descriptive Location West side of Regional Rd 27, North of

Project Name Niagara Wind

Project # 160958269

Field Staff J. Keene, K. Clayton

Time 10:21

Datum NAD83

N 4765373

Vaughn Rd

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) 30°C

Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)

Mean Bankfull Width 2.5 (m) Mean Water Depth _____ (cm)

_____ % Riffle _____ % Pool _____ % Run _____ % Flat

Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 40 Sand 10 Silt _____ Muck _____

Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg

Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

85% grasses, early

Adjacent Land Use say

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

dry

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____

Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 44-2 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keene, K. Clayton
 Date June 20/12 Time 10:30
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 17T E 622021 N 4765373 Datum NAD83
 Descriptive Location off of Regional Rd 27 (East side),
north of Vaughn Rd.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 30
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 1-2 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 40 Sand 10 Silt _____ Muck _____
 Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
85%, grasses, early

Adjacent Land Use

crops - Alfalfa, soy

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
potential spawning in spring

Migratory Obstructions (seasonal, permanent)
dry

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by K Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Central Welland River
↳ unnamed creek

NON
REA

Station # 45-1 Project Name Niagara Wind
Watercourse Name Unknown Project # 160950269
Photos 9123 - 9125 Field Staff K. Clayton, J. Keene
Date June 20/12 Time 10:45
Weather conditions in previous 24 hrs hot & humid
GPS Coordinates (Zone) 624027 E 4765154 N Datum NAD83
Descriptive Location East of Turbine 76, off of Vaughn Rd ITT

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 30
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

_____ Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck
_____ Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

50% grasses, early farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by K. Clayton

Field Notes QA/QCed by JK



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Unnamed creek
to CWR

Non
REA

Station # 45-2

Watercourse Name Unknown

Photos 9126-9128

Date June 20/12

Weather conditions in previous 24 hrs not humid

GPS Coordinates (Zone) 624331 E 4765169

Descriptive Location East of 45-1, off of Vaughn Rd.

Project Name Niagara Wind

Project # 160950269

Field Staff K. Clayton, J. Keene

Time 10:45

Datum 17T Nad.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) 32

Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)

Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)

_____ % Riffle _____ % Pool _____ % Run _____ % Flat

Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

_____ Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____

_____ Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): _____ Undercut Banks _____ Deep Pool _____ Watercress _____ Aquatic Veg Typha RCG

Overhanging Vegetation _____ Woody Debris _____ Boulder _____ Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 50% Typha, early

Adjacent Land Use Agricultural land

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations dm

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____

Surficial Drainage (i.e. furrows) ✓ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by K. Clayton

Field Notes QA/QCed by JK



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 46-1
 Watercourse Name unknown
 Photos
 Date June 20/12
 Weather conditions in previous 24 hrs not humid
 GPS Coordinates (Zone) 17T E 626828
 Descriptive Location N of Vaughn Rd, west of Glee Road

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, K. Clayton
 Time 17:19
 Datum NAD83

Water Quality

Dissolved Oxygen (mg/L) - Dry
 Water Temperature (°C) pH Conductivity (µS/cm)
 Time in situ measurements taken Air Temperature (°C) 30°C

Watercourse Dimensions & Morphology

Mean Watercourse Width (m)
 Mean Bankfull Width 3m (m)
 % Riffle % Pool
 Evidence of eroding banks, Comments on bank stability % Run % Flat

Substrate (% cover)

Bedrock Cobble 10 Sand 40 Silt Muck
 Boulder Gravel 50 Clay Marl Detritus

In-water Cover

Cover Types Present (circle):
 Overhanging Vegetation Undercut Banks Deep Pool Watercress Aquatic Veg
 Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 15% grasses, early

Adjacent Land Use

Corn & soy

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) potential spawning in spring

Migratory Obstructions (seasonal, permanent) dry - seasonal

Note any fish observations

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel Grassed Swale Buried Tile
 Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Stantec

Station # 47-1 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos _____ Field Staff J. Keen, K. Clayton
 Date June 21/12 Time 15:14
 Weather conditions in previous 24 hrs _____
 GPS Coordinates (Zone) 17T E 621983 N 4766607 Datum Nad83
 Descriptive Location off of corner of Regional Rd 20 & 27

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 32°C ±
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 2 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability stable banks

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ✓ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

along side Road dominated by typha & Phragmites

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

BEA

Station # 47-2
 Watercourse Name unknown
 Photos June 21/12
 Date June 21/12
 Weather conditions in previous 24 hrs Hot & humid
 GPS Coordinates (Zone) 17T E 622651 N 4766473 Datum Nad83
 Descriptive Location off of Regional Rd 20, E of 47-1

Water Quality

- dry
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 32°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress
 Overhanging Vegetation Woody Debris Boulder Other
Aquatic Veg Phrag Typ RCG

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
100%, RCG, early

Adjacent Land Use

Residential, Road, Say

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) dry

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Stantec

Station # 47-3
 Watercourse Name unknown
 Photos _____
 Date June 21/12
 Weather conditions in previous 24 hrs _____
 GPS Coordinates (Zone) 17T E 623014 N 4766498 Datum Nad83
 Descriptive Location off of Regional Road 20, East of 47-2

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, K. Clayton
 Time 15:30

Water Quality

Dissolved Oxygen (mg/L) _____ pH -Dry Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 32°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 1.5 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress
Overhanging Vegetation Woody Debris Boulder Other _____ Aquatic Veg

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
90% Typha, early

Adjacent Land Use farmland, Road,

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) dry

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by K. Clayton

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Defined on south side
lack of definition not
less 20% DFL

Station # 48-1
Watercourse Name unknown
Photos See photo log
Date June 22/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 10:31

Weather conditions in previous 24 hrs Minor precip
GPS Coordinates (Zone) 17T E 0623407 N 4766520 Datum Nad83
Descriptive Location On R.R. 20 ~ 1 km east of R.R. 27

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 28°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.0 (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 2.0 (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 20 Silt 20 Muck _____
Boulder 10 Gravel 40 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

2% mature trees, reed canary grass
Adjacent Land Use house, roads, hay fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possible spawn
Migratory Obstructions (seasonal, permanent) _____
Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☒ Grassed Swale ☒ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by MF

Field Notes QA/QCed by MEE



Meadow



reed canary grass
lack of def'n



R.R. 20

R.R. 27
↓ ~1km

cattail / reed canary grass



MANICURED GRASS



MANICURED GRASS





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
Intermittent
well defined

Station # 49-1
Watercourse Name unknown
Photos See photo log
Date June 22/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, ME
Time 09:52

Weather conditions in previous 24 hrs minor precip.
GPS Coordinates (Zone) 17T E 0626247 N 4766926 Datum NAD83
Descriptive Location On Silverdale Rd ~ 200 m north of R.R. 20

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 25°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth 10 (cm) ← west e of culv opening
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool 100 % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability none. well veget'd.

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt 30 Muck _____
Boulder _____ Gravel 30 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

2% mature trees near by

Adjacent Land Use

ac fields, house, rds.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possible spawn

Migratory Obstructions (seasonal, permanent)

Dry - water @ west end culvert only. - East end dry

Note any fish observations none.

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. Barn swallows, green frogs, tadpoles

Field Notes Authored by MF

Field Notes QA/QCed by MEE



R.R. 20

graze

DRY

SW

RD

SILVERDALE RD.

DRY

MANICURED
GRASS

SOY



MANICURED
GRASS

CORN



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Unnamed Creek
to CWR

Nor
REA

Station # 50-1
Watercourse Name Unknown
Photos _____
Date June 20/12

Project Name Niagara Wind
Project # 11609.50269
Field Staff K. Clayton J. Keene
Time 16:00

Weather conditions in previous 24 hrs hot & humid
GPS Coordinates (Zone) 621891 E 4767594 N Datum ITN
Descriptive Location Runs north & south along Regional Rd 20 of
concession 4, west of 50-2

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 32
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

_____ Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck
_____ Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Road, farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by K. Clayton

Field Notes QA/QCed by OK



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Unnamed Creek
to CWR

Na
RE

Station # 50-2
Watercourse Name Unknown
Photos _____
Date June 20/12
Weather conditions in previous 24 hrs Hot & humid
GPS Coordinates (Zone) 622065 E 4767880 N
Descriptive Location E of Regional Rd 20, & 50-1, off of
Concession 4

Project Name Niagara Wind
Project # 100900269
Field Staff K. Clayton, J. Keene
Time 16:05

Datum NAD 83

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 30
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations dry channel

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by K. Clayton

Field Notes QA/QCed by JK



WIND FARM WATERBODY RAPID ASSESSMENT FORM

Stantec

Station # 51-31 ml.
 Watercourse Name unknown
 Photos _____
 Date June 21/12
 Weather conditions in previous 24 hrs _____
 GPS Coordinates (Zone) 17T E 621997
 Descriptive Location off of Regional Road

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, K. Clayton
 Time 15:52
 Datum NAD83

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 33°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width 4 (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress
Overhanging Vegetation Woody Debris Boulder Other _____
Aquatic Veg Typha Rc

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
100% Typha, early

Adjacent Land Use
504, Road, forest

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) dry

Note any fish observations _____

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

but Typha corridor - a little water, not enough to get 4s
ml moderately
not defined channel

Field Notes Authored by K. Clayton

Field Notes QA/QCed by MEE



WIND FARM WATERBODY RAPID ASSESSMENT FORM

REF

Stantec

Station # 52-1
 Watercourse Name unknown
 Photos _____
 Date June 21/12
 Weather conditions in previous 24 hrs Hot + humid
 GPS Coordinates (Zone) 17T E 622011
 Descriptive Location off of Regional Rd 569, near intersection of RR 20

Project Name Niagara Wind
 Project # 160958269
 Field Staff J. Keene, K. Clayton
 Time 16:03

Water Quality

Dissolved Oxygen (mg/L) 2.10 pH 8.23 Conductivity (µS/cm) 1165
 Water Temperature (°C) 25.54 Air Temperature (°C) 32.0
 Time in situ measurements taken 16:05

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.5 (m) Maximum Pool Depth 0.15 (cm)
 Mean Bankfull Width 5 (m) Mean Water Depth 0.10 (cm)
 _____ % Riffle _____ % Pool 100 % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability stable - vegetated

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt _____ Muck _____
 Boulder _____ Gravel 50 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress
Overhanging Vegetation Woody Debris Boulder Other algae Aquatic Veg
 Iris TYPE
 duckweed

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
52%, Tundra, early

Adjacent Land Use farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
spawning, nursery, foraging

Migratory Obstructions (seasonal, permanent)
permanent

Note any fish observations could be dry by end of summer

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. Turbid water

Field Notes Authored by K. Clayton

Field Notes QA/QCed by WEE



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

non REA - south

REA
use + @ culvert
only

Station # 54-1
Watercourse Name unknown
Photos See photo log
Date June 22/12

Project Name Niagara Wind
Project # 160958269
Field Staff MELMF
Time 09:34

Weather conditions in previous 24 hrs Minor precip.
GPS Coordinates (Zone) 17T E 0626245 N 4769264 Datum Nad83
Descriptive Location On Fifteen Rd ~ 300m east of Silverdale Rd

STAND
WATER
only

Water Quality

Dissolved Oxygen (mg/L) 1 pH 7 Conductivity (µS/cm) 1
Water Temperature (°C) 1 Air Temperature (°C) 24
Time in situ measurements taken 1

Watercourse Dimensions & Morphology

Mean Watercourse Width 0.6 (m) Maximum Pool Depth 0.20 (cm)
Mean Bankfull Width 1.0 (m) Mean Water Depth 0.10 (cm)
% Riffle 100 % Pool 0 % Run 0 % Flat 0
Evidence of eroding banks, Comments on bank stability mod def'n, minor scour

Substrate (% cover)

Bedrock 0 Cobble 0 Sand 40 Silt 30 Muck 0
Boulder 0 Gravel 30 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks 0 Deep Pool 0 Watercress 0 Aquatic Veg
Overhanging Vegetation 0 Woody Debris 0 Boulder 0 Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 2% reed canna grass

Adjacent Land Use ag fields, rd, farms.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) possible spawn, foliage, nursery

Migratory Obstructions (seasonal, permanent) dam @ times

Note any fish observations yes


Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel ✓ Grassed Swale 0 Buried Tile 0
Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg ✓ Dry 0

Other Habitat Notes, Incidental Wildlife Observations, etc. frog sp, tadpoles, song sparrow


Field Notes Authored by MELMF

Field Notes QA/QCed by MRE




soy bean

reed canary grass



FIFTEEN RD

Silverdale Rd



reed canary grass

v = cattail

soy bean



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

RED
DRY

Pond is ~~offering~~ flows
providing

Station # 55-1
Watercourse Name unknown
Photos See photo log
Date June 22/12
Weather conditions in previous 24 hrs Minor amounts of rain
GPS Coordinates (Zone) 17T E 0627007 N 4768151 Datum NAD83
Descriptive Location On Concession 4 ~ 800 m east of Beamer Rd.

Project Name Niagara Wind
Project # 160958269
Field Staff MF, ME
Time 08:51

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 23°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.2 (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 3.0 (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____
minor scour near road

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt 10 Muck _____
Boulder _____ Gravel 40 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
70% mature + immature trees + shrub species on both banks.
Adjacent Land Use
House, ag fields, rd.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
possible spawn.
Migratory Obstructions (seasonal, permanent)
Dries up.
Note any fish observations none.

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. Green Heron, Green Frog.
Song birds.


Field Notes Authored by MF

Field Notes QA/QCed by ME

N →

✓ cattail / reed canopy

↑
Beamer Rd
~ 800m



WOODLOT

Concession 4

Flows ↓

POND



HEDGEROW



WOODLOT



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
DRY
little definition

Station # 55-2
Watercourse Name unknown
Photos See photo log
Date June 22/12
Weather conditions in previous 24 hrs minor precip.
GPS Coordinates (Zone) 17T E 0625497 N 4768055 Datum NAD83
Descriptive Location On Con 4 ~ 600 m west of Beamer Road

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 09:18

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 23°C
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.0 (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 1.2 (m) Mean Water Depth _____ (cm)
_____% Riffle _____% Pool _____% Run _____% Flat
Evidence of eroding banks, Comments on bank stability minor scour.
50% north side 0% south side No mature trees.

Substrate (% cover)

Bedrock	Cobble	Sand	Silt	Muck
Boulder	Gravel	Clay	Marl	Detritus

50 16

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
50% north side (mature trees) 0% south side through field
Adjacent Land Use
ag field, woodlot, rd

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
possible spawn
Migratory Obstructions (seasonal, permanent)
dry
Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MF

Field Notes QA/QCed by ME

N →

Do

Mixed
woodlot

Reed cutting grass

Do

Can &

Silverdale Rd

Beaver Rd
↓



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

NON

REA

Terrestrial swale

No defin @ either end.

Station # 56-1
Watercourse Name unknown
Photos See photo log
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 15:14

Weather conditions in previous 24 hrs No rain - hot + humid
GPS Coordinates (Zone) 17T E 0628139 N 4768199 Datum NAD83
Descriptive Location On Concession 4 ~ 500 m east of Hodgking Rd.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 31°C
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

ag field, rd, house

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

none

Migratory Obstructions (seasonal, permanent)

Note any fish observations

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale ☒ Buried Tile _____
Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. bobolink

Field Notes Authored by mi

Field Notes QA/QCed by MEE



manicured
grass



reed canopy grass
no do'n

Hodgkins Rd ~ 500 ↓



Stantec

* Check w/ Katie & Joes notes

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Now
REA
Grass/Ag Swale
DRY

Station # 56-2
Watercourse Name unknown
Photos See photo log
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME/MP
Time 15:23

Weather conditions in previous 24 hrs no rain
GPS Coordinates (Zone) 17T E 0627591 N 4768237 Datum NAD83
Descriptive Location On Hodgkin Rd ~ 30 m north of Concession 4.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 31.0
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

_____ Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck
_____ Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Ag. fields, rds

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale ☒ Buried Tile _____
Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by MP

Field Notes QA/QCed by MEE



WOOD LOT

corn

ditch

Hodgkin Rd

corn

Concession 4

corn



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

N6N-REI
DRY

Station # 56-3
Watercourse Name unknown
Photos See photos log
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 13:40

Weather conditions in previous 24 hrs No rain
GPS Coordinates (Zone) 17T E 0627688 N 4768178 Datum Nad83
Descriptive Location On Concession 4 ~ 70m east of Hodgkins Rd.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (μ S/cm) _____
Water Temperature ($^{\circ}$ C) _____ Air Temperature ($^{\circ}$ C) 31 $^{\circ}$ C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) _____

Adjacent Land Use

ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

None

Migratory Obstructions (seasonal, permanent) _____

dry

Note any fish observations _____

None

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale ☒ Buried Tile _____
Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. Bobolink

Field Notes Authored by MF

Field Notes QA/QCed by MEE



Crown = well mix of Aquatic veg + Terr veg. Defined through dredging.
Holmes = Ag Field, Planted + harvested, drives through it.



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
DRY

Station # 56-4
Watercourse Name unknown
Photos See photo by
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 16:10

Weather conditions in previous 24 hrs No rain
GPS Coordinates (Zone) 17T E 0627568 N 4768098 Datum Nad83
Descriptive Location Immediately south of Concession 4 + west of Hodgkin Rd. on the Crown property

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity ($\mu\text{S}/\text{cm}$) _____
Water Temperature ($^{\circ}\text{C}$) _____ Air Temperature ($^{\circ}\text{C}$) 31°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 2.5 (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability minor undercutting

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt 30 Muck _____
Boulder _____ Gravel 30 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
0%

Adjacent Land Use

ag field, house

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
none

Migratory Obstructions (seasonal, permanent)
dry

Note any fish observations
none

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. Snake sp.

Field Notes Authored by ME

Field Notes QA/QCed by MEE

Py

Hood & Kin Road

CORN

Concession 4

BARN

HOUSE

Bean field

Possible Non-REA?

REA

HOLMES PROP.

- planted & harvested in swale

CROWN PROP.

CORN

- defn through dredging
- grass within



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

NON REA
57-1

Station # 57-1
Watercourse Name unknown
Photos See photos log
Date June 21/12
Weather conditions in previous 24 hrs no rain
GPS Coordinates (Zone) 17T E 0630072 N 4768285 Datum NAD83
Descriptive Location On Concession 4 ~ 600m east of Rosedene Rd.

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 14:02

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 31°C
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

agr field, rd

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale ☒ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

None

Field Notes Authored by MF

Field Notes QA/QCed by MCE



Rosedene Rd



~ 600m

Soy bean

Concession 4

Non
REA

meadow.



CUT FIELD



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 57-2 Project Name Niagara Wind
 Watercourse Name unknown Project # 160958269
 Photos See photo log Field Staff ME, ME
 Date June 21/12 Time 14:10
 Weather conditions in previous 24 hrs No rain - hot & humid
 GPS Coordinates (Zone) 17T E 0629477 N 4768259 Datum NAD83
 Descriptive Location On Concession 4 ~ 200m east of Rosedene Rd

Water Quality

Dissolved Oxygen (mg/L) 7.77 pH 7.75 Conductivity (µS/cm) 1517
 Water Temperature (°C) 24.30 Air Temperature (°C) 31°C
 Time *in situ* measurements taken 14:20

Watercourse Dimensions & Morphology

Mean Watercourse Width 3.5 (m) Maximum Pool Depth 20 (cm)
 Mean Bankfull Width 6.0 (m) Mean Water Depth 10 (cm)
 % Riffle 100 % Pool _____ % Run _____ % Flat _____
 Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 50 Silt 30 Muck _____
 Boulder _____ Gravel 20 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

2% reed canopy grass, mature trees
 Adjacent Land Use house, ag, rds

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn, forage, nursery
 Migratory Obstructions (seasonal, permanent) dry @ times.
 Note any fish observations none

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. many frog sp.

Field Notes Authored by ME

Field Notes QA/QCed by ME



Rosedene Rd



manicured grass

standing water

reed canary grass

reed canary grass

manicured grass

concession 4


* = various aquatic veg.

ag

standing water

reed canary grass

reed canary grass





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Standing water @ culvert openings only. well defined

Station # 57-3
Watercourse Name unknown
Photos See photo log
Date June 21/12

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 14:24

Weather conditions in previous 24 hrs no rain
GPS Coordinates (Zone) 17T E 0629269 N 4767882 Datum Nad83
Descriptive Location On Rosedene Rd ~ 300m south of Concession 4

Water Quality

Dissolved Oxygen (mg/L) 8.46 pH 8.02 Conductivity (µS/cm) 1674
Water Temperature (°C) 23.18 Air Temperature (°C) 32°C
Time in situ measurements taken 14:35

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth 10 (cm)
Mean Bankfull Width 4.0 (m) Mean Water Depth 4 (cm)
% Riffle 100 % Pool 0 % Run 0 % Flat 0
Evidence of eroding banks, Comments on bank stability minor scour

Substrate (% cover)

Bedrock 0 Cobble 0 Sand 40 Silt 30 Muck 0
Boulder 0 Gravel 30 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation 0 Woody Debris 0 Boulder 0 Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

2% seedcanary grass
Adjacent Land Use house, off-line pond, ag.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn, forage, nursery
Migratory Obstructions (seasonal, permanent)

dry
Note any fish observations none seen

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel 0 Grassed Swale 0 Buried Tile 0
Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg ✓ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. none green frogs


Field Notes Authored by MF

Field Notes QA/QCed by MEE



W. scottall
1/2 = reed canopy.

Rose dune Rd



conc. 4



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA on ea
side only.

defined banks on
east side only

DRY

Station # 98-1
Watercourse Name unknown
Photos See photo log
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 13:30

Weather conditions in previous 24 hrs no precipitation
GPS Coordinates (Zone) 17T E 0631261 N 4768314 Datum Nad83
Descriptive Location On Victoria Rd ~ 10m south of Concession 4

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 31°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 0.5 (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 1.0 (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability minor undercut banks - def. road

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 20 Silt 20 Muck _____
Boulder 20 Gravel 20 Clay _____ Marl 10 Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
0% seed canopy grass

Adjacent Land Use

ag fields, rd, house

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
none

Migratory Obstructions (seasonal, permanent)
dry

Note any fish observations none

Waterbody Notes


Natural Watercourse ☒ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

↓ seed canopy

Other Habitat Notes, Incidental Wildlife Observations, etc.


Field Notes Authored by MF

Field Notes QA/QCed by ME




REA
gravel/sand + defined

red cedar grass
red cedar grass



VICTORIA RD



NON REA

Concession 4



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

FSEM - 15 mile Creek

Non
REA

Station # 59-1
Watercourse Name Unknown
Photos —
Date June 20/13
Weather conditions in previous 24 hrs hot & humid
GPS Coordinates (Zone) 631169 E 4770090
Descriptive Location off of Victoria Avenue, N of Kilman Road

Project Name Niagara Wind
Project # 160950269
Field Staff Marc Faiella Mitchell
Time 16:30
Datum 1771 N

Water Quality

Dissolved Oxygen (mg/L) — pH — Conductivity (µS/cm) —
Water Temperature (°C) — Air Temperature (°C) 32
Time *in situ* measurements taken —

Watercourse Dimensions & Morphology

Mean Watercourse Width — (m) Maximum Pool Depth — (cm)
Mean Bankfull Width — (m) Mean Water Depth — (cm)
— % Riffle — % Pool — % Run — % Flat
Evidence of eroding banks, Comments on bank stability —

Substrate (% cover)

— Bedrock — Cobble — Sand — Silt — Muck
— Boulder — Gravel — Clay — Marl — Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other —

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use 75% grasses, early
Transmission line, farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent) dry

Note any fish observations —

Waterbody Notes

Natural Watercourse — Trapezoidal Channel — Grassed Swale — Buried Tile —
Surficial Drainage (i.e. furrows) — Dugout Pond — Dominated by Aquatic Veg — Dry —

Other Habitat Notes, Incidental Wildlife Observations, etc. —

Field Notes Authored by M. Faiella

Field Notes QA/QCed by OK



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

FSEM 15 mile Creek

Nar
REI

Station # 59-2
Watercourse Name unknown
Photos _____
Date June 20/15

Project Name Niagara Wind
Project # 0160950269
Field Staff K. Clanton, J. Keene
Time 16:39

Weather conditions in previous 24 hrs hot & humid

GPS Coordinates (Zone) 631185 E 4769867 N Datum ITM

Descriptive Location off of Victoria Avenue, West of Kilman Road
South of 59-1

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 32
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 75%, grasses, early

Adjacent Land Use farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations any

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by M. Faiella

Field Notes QA/QCed by OK



REA on
South side
Grassed swa
North side
DRY

Project Name Niagara Wind
Project # 160958269
Field Staff ME, ME
Time 13:36

Weather conditions in previous 24 hrs no rain
GPS Coordinates (Zone) 17T E 0630566 N 4768308 Datum Nad83
Descriptive Location On Concession 4 ~ 500 m west of Victoria Rd

DRY

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity ($\mu\text{S}/\text{cm}$) _____
 Water Temperature ($^{\circ}\text{C}$) _____ Air Temperature ($^{\circ}\text{C}$) 31 $^{\circ}\text{C}$
 Time *in situ* measurements taken _____

DPH

Mean Watercourse Width 0.30 (m) Maximum Pool Depth (cm)
Mean Bankfull Width 1.0 (m) Mean Water Depth (cm)
 % Riffle % Pool % Run % Flat
Evidence of eroding banks, Comments on bank stability
Scrub minor undercut on south side

Bedrock	Cobble	20	Sand	25	Silt	25	Muck
Boulder	10	Gravel	20	Clay		Marl	Detritus

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

houses, barn, rds

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations *none*

Natural Watercourse ☒ Trapezoidal Channel ☐ Grassed Swale ☒ Buried Tile ☐
 Surficial Drainage (i.e. furrows) ☐ Dugout Pond ☐ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes QA/QCed by MEE

DRY


~~N~~ →

reed
canal grass

reed
canal grass

manicured grass

manicured
grass
↑



Concession 4

VICTORIA RD



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

NON
REA

See back

Station # 58-3
Watercourse Name unknown
Photos See photo log
Date June 21/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 13:51

Weather conditions in previous 24 hrs no precipitation
GPS Coordinates (Zone) 17T E 0630494 N 4768306 Datum NAD83
Descriptive Location On Concession 4 ~ 700m west of Victoria Rd

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 31°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

none

Field Notes Authored by MF

Field Notes QA/QCed by MEE

(N →)

graze

NON-REA

DRY

meadow

REA

DRY

concession 4



NON-REA

MANICURED
↑ grass

58-3

DRY



NON-REA

58-2

POND

VICTORIA RD.



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Major watercourse
Permanent

Station # 60-1

Watercourse Name unknown

Photos see photo log

Date June 20/12

Weather conditions in previous 24 hrs no precip

GPS Coordinates (Zone) 17T E 0631123

Descriptive Location On Victoria Road ~ 500m north of Sixteen Rd

Project Name Niagara Wind

Project # 160958269

Field Staff ME, MF

Time 16:49

Water Quality

Dissolved Oxygen (mg/L) 3.44

pH 7.83

Conductivity (µS/cm) 610

Water Temperature (°C) 27.80

Air Temperature (°C) 32.0

Time *in situ* measurements taken

Watercourse Dimensions & Morphology

Mean Watercourse Width 8.0 (m)

Maximum Pool Depth ~7100 (cm)

Mean Bankfull Width 9.0 (m)

Mean Water Depth ~7100 (cm)

% Riffle 10

% Pool

% Run 90

% Flat

Evidence of eroding banks, Comments on bank stability minor undercut.

Substrate (% cover)

Bedrock Too deep Boulder Too deep Cobble Too deep Gravel Too deep Sand Too deep Clay Too deep Silt Too deep Marl Too deep Muck Too deep Detritus Too deep

In-water Cover

Cover Types Present (circle):

Overhanging Vegetation Undercut Banks Deep Pool Aquatic Veg

Woody Debris

Boulder

Other

Watercress

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

12% sparse shrubs on east + west side, some trees on west side

Adjacent Land Use

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn, forage, nursery

Migratory Obstructions (seasonal, permanent)

none observed

Note any fish observations Corp

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☐ Grassed Swale ☐ Buried Tile ☐

Surficial Drainage (i.e. furrows) ☐ Dugout Pond ☐ Dominated by Aquatic Veg ☒ Dry ☐


Other Habitat Notes, Incidental Wildlife Observations, etc. Corp (many), barn swallows

Field Notes Authored by MF

Field Notes QA/QCed by MEE




Campground
△ △ △




POOL



FLAT




meadow



VICTORIA RD

MM = RCG

meadow



FLAT



wheat



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

- former does not pour it -

- very little depth within ROW

- dry channel but standing water within culvert
- full of RCG

RCG = Reed canary grass

REA

Station # 67-1

Watercourse Name unknown

Photos See photo log

Date 2012 06 20

Weather conditions in previous 24 hrs No rain

GPS Coordinates (Zone) 17T E 0631091

Descriptive Location On Victoria ~ 800m South of Twenty Mile Rd.

Project Name Niagara Wind

Project # 160950269

Field Staff ME, MF

Time 16:35

N 4771901 Datum NAD 83

Water Quality

Dissolved Oxygen (mg/L) pH Conductivity (µS/cm)

Water Temperature (°C) Air Temperature (°C)

Time in situ measurements taken

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.5 (m) Maximum Pool Depth (cm)
Mean Bankfull Width > 20.0 (m) Mean Water Depth (cm)
% Riffle % Pool % Run % Flat
Evidence of eroding banks, Comments on bank stability none observe

Substrate (% cover)

Bedrock Cobble Sand 40 Silt 30 Muck
Boulder Gravel 30 Clay Marl Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 0%

Adjacent Land Use

ag fields, rd

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) none

Migratory Obstructions (seasonal, permanent) dry

Note any fish observations none


Waterbody Notes

Natural Watercourse Trapezoidal Channel Grassed Swale Buried Tile
Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg Dry

Other Habitat Notes, Incidental Wildlife Observations, etc. song birds

Field Notes Authored by ME

Field Notes QA/QCed by MEE





BANK

meadow sp

VICTORIA ROAD

BANK

meadow sp





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

FSEM
15 mile Creek

Nor
REA

Station # 62-1
 Watercourse Name 15 mile Creek
 Photos _____
 Date June 20/12
 Weather conditions in previous 24 hrs hot & humid
 GPS Coordinates (Zone) 629389 E 4766813 N Datum 17T1
 Descriptive Location off of Regional Rd 20, east of
Peardene Rd/15 mile Road

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 32°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by M. Faiella

Field Notes QA/QCed by TK



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

MP
NOT
REA

Station # 63-1
Watercourse Name UNKNOWN
Photos See photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, ME
Time 10:27

Weather conditions in previous 24 hrs Minor precipitation
GPS Coordinates (Zone) 17T E 0623118 N 4760378 Datum NAD83
Descriptive Location On Sideroad 42 ~ 800 m north of Concession 6, on west side of road

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Rd side ditch full of seed canary grass w spots of cattail

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent)

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale ☒ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by ME

Field Notes QA/QCed by MEE



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 63-2
 Watercourse Name unknown
 Photos See photo log
 Date 2012 06 19
 Weather conditions in previous 24 hrs minor precip
 GPS Coordinates (Zone) 17T E 0623141 N 4759987 Datum NAD83
 Descriptive Location On Side road 42 ~ 500 m north of Concession 6

Project Name Niagara Wind
 Project # 160950269
 Field Staff ME, MF
 Time 10:40

Water Quality

Dissolved Oxygen (mg/L) 10.20 pH 8.37 Conductivity (μ S/cm) 676
 Water Temperature ($^{\circ}$ C) 28.27 Air Temperature ($^{\circ}$ C) 30 $^{\circ}$ C
 Time in situ measurements taken 10:50

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.5 (m) Maximum Pool Depth 8.0 (cm)
 Mean Bankfull Width 5.0 (m) Mean Water Depth 2.0 (cm)
 % Riffle 100 % Pool 0 % Run 0 % Flat 0
 Evidence of eroding banks, Comments on bank stability none observed, well veget'd

Substrate (% cover)

Bedrock	Cobble	Sand	Silt	Muck
Boulder	Gravel	Clay	Marl	Detritus

10 40 40
10

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) 0%

Adjacent Land Use

ag, rd, house

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) forage, spawn, nursery

Migratory Obstructions (seasonal, permanent) lack of water

Note any fish observations none

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel ✓ Grassed Swale ✓ Buried Tile ✓
 Surficial Drainage (i.e. furrows) ✓ Dugout Pond ✓ Dominated by Aquatic Veg ✓ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. goldfinch

Field Notes Authored by MF

Field Notes QA/QCed by MEE



soy bean

corn

OPEN
WATER

SIDEROAD 42

↙ = cattail

= patches of emerg.
aquatic veg.

soy bean

corn



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 65-1
Watercourse Name unknown
Photos See photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 13:11

Weather conditions in previous 24 hrs minor precip
GPS Coordinates (Zone) 17T E 6623837 N 4758126 Datum NAD83
Descriptive Location Along Wellandport Rd ~ 400 m South of Conc 5

Water Quality

Dissolved Oxygen (mg/L) 4.36 pH 7.18 Conductivity (μ S/cm) 3592
Water Temperature ($^{\circ}$ C) 22.56 Air Temperature ($^{\circ}$ C) 30.2
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.5 (m) Maximum Pool Depth 25 (cm)
Mean Bankfull Width 4.0 (m) Mean Water Depth 10 (cm)
_____% Riffle _____% Pool _____% Run _____% Flat
Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt 30 Muck _____
Boulder _____ Gravel 20 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
10% mature/immature trees + shrub sp

Adjacent Land Use

agr. rds, houses

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
spawn?

Migratory Obstructions (seasonal, permanent)
lack of water

Note any fish observations none


Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MF

Field Notes QA/QCed by ME



- ### = cattail
- ||| = reed canary
- * * = duckweed/arrowhead



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 65-2
Watercourse Name unknown
Photos see photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, ME
Time 13:38

Weather conditions in previous 24 hrs minor precip.
GPS Coordinates (Zone) 17T E 0623858 N 4757235 Datum NAD83
Descriptive Location On Wellandport Rd ~ 500 m south of Conc 5

Water Quality

Dissolved Oxygen (mg/L) 4.24 pH 7.99 Conductivity (µS/cm) 913
Water Temperature (°C) 22.96 Air Temperature (°C) 30.2
Time in situ measurements taken 13:50

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth 25 (cm)
Mean Bankfull Width 10.0 (m) fixed Mean Water Depth 10 (cm)
% Riffle 100 % Pool 0 % Run 0 % Flat 0
Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock 0 Cobble 10 Sand 30 Silt 30 Muck 0
Boulder 10 Gravel 20 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks recalibrated Deep Pool Watercress 0 Aquatic Veg
Overhanging Vegetation Woody Debris 0 Boulder 0 Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

10% immature / mature tree + shrub sp.

Adjacent Land Use

Ag fields, new house

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawning / nursery

Migratory Obstructions (seasonal, permanent)

lack of water, thick w/ aquatic veg.

Note any fish observations none

Waterbody Notes


Natural Watercourse ☒ Trapezoidal Channel ☐ Grassed Swale ☐ Buried Tile ☐
Surficial Drainage (i.e. furrows) ☐ Dugout Pond ☐ Dominated by Aquatic Veg ☒ Dry ☐

Other Habitat Notes, Incidental Wildlife Observations, etc.

green frogs

Field Notes Authored by ME


Field Notes QA/QCed by MEE



new house
septic tank




reed canary




reed canary




Ag.



OLD RAIL BED



corn




OPEN WATER

REED CANARY



corn



scattail

duckweed / pond weed.

sedge sp.



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 65.3 Project Name Niagara Wind
 Watercourse Name unknown Project # 160950269
 Photos see photo log Field Staff ME, MF
 Date 2012 06 19 Time 14:09
 Weather conditions in previous 24 hrs minor precip.
 GPS Coordinates (Zone) 17T E 0623013 N 4757840 Datum NAD83
 Descriptive Location On un-maintained rd of Shaflly Rd ~ 250 m north of Con. 5

Water Quality

Dissolved Oxygen (mg/L) pH Conductivity (µS/cm)
 Water Temperature (°C) Air Temperature (°C)
 Time *in situ* measurements taken

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.5 (m) Maximum Pool Depth 30 (cm)
 Mean Bankfull Width 6.0 (m) Mean Water Depth 15 (cm)
 % Riffle 10/10 % Pool % Run % Flat
 Evidence of eroding banks, Comments on bank stability none

Substrate (% cover)

Bedrock	Cobble	<u>10</u>	Sand	<u>30</u>	Silt	<u>40</u>	Muck
Boulder	Gravel	<u>20</u>	Clay		Marl		Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

10% mature trees/shrubs, reed canary grass
 Adjacent Land Use ag.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possibly spawning
 Migratory Obstructions (seasonal, permanent)

back of water
 Note any fish observations none

Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel Grassed Swale Buried Tile
 Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg ✓ Dry


Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by MP

Field Notes QA/QCed by MEE



corn




shrubs

corn

SHARLEY RA

corn



Not sure of
flow direction



corn

-  = sedge sp
-  = algae mats.
-  = cattail
-  = reed canopy grass
-  = duckweed



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

no flow

Station # 65-4
Watercourse Name unknown
Photos See photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, ME
Time 14:24

Weather conditions in previous 24 hrs minor precip
GPS Coordinates (Zone) 17T E 06230361 N 4757316 Datum NAD83
Descriptive Location On Shafley Rd ~ 200m south of Con 5
within ROW

Water Quality

Dissolved Oxygen (mg/L) 3.10 pH 7.89 Conductivity (µS/cm) 733
Water Temperature (°C) 23.41 Air Temperature (°C) 30°C
Time in situ measurements taken 14:35

Watercourse Dimensions & Morphology

Mean Watercourse Width 3.0 (m) Maximum Pool Depth 30 (cm)
Mean Bankfull Width 7.0 (m) Mean Water Depth 20 (cm)
% Riffle 100 % Pool 0 % Run 0 % Flat 0
Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock	Cobble	Sand	Silt	Muck
Boulder	Gravel	Clay	Marl	Detritus
		<u>30</u>	<u>40</u>	
	<u>20</u>		<u>10</u>	

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

40% ash sp, elm sp, shrubs
Adjacent Land Use house, ATV trails, rds, ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawning nursery forage
Migratory Obstructions (seasonal, permanent) none observed
Note any fish observations none


Waterbody Notes

Natural Watercourse ✓ Trapezoidal Channel ✓ Grassed Swale ✓ Buried Tile ✓
Surficial Drainage (i.e. furrows) ✓ Dugout Pond ✓ Dominated by Aquatic Veg ✓ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. cardinals, green frogs

Field Notes Authored by ME

Field Notes QA/QCed by MEE



Hedgrows

meadow

ATV TRAIL

SHARLEY RD.



manicured grass



reed canopy grass

flag

✓ = sedge

••• = duck weed



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

STANDING WATER

REA on E side only
Swale on E side

Station # 66-1
Watercourse Name unknown
Photos See photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 12:18

Weather conditions in previous 24 hrs minor precip
GPS Coordinates (Zone) 17T E 0623903 N 4756462 Datum NAD83
Descriptive Location On Wellandport Rd (#4) ~ 800m north of Hwy 3

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 29°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.5 (m) Maximum Pool Depth 30 (cm)
Mean Bankfull Width 3.5 (m) Mean Water Depth 10 (cm)
% Riffle 40 % Pool 60 % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt 30 Muck _____
Boulder _____ Gravel 30 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
0%

Adjacent Land Use

ag. house

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
possible spawn

Migratory Obstructions (seasonal, permanent)
lack of water

Note any fish observations none

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MF

Field Notes QA/QCed by ME



meadow
sp

Corn

WALLAND PORT RD

Corn



= thick w cattail / frog



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 66-2
Watercourse Name UNKNOWN
Photos See photo log
Date 2012 Oct 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 12:45

Weather conditions in previous 24 hrs none

GPS Coordinates (Zone) 17T E 0623924 N 4755835 Datum NAD83

Descriptive Location On west side of Wellandport Rd (parallel) to Highway 3

Water Quality

Dissolved Oxygen (mg/L) 3.24 pH 7.95 Conductivity ($\mu\text{S/cm}$) 717
Water Temperature ($^{\circ}\text{C}$) 22.19 Air Temperature ($^{\circ}\text{C}$) 30.0
Time in situ measurements taken 12:57

Watercourse Dimensions & Morphology

Mean Watercourse Width 30 (m) Maximum Pool Depth 30 (cm)
Mean Bankfull Width 50 (m) Mean Water Depth 15 (cm)
% Riffle 100 % Pool 0 % Run 0 % Flat 0
Evidence of eroding banks, Comments on bank stability none. Well veget'd

Substrate (% cover)

Bedrock 0 Cobble 0 Sand 40 Silt 40 Muck 0
Boulder 0 Gravel 20 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation 0 Woody Debris 0 Boulder 0 Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

Adjacent Land Use

Rds, industrial buildings

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn, nursery, forage

Migratory Obstructions (seasonal, permanent)

lack of water

Note any fish observations none

Waterbody Notes

Natural Watercourse 0 Trapezoidal Channel ✓ Grassed Swale 0 Buried Tile 0
Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg ✓ Dry 0

Other Habitat Notes, Incidental Wildlife Observations, etc. Frog sp

Field Notes Authored by MF

Field Notes QA/QCed by MEE

Hwy 3

Build

Building

Mixed trees



WELLAND PORT RD.



Coln.

Lead canopy veg.

Agro-veg.

504 bean

to/poom
pot. w

Non
REA
(Ters veg throught)

22



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

BFC - North Forks Drain N
REA

Station # 67-1
Watercourse Name unknown
Photos —
Date June 20/12
Weather conditions in previous 24 hrs hot & humid
GPS Coordinates (Zone) 617552 E 4753776 N
Descriptive Location off of Hwy 3 (north of Hwy 3), west of 67-2

Project Name Niagara Wind
Project # 161950869
Field Staff M. Faircliff, M. Ellard
Time 14:42

Water Quality

Dissolved Oxygen (mg/L) — pH — Conductivity (µS/cm) —
Water Temperature (°C) — Air Temperature (°C) 32
Time in situ measurements taken —

Watercourse Dimensions & Morphology

Mean Watercourse Width — (m) Maximum Pool Depth — (cm)
Mean Bankfull Width — (m) Mean Water Depth — (cm)
— % Riffle — % Pool — % Run — % Flat
Evidence of eroding banks, Comments on bank stability —

Substrate (% cover)

Bedrock — Cobble — Sand — Silt — Muck —
Boulder — Gravel — Clay — Marl — Detritus —

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other —

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) —

Adjacent Land Use

farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) —

Migratory Obstructions (seasonal, permanent) dry

Note any fish observations —

Waterbody Notes

Natural Watercourse — Trapezoidal Channel — Grassed Swale — Buried Tile —
Surficial Drainage (i.e. furrows) — Dugout Pond — Dominated by Aquatic Veg — Dry —

Other Habitat Notes, Incidental Wildlife Observations, etc. —

Field Notes Authored by M. Faircliff

Field Notes QA/QCed by TK



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

BFC -
North Forks
Drain

Non
REA

Station # 67-2
Watercourse Name unknown
Photos _____
Date June 20/12
Weather conditions in previous 24 hrs hot & humid
GPS Coordinates (Zone) 617802 E 4753890
Descriptive Location N of Hwy 3, east of 67-1

Project Name Nidana Wind
Project # 160952269
Field Staff M. Faiella, M. Ellah
Time 14:49

Datum 17T

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 32
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

_____ Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck
_____ Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus

In-water Cover

Cover Types Present (circle): _____ Undercut Banks _____ Deep Pool _____ Watercress _____ Aquatic Veg
Overhanging Vegetation _____ Woody Debris _____ Boulder _____ Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) _____

Adjacent Land Use

farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) ☒ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by

M. Faiella

Field Notes QA/QCed by

JK



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REF

Station # 68-1
Watercourse Name unknown
Photos see photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, ME
Time 14:55

Weather conditions in previous 24 hrs minor precip
GPS Coordinates (Zone) 17T E 0620309 N 4755171 Datum NAD83
Descriptive Location On Hutchinson Rd ~ 300m north of Hwy 3

Water Quality

Dissolved Oxygen (mg/L) 8.61 pH 8.07 Conductivity (μ S/cm) 860
Water Temperature ($^{\circ}$ C) 23.11 Air Temperature ($^{\circ}$ C) 30 $^{\circ}$ C
Time in situ measurements taken 15:01

Watercourse Dimensions & Morphology

Mean Watercourse Width 3.0 (m) Maximum Pool Depth 20 (cm)
Mean Bankfull Width 7.0 (m) Mean Water Depth 15 (cm)
% Riffle 100 % Pool 0 % Run 0 % Flat 0
Evidence of eroding banks, Comments on bank stability none observed. Well veget'd

Substrate (% cover)

Bedrock 0 Cobble 10 Sand 40 Silt 40 Muck 0
Boulder 0 Gravel 10 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
15% shrubs, red canopy grass, mature tree sp. sedge
Adjacent Land Use school, rd, ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
spawn, boulder nursery

Migratory Obstructions (seasonal, permanent)
lack of water, thick veg

Note any fish observations None

Waterbody Notes

Natural Watercourse 0 Trapezoidal Channel ✓ Grassed Swale 0 Buried Tile 0
Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg ✓ Dry 0

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by ME

Field Notes QA/QCed by MEE



old ag

shrubs

HUTCHINSON RA.

AG

meadow sp

School yard

wheat

••••• = duckweed
↘ = sedge sp.
○ = open water.



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 69-1
Watercourse Name unknown
Photos See photo log
Date 2012 Nov 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 15:11

Weather conditions in previous 24 hrs minor precip
GPS Coordinates (Zone) 17T E 0620694 N 4754549 Datum NAD83
Descriptive Location On Hutchinson Rd ~ 300m south of Hwy 3

Water Quality

Dissolved Oxygen (mg/L) 3.87 pH 7.69 Conductivity (µS/cm) 754
Water Temperature (°C) 24.97 Air Temperature (°C) 30°C
Time in situ measurements taken 15:16

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth 30 (cm)
Mean Bankfull Width 7.0 (m) Mean Water Depth 15 (cm)
% Riffle 100 % Pool 0 % Run 0 % Flat 0
Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock	Cobble	<u>10</u>	Sand	<u>40</u>	Silt	<u>20</u>	Muck
Boulder	Gravel	<u>20</u>	Clay		Marl		Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

3% sparse shrubs, reed canopy

Adjacent Land Use

ag. rds

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn, forage, nursery

Migratory Obstructions (seasonal, permanent)

lack of water

Note any fish observations none

Waterbody Notes




Natural Watercourse Trapezoidal Channel Grassed Swale Buried Tile
Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg Dry

Other Habitat Notes, Incidental Wildlife Observations, etc.



Field Notes Authored by MF

Field Notes QA/QCed by ME

2
→



HUTCHINSON RD.



= thick duckweed
 = sedge sp.



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 69.2
Watercourse Name unknown
Photos See photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 15:22

Weather conditions in previous 24 hrs minor precip
GPS Coordinates (Zone) 17T E 0621122 N 4753870 Datum NAD83
Descriptive Location Along Hutchinson Rd from ~ 50 south of Hwy 3 to ~ 100 m south of Jenny Temp Rd on West Side - Runs Parallel

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 30°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth 10 (cm)
Mean Bankfull Width 4.0 (m) Mean Water Depth 5 (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability No flow. No observed erosion

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 50 Silt 30 Muck _____
Boulder _____ Gravel 10 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
40% mature + immature tree + shrub species, reed canopy
Adjacent Land Use houses, rd, ag

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
spawning, foraging, nursery
Migratory Obstructions (seasonal, permanent)
lack of water
Note any fish observations none

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by MF

Field Notes QA/QCed by MEE



Jenny Jump

aquatic veg throughout
duckweed / cattail / reed cany



HUTCHINSON RD

Cemetery

Hwy 3



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 70-1
Watercourse Name Unknown
Photos see photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 15:56

Weather conditions in previous 24 hrs hot + humid, minor precip
GPS Coordinates (Zone) 17T E 0622993 N 4755428 Datum NAD83
Descriptive Location On Twinline Runnville/Wainfleet rd ~ 800m south of Bucker Rd

Water Quality

Dissolved Oxygen (mg/L) 3.98 pH 7.93 Conductivity (µS/cm) 579
Water Temperature (°C) 23.21 Air Temperature (°C) 30.2
Time in situ measurements taken 16:03

Watercourse Dimensions & Morphology

Mean Watercourse Width 3.0 (m) Maximum Pool Depth 50 (cm)
Mean Bankfull Width 6.0 (m) Mean Water Depth 30 (cm)
% Riffle 100 % Pool 0 % Run 0 % Flat 0
Evidence of eroding banks, Comments on bank stability none observed but recent dredging on south bank

Substrate (% cover)

Bedrock 0 Cobble 0 Sand 40 Silt 40 Muck 0
Boulder 0 Gravel 20 Clay 0 Marl 0 Detritus 0

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other 0

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
50% mature/immature tree + shrub species.

Adjacent Land Use

green houses, houses.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
spawning, nursery, foraging

Migratory Obstructions (seasonal, permanent)
none observed

Note any fish observations none



Waterbody Notes

Natural Watercourse 0 Trapezoidal Channel ✓ Grassed Swale 0 Buried Tile 0
Surficial Drainage (i.e. furrows) 0 Dugout Pond 0 Dominated by Aquatic Veg ✓ Dry 0

Other Habitat Notes, Incidental Wildlife Observations, etc. 0

Field Notes Authored by MF

Field Notes QA/QCed by ME





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 71-1
Watercourse Name unknown
Photos See photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 16 22

Weather conditions in previous 24 hrs Minor precip
GPS Coordinates (Zone) 17T E 0623948 N 4755150 Datum NAD83
Descriptive Location On Hendershot Rd ~ 400m south of Hwy 3. Near farm silos

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 28°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth 8.0 (cm)
Mean Bankfull Width 5.0 (m) Mean Water Depth 5.0 (cm)
_____ % Riffle 100 % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability None

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt 30 Muck _____
Boulder _____ Gravel 20 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

3% seed canopy grass

Adjacent Land Use

ag fields, rd.

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possible spawn

Migratory Obstructions (seasonal, permanent)

lack of water, thick seed canopy grass

Note any fish observations none

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MF

Field Notes QA/QCed by MEE



As

OPEN H₂O
↑ (agitation)

reed canary grass

As

HENDERSHOT RD

manicured grass

FARM
OP.



reed canary grass

As

As



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Defined channel

REA

Station # 72-1
Watercourse Name unknown
Photos see photo log
Date 2012 06 19

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 15:37

Weather conditions in previous 24 hrs minor precip
GPS Coordinates (Zone) 17T E 0621115 N 4753895 Datum NAD83
Descriptive Location On Hutchinson Rd ~250m north of Jenny Jump Rd

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth N/A (cm)
Mean Bankfull Width 5.0 (m) Mean Water Depth N/A (cm)
N/A % Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

2% seed canopy grass, sparse shrubs

Adjacent Land Use

as, houses

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possible spawn

Migratory Obstructions (seasonal, permanent)

lack of water, thick veg.

Note any fish observations none - off row

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MF

Field Notes QA/QCed by MEE



69-2

HUTCHINSON RD

soy bean

72-1



thick with cattails.

COLA

Jenny Jump



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

DRY

Station # 73-1
Watercourse Name unknown
Photos See photo log
Date June 20/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 09:20

Weather conditions in previous 24 hrs No precip
GPS Coordinates (Zone) 17T E 0623995 N 4754257 Datum NAD83
Descriptive Location On Henderson Rd ~ 400m north of Townline Dunville/Danforth

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width 4.0 (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability None

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt 30 Muck _____
Boulder _____ Gravel 30 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

4% cattail, seed canary grass
Adjacent Land Use ag fields, houses

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possible spawn
Migratory Obstructions (seasonal, permanent)

dry @ times
Note any fish observations none - dry






Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒


Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MF

Field Notes QA/QCed by MFE



Hendryshot Rd





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

BFC - East Kelly Drain

Non R

Station # 73-2
Watercourse Name unknown
Photos _____
Date June 20/12

Project Name Niagara Wind
Project # 1
Field Staff M. Faiella, M. Ellah
Time 9:32

Weather conditions in previous 24 hrs hot & humid
GPS Coordinates (Zone) 623876E 4754036 N Datum 17T
Descriptive Location off of Township Dunnville - Wainfleet, West of Henderhot Rd, south of 73-1

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) 32°C
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
_____ % Riffle _____ % Pool _____ % Run _____ % Flat
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other Terrestrial Vegetation

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional) _____

Adjacent Land Use

farmland

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by M. Faiella

Field Notes QA/QCed by JK



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

ENDS @ C
Bank Rd
Drains
can

Station # 74-1
Watercourse Name unknown
Photos See photo log
Date June 20/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, MF
Time 10:31

Weather conditions in previous 24 hrs hot & humid

GPS Coordinates (Zone) 17T E

N

Datum Nad83

Descriptive Location On Hutchinson Rd on west side of road (parallel)
From ~600m north of Booker Rd to ~500m south of Booker Road.

Start = 17T 0621757, 4752809 END = 17T 0623609, 4749927

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 3.0 (m)

Maximum Pool Depth 10 (cm)

Mean Bankfull Width 6.0 (m)

Mean Water Depth 5 (cm)

% Riffle

100

% Pool

% Run

% Flat

Evidence of eroding banks, Comments on bank stability

each

some dredging @ northern end of

Substrate (% cover)

Bedrock _____ Cobble 10 Sand 40 Silt 40 Muck _____
Boulder _____ Gravel 10 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle):

Undercut Banks

Deep Pool

Watercress

Aquatic Veg

Overhanging Vegetation

Woody Debris

Boulder

Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

20% sumac, other shrubs, red canary grass, cat tail, pockets of mature trees

Adjacent Land Use

Rds, houses, ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn, nursery, forage

Migratory Obstructions (seasonal, permanent)

thick aquatic veg & lack of water @ times

Note any fish observations none

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. Barn swallows (20'ish)

Field Notes Authored by ME

Field Notes QA/QCed by MEF



Canal Bank Rd
~ 5 km

Possible
T₁ off row
Thick with veg.



AS

BOOKER RD

HUTCHINSON RD



AS



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

NON
REA

Station # 73-2
Watercourse Name unknown
Photos 913, 914, 915
Date June 12

Project Name Niagara Wind
Project # 160958269
Field Staff ME, ME
Time 09:40

Weather conditions in previous 24 hrs no precip
GPS Coordinates (Zone) 17T E N Datum Nad83
Descriptive Location Connected to 73-1. Located south of REA (73-1). Channel along Townline Rd. Dredged on west property as well.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
Adjacent Land Use Channel has been dredged and is dominated by young terrestrial veg

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations Dry

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by ME

Field Notes QA/QCed by ME



-Dredged
-Terrestrial veg within
73-2 cont'd
non REA

Towline Rd

73-1 REA
↓

73-2 NON REA

-Dredged
-Terr veg within



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

~~None~~ m.f.
REA
DRY

Station # 75-1
Watercourse Name unknown
Photos See photo log
Date June 20/12

Project Name Niagara Wind
Project # 160958269
Field Staff ME/MF
Time 09:53

Weather conditions in previous 24 hrs None

GPS Coordinates (Zone) 17T E 0623721 N 4752879 Datum NAD83
Descriptive Location On Booker Rd ~ 800m west of Twinline Dunville/Wainfleet

Water Quality

~~DRY~~ Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability _____

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
Channel with dogwood sp, poplar sp, sumac, red pine, other meadow sp
Adjacent Land Use _____

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) _____

Migratory Obstructions (seasonal, permanent) _____

Note any fish observations _____

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. trapezoidal channel with sedges and cattails mfp.

Field Notes Authored by mf

Field Notes QA/QCed by MEE



Wheat

Wheat

Booker Rd.

reed canny grass

Meadow Jn

Meadow sp

Wood lot
x 100 boom

plowed



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 77-1

Watercourse Name UNKNOWN

Photos See photo log

Date 2012 06 26

Weather conditions in previous 24 hrs hot & humid

GPS Coordinates (Zone) 17T E 0621224

N 4749592 Datum NAD83

Descriptive Location On Bird Rd ~ 500m north of Canal Bank Rd.
on east side of rd. (parallel)

Project Name Niagara Wind

Project # 160950269

Field Staff ME, ME

Time 13:00

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) _____

Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 1.5 (m) Maximum Pool Depth _____ (cm) DRY

Mean Bankfull Width 3.0 (m) Mean Water Depth _____ (cm)

_____ % Riffle _____ % Pool _____ % Run _____ % Flat

Evidence of eroding banks, Comments on bank stability none

Full of cattail + sedge but dry

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt 40 Muck _____
Boulder _____ Gravel 20 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg

Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

10% native trees + shrubs along riparian zone

Adjacent Land Use

ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possible spawn. Connected to feeder canal

Migratory Obstructions (seasonal, permanent)

dryer

Note any fish observations None.

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____

Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry ☒

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MP

Field Notes QA/QCed by MEE



ITE 0660 W

Full of cat hair / Argemones &
sage sp.

BIRD RD

OLD RAIL BED

Canal Bank RA



As



SW


SW

SW

SW

/// = sedge sp
||| = cut hair
... = dockweed
CORN (SW) = standing H₂O

Maintained
grass



soy bean



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

off Row. Could not properly assess. water observed.
Has been dredged but considered RBA waterbody

RE A

Station # 78-1
Watercourse Name unknown
Photos see photo log
Date 2012 06 20
Weather conditions in previous 24 hrs No precip.
GPS Coordinates (Zone) 17T E 0622481 N 4749465 Datum NAD83
Descriptive Location On Canal Bank Rd ~ 1km east of Bird Rd

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 13:38

OFF ROW

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.5 (m) Maximum Pool Depth N/A (cm)
Mean Bankfull Width _____ (m) Mean Water Depth N/A (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability none observed but recently dredged (1-2 years)

MA?

Substrate (% cover)

Bedrock _____ Cobble _____ Sand _____ Silt _____ Muck _____
Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
0%

Adjacent Land Use

ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
possible spawn. Connected to Freder Canal

Migratory Obstructions (seasonal, permanent)

Note any fish observations None - off Row

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry _____


Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by MF

Field Notes QA/QCed by ME



78-1



911#
424

COIN

fragments

81952

CANAL RD.

FEEDER CANAL



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA
CANAL

Station # 79-1

Watercourse Name unknown

Photos See photo log

Date June 20/12

Project Name Niagara Wind

Project # 160958269

Field Staff ME, ME

Time 11:12

Weather conditions in previous 24 hrs none - hot + humid

GPS Coordinates (Zone) 17T E 0622558 N 4749489 Datum NAD83

Descriptive Location On Canal Bank Rd. Canal runs along rd. Canal runs on west side of Canal Bank Rd.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____

Water Temperature (°C) _____ Air Temperature (°C) _____

Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 8.0 (m) Maximum Pool Depth >100 (cm)

Mean Bankfull Width 10.0 (m) Mean Water Depth ~50.0 (cm)

_____ % Riffle 100 % Pool _____ % Run _____ % Flat

Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 30 Silt 45 Muck _____
Boulder _____ Gravel 20 Clay _____ Marl 5 Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
40% immature/mature tree + shrub species throughout

Adjacent Land Use
Houses, rds, ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
Nursery, spawn, forage

Migratory Obstructions (seasonal, permanent)
none observed

Note any fish observations None

Waterbody Notes

Natural Watercourse ☒ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. _____

Field Notes Authored by ME

Field Notes QA/QCed by MEE



CANAL

CANAL BANK RD



Stantec

Has been dredged recently but riparian full of cattails.
Channel would have been full of cattails and will again

WIND FARM WATERBODY RAPID ASSESSMENT FORM

UMFRE A

STANDING WAT
+ DRY SP

Station # 80-1
Watercourse Name Unknown
Photos See photo log
Date 2018 06 20

Project Name Niagara Wind
Project # 160950269
Field Staff ME MP
Time 14:11

Weather conditions in previous 24 hrs no precip
GPS Coordinates (Zone) 17T E 0621309 N 4747055 Datum NAD83
Descriptive Location On Rymer Road ~ 200 m west of Dickhaut Rd.
Runs parallel with road on south side.

Water Quality

Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
Water Temperature (°C) _____ Air Temperature (°C) _____
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 0.3 (m) Maximum Pool Depth 4 (cm)
Mean Bankfull Width 3.0 (m) Mean Water Depth 2 (cm)
% Riffle _____ % Pool 100 % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability has been dredged recently

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt 40 Muck _____
Boulder _____ Gravel 20 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

10% from tree side mature trees.
Adjacent Land Use ag fields, houses

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possible spawning
Migratory Obstructions (seasonal, permanent) dry @ times
Note any fish observations none

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel MP Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. not connected to W.P.
any water bodies within 2 km Roadside ditch containing int. stream

Field Notes Authored by MP

Field Notes QA/QCed by MEE

DICKHOUT RD



CORN

RYMER RD



R11T005



⊗ = turbine



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Station # 81-1
Watercourse Name Unknown
Photos See photo log
Date 2012 06 20

Project Name Niagara Wind
Project # 160950269
Field Staff ME, MF
Time 13:52

Weather conditions in previous 24 hrs No precip
GPS Coordinates (Zone) 17T E 0621911 N 4748513 Datum NAD83
Descriptive Location On Burd Rd ~ 800m south of Canal Bank Rd

Water Quality

Dissolved Oxygen (mg/L) 3.89 pH 7.80 Conductivity (µS/cm) 987
Water Temperature (°C) 26.71 Air Temperature (°C) 27°C
Time in situ measurements taken 14:00

Watercourse Dimensions & Morphology

Mean Watercourse Width 30 (m) Maximum Pool Depth 10 (cm) STANDING WATER
Mean Bankfull Width 50 (m) Mean Water Depth 2 (cm)
% Riffle _____ % Pool _____ % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability none observed

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 40 Silt 30 Muck _____
Boulder _____ Gravel 30 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

2% cattail + meadow sp. Choked w cattails
Adjacent Land Use ag fields, rd

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

possible spawn
Migratory Obstructions (seasonal, permanent)

dry @ times
Note any fish observations none

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc.

Field Notes Authored by MF

Field Notes QA/QCed by MFE


Various aquatic veg

Standing water



Previously accessed

Cattail + duckweed throughout.



CHANNEL

BIRD RD.



|| = cattail

CANAL BANK RD



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

REA

Pockets of standing w
No flows.

Station # 83-1

Watercourse Name Unknown

Photos see photo log

Date 2012 06 26

Weather conditions in previous 24 hrs no precipitation

GPS Coordinates (Zone) 17T E 0625918

Descriptive Location On Minor Rd ~ 15 m north of Hutchinson Rd

Project Name Niagara Wind

Project # 160950269

Field Staff MEIME

Time 14:48

Datum NAD83

Water Quality

Dissolved Oxygen (mg/L) pH Conductivity (µS/cm)

Water Temperature (°C) Air Temperature (°C) 30°C

Time in situ measurements taken

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.0 (m) Maximum Pool Depth 8 (cm)

Mean Bankfull Width 8.0 (m) Mean Water Depth 4 (cm)

% Riffle 100 % Pool % Run % Flat

Evidence of eroding banks, Comments on bank stability

Substrate (% cover)

Bedrock Cobble Sand 40 Silt 30 Muck

Boulder Gravel 30 Clay Marl Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg

Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

30% mature + imature shrub + tree species.

Adjacent Land Use

res, houses, woodlot, ag. fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn (possible) forage.

Migratory Obstructions (seasonal, permanent)

dry @ times: pockets of standing water

Note any fish observations none

Waterbody Notes

Natural Watercourse Trapezoidal Channel ✓ Grassed Swale Buried Tile

Surficial Drainage (i.e. furrows) Dugout Pond Dominated by Aquatic Veg ✓ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. song birds, arrowhead, RCG

Field Notes Authored by ME

Field Notes QA/QCed by ME



83-2



Hutchinson Rd





- * = arrowhead
- ☼ = duckweed
- || = cattail
- ☼ = shrubs

MINOR RD



old access
bridge

woodlot





Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

RBA

Station # 83-2
Watercourse Name unknown
Photos see photo log
Date 2012 06 20

Project Name Niagara Wind
Project # 160950269
Field Staff ME MP
Time 19:10

Weather conditions in previous 24 hrs no precipitation - hot + humid
GPS Coordinates (Zone) 17T E 8226500 N 4749162 Datum NAD83
Descriptive Location Connects to 83-1 and continues 500 away from
Hutchinson Rd.

Water Quality

Dissolved Oxygen (mg/L) 3.04 pH 7.90 Conductivity (µS/cm) 500
Water Temperature (°C) 22.34 Air Temperature (°C) 30°C
Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width 2.5 (m) Maximum Pool Depth 1.600 (cm)
Mean Bankfull Width 10.0 (m) Mean Water Depth 30.0 (cm)
% Riffle _____ % Pool 100 % Run _____ % Flat _____
Evidence of eroding banks, Comments on bank stability none observed.

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 30 Silt 40 Muck _____
Boulder _____ Gravel 30 Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

15% wild grape, trees, shrubs

Adjacent Land Use

ag fields

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

spawn, nursery

Migratory Obstructions (seasonal, permanent)

none observed

Note any fish observations none

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel ☒ Grassed Swale _____ Buried Tile _____
Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg ☒ Dry _____

Other Habitat Notes, Incidental Wildlife Observations, etc. painted turtle

Field Notes Authored by MP

Field Notes QA/QCed by ME



SEITZ
PROPERTY



83-2



HUTCHINSON RD

MINOR RD.

83-1

* = arrowhead
i.e. = duckweed.



WIND FARM WATERBODY RAPID ASSESSMENT FORM

Stantec

Station # R11T082 Project Name Niagara Wind Farm
 Watercourse Name 2 Project # 160960269
 Photos 8059 - 8067 Field Staff Trevor Chandler, Hamish Aubrey
 Date 19 Sept 2012 Time 12:45 pm
 Weather conditions in previous 24 hrs Fine. Rain day prior
 GPS Coordinates (Zone) 17T E 06182259 N 475428960 Datum NAD 83
 Descriptive Location Corn field with watercourse 2 connecting downstream
North of Hwy 3 by approx 700m, 600m East of Crown Rd

Water Quality NA - no surface water
 Dissolved Oxygen (mg/L) _____ pH _____ Conductivity (µS/cm) _____
 Water Temperature (°C) _____ Air Temperature (°C) 17°C
 Time in situ measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width Dry (m) Maximum Pool Depth No pools - dry (cm)
 Mean Bankfull Width 2-3 (m) Mean Water Depth Dry (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability No evidence of fluvial erosion
Channel is adjacent fields are ploughed to top of bank

Substrate (% cover) → Soil

☒ Bedrock	☒ Cobble	<u>Yes - 10</u> Sand	<u>Yes - 70</u> Silt	☒ Muck
☒ Boulder	☒ Gravel	<u>Yes - 70</u> Clay	<u>Yes - 70</u> Marl	☒ Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other Dry -

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
Agricultural weeds - 60% shaded - herbaceous
 Adjacent Land Use Corn field, agricultural exotics

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings) No water, unlikely to bear fish

Migratory Obstructions (seasonal, permanent) Low - no flow

Note any fish observations No

Waterbody Notes

Natural Watercourse No Trapezoidal Channel Mostly Grassed Swale No Buried Tile Unlikely
 Surficial Drainage (i.e. furrows) No Dugout Pond No Dominated by Aquatic Veg No Dry Yes

Other Habitat Notes, Incidental Wildlife Observations, etc.

Straight trapezoidal channel,
along entire site. Channel bed does not appear to be planted
but channel is used to drain agricultural fields. Water sourced
from wetland situated north of channel. No aquatic plants

Field Notes Authored by Trevor + Hamish

Field Notes QA/QCed by ME



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Station # QL-SGR31
 Watercourse Name Spring Creek Tributary 1
 Photos 5133 5134 5140
 Date 19 Sept 2012

Project Name Niagara Wind Farm
 Project # 160960269
 Field Staff Trewer & Hamish
 Time 5:35 pm

Weather conditions in previous 24 hrs Fine - Rain, 15°C
 GPS Coordinates (Zone) 17T E 0620005 N 4775198 Datum Nad83
 Descriptive Location South Grimsby Rd 3 200 m north of Yonge St

Water Quality NA - Dry
 Dissolved Oxygen (mg/L) ✓ pH ✓ Conductivity (µS/cm) ✓
 Water Temperature (°C) ✓ Air Temperature (°C) 17°C
 Time in situ measurements taken ✓

Watercourse Dimensions & Morphology

Mean Watercourse Width Dry (m) Maximum Pool Depth ✓ (cm)
 Mean Bankfull Width ✓ (m) Mean Water Depth ✓ (cm)
✓ % Riffle ✓ % Pool ✓ % Run ✓ % Flat
 Evidence of eroding banks, Comments on bank stability ✓

Substrate (% cover)

100 Bedrock 100 Cobble 100 Sand 100 Silt ✓ Muck
✓ Boulder ✓ Gravel ✓ Clay ✓ Marl ✓ Detritus

In-water Cover

Dry
 Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other ✓

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)

30% shaded - grasses
 Adjacent Land Use Agricultural

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent) unlikely

Note any fish observations no - low flow
no

Waterbody Notes

Natural Watercourse N Trapezoidal Channel ✓ Grassed Swale N Buried Tile N
 Surficial Drainage (i.e. furrows) N Dugout Pond N Dominated by Aquatic Veg N Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc.

Box culvert - approx 6m wide - some ponded water under
culvert, otherwise channel is dry

Field Notes Authored by Hamish

Field Notes QA/QCed by MP



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Station # CL-SGR32/A Project Name Niagara Wind
 Watercourse Name Trib to Spring Creek 2 Project # 160950269
 Photos 8141-5 Field Staff Trevor Chandler & Hannah A
 Date Sept 19/12 Time 5:30
 Weather conditions in previous 24 hrs Rain
 GPS Coordinates (Zone) 17T E 0620261 N 4776015 Datum NAD83
 Descriptive Location South Grimsby Rd 3, 400m N of Con 7

Water Quality

Dissolved Oxygen (mg/L) Dry pH ✓ Conductivity (µS/cm) ✓
 Water Temperature (°C) ✓ Air Temperature (°C) 17°C
 Time *in situ* measurements taken _____

Watercourse Dimensions & Morphology

Mean Watercourse Width _____ (m) Maximum Pool Depth _____ (cm)
 Mean Bankfull Width _____ (m) Mean Water Depth _____ (cm)
 _____ % Riffle _____ % Pool _____ % Run _____ % Flat
 Evidence of eroding banks, Comments on bank stability stable

Substrate (% cover)

Bedrock _____ Cobble _____ Sand 100% Silt _____ Muck _____
 Boulder _____ Gravel _____ Clay _____ Marl _____ Detritus _____

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other _____

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
10% agric pasture/grass, early

Adjacent Land Use

agric/pasture

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)
none

Migratory Obstructions (seasonal, permanent)
Dry

Note any fish observations none

Waterbody Notes

Natural Watercourse _____ Trapezoidal Channel _____ Grassed Swale ✓ Buried Tile _____
 Surficial Drainage (i.e. furrows) _____ Dugout Pond _____ Dominated by Aquatic Veg _____ Dry ✓

Other Habitat Notes, Incidental Wildlife Observations, etc. poorly defined channel in grassy field

Field Notes Authored by Trevor Chandler Field Notes QA/QCed by MS



Stantec

WIND FARM WATERBODY RAPID ASSESSMENT FORM

Station # CL-SAR 33
 Watercourse Name Spring creek
 Photos 3146 3149
 Date 19 Sept 2012
 Weather conditions in previous 24 hrs Fine - Rain 15°C
 GPS Coordinates (Zone) 17T E 0620837 N 4776591 Datum NAD83
 Descriptive Location South Grimsley Road 3 - Fly Rd 20 m south of Fly Rd

Water Quality

NA - Dry at Culvert
 Dissolved Oxygen (mg/L) pH Conductivity (µS/cm)
 Water Temperature (°C) Air Temperature (°C) 17°C
 Time in situ measurements taken

Watercourse Dimensions & Morphology

Mean Watercourse Width 3 (m) Maximum Pool Depth ~30 (cm)
 Mean Bankfull Width ~6 (m) Mean Water Depth 5 cm (cm)
 % Riffle 100 % Pool % Run % Flat
 Evidence of eroding banks, Comments on bank stability Stable

Substrate (% cover)

Bedrock Cobble Sand 100 Silt Muck
 Boulder Gravel Clay Marl Detritus

In-water Cover

Cover Types Present (circle): Undercut Banks Deep Pool Watercress Aquatic Veg
 Overhanging Vegetation Woody Debris Boulder Other

Riparian Zone

Riparian Cover (% of watercourse shaded, dominant vegetation, mature or early successional)
70% - shaded by grasses & trees & aquatic veg

Adjacent Land Use

Rural residential, down wooded area, agricultural field

Fish Habitat Potential

Critical Habitat (spawning or nursery areas, groundwater upwellings)

Migratory Obstructions (seasonal, permanent) unlikely

Note any fish observations no no - low flow & heavily vegetated

Waterbody Notes

Natural Watercourse Trapezoidal Channel Y Grassed Swale N Buried Tile N
 Surficial Drainage (i.e. furrows) N Dugout Pond N Dominated by Aquatic Veg Y Dry N

Other Habitat Notes, Incidental Wildlife Observations, etc.

Watch the poison ing! concrete box culvert - approx 4-5 m

Field Notes Authored by Harold

Field Notes QA/QCed by MR