

ELC Polygon: #32-4 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains/potential reptile hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains/potential bat hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains/potential bat roosting features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains/potential stick nests?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--	--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



d. Coll. Title 32', Roadside ELC,
Poly S Woodland & Wildlife Habitat
Assessment Form

Field Personnel: N. Charleston

Weather Conditions:	TEMP (°C): 20	WIND: 2-3	CLOUD: 90%	PPT: —	PPT (in last 24 hrs) Rain
---------------------	------------------	--------------	---------------	-----------	------------------------------

TOPOGRAPHIC FEATURE

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: 32-5	☐ LACUSTRINE ☐ RIVERINE ☒ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☐ TABLELAND ☐ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☐ CULTURAL
	START TIME: 3:45			
	END TIME:			

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY			
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER	5-7	4	Typ ANGU > PHAARUN > Galium sp

SVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	☒	☐	☐	☐
	<10	10 - 24	25 - 50	>50

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

/EGETATION TYPE:	<i>P. dulcis</i>	CODE:	110671
------------------	------------------	-------	--------

COMPLEX		CODE:
---------	--	-------

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

(Project Manager)

ELC Polygon: # 32-5 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (*indicate on map*)

Reptile / Bat Hibernacula Features: Contains ☒ potential reptile hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (**if yes, describe in table below*)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains ☒ potential bat hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (**if yes, describe in table below*)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains ☒ potential bat roosting features?
☐-Y* / ☒-N / ☐-Unknown, no access (**if yes, describe in table below*)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains ☒ large stick nests?
☐-Y* / ☒-N / ☐-Unknown, no access (**if yes, describe in table below*)

STICK NEST(S) IDENTIFIED					
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains ☒ seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (**if yes, describe in table below*)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Coll. Tile 32', Roadside ELC,
Poly 6 Woodland & Wildlife Habitat
Assessment Form

Project Name: NRWIC

Field Personnel: N. Charlton

Weather Conditions:	TEMP (°C): 20	WIND: 2-3	CLOUD: 90%	PPT: —	PPT (in last 24 hrs): rain
---------------------	------------------	--------------	---------------	-----------	-------------------------------

TOPOGRAPHIC FEATURE		HISTORY
☐ LACUSTRINE	☐ TALUS	☒ NATURAL
☐ RIVERINE	☐ CREVICE / CAVE	
☐ BOTTOMLAND	☐ ALVAR	☐ CULTURAL
☐ TERRACE	☐ ROCKLAND	
☐ VALLEY SLOPE	☐ BEACH / BAR	
☐ TABLELAND	☐ SAND DUNE	
☒ ROLL. UPLAND	☐ BLUFF	
☐ CLIFF		

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY			
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER	5-7	4	PHALARIS

VR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

/EGETATION TYPE: <u>reed canary grass mineral meadow marsh</u>		CODE: <u>MAN 2-2</u>
COMPLEX		CODE:

Evidence of Disturbance / Notes:

borderline delineation - just over 1m on each side

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature

(Project Manager)

ELC Polygon: #32-6 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED						
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature	

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel. (519) 836-6050
Fax: (519) 836-2493

Coll. Tile 32;
Poly 7 Woodl

Roadside ELC, Woodland & Wildlife Habitat Assessment Form

Project Number: 160950269

Project Name: NRWC

Date: June 27

Field Personnel: N. Charlton

Weather Conditions:	TEMP (°C): 20	WIND: 2-3	CLOUD: 90	PPT: —	PPT (in last 24 hrs): rain
---------------------	------------------	--------------	--------------	-----------	-------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON:	TOPOGRAPHIC FEATURE		HISTORY
	START TIME:	☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☐ TABLELAND ☒ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☐ CULTURAL
	END TIME:			

STAND DESCRIPTION:

	LAYER	HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	3	QUERUBR >> QUEALSA = ACESASA
2	SUB-CANOPY	3	3	ULMAMER > CAROVAT
3	UNDERSTOREY			
4	GRD. LAYER	5-7	4	SOLIDAGO > GRASS

IT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

VR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	R	<10	R	10 - 24	O	25 - 50	N	>50
-----------------	---	-----	---	---------	---	---------	---	-----

BUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	☒ MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---	--------	------------

VEGETATION TYPE:	CODE:
------------------	-------

Fresh-moist Oak-Sugar Maple Deciduous forest	70D9-
--	-------

COMPLEX	deciduous swamp	CODE: SWD
---------	-----------------	-----------

Evidence of Disturbance / Notes:

visibility to interior low, can only see ~10m from road

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

(Project Manager)

ELC Polygon: #32-7 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐ -Y* / ☒ -N / ☐ Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seal; SI=other sign; TK=track; VO=vocalization



Coll. Title 83; Roadside ELC,
Poly 1 Woodland & Wildlife Habitat
Assessment Form

Field Personnel: N.C

POLYGON DESCRIPTION

ELC

COMMUNITY DESCRIPTION & CLASSIFICATION

END TIME: 2:15

TOPOGRAPHIC FEATURE	HISTORY
1. Topographic Feature: The area is characterized by a mix of low-lying fields and scattered trees, with a prominent line of trees running horizontally across the middle of the map.	2. Historical Context: The area is part of a larger land parcel, with a boundary line visible on the right side of the map. The land is currently owned by the State of New York.

☐ LACUSTRINE	☐ TALUS	☐ NATURAL
☐ RIVERINE	☐ CREVICE / CAVE	☒ CULTURAL
☐ BOTTOMLAND	☐ ALVAR	
☐ TERRACE	☐ ROCKLAND	
☒ VALLEY SLOPE	☐ BEACH / BAR	
☐ TABLELAND	☐ SAND DUNE	
☐ ROLL. UPLAND	☐ BLUFF	
☐ CLIFF		

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	3	3	FRAPENN
2	SUB-CANOPY	4	2	FRAPENN>
3	UNDERSTOREY			
4	GRD. LAYER	5-7	4	SOLIDAGO > GRASSES >> CENTAURUS

HT CODES: 1= $\geq 25\text{m}$ 2= $10 < \text{HT} \leq 25\text{m}$ 3= $2 < \text{HT} \leq 10\text{m}$ 4= $1 < \text{HT} \leq 2\text{m}$ 5= $0.5 < \text{HT} \leq 1\text{m}$ 6= $0.2 < \text{HT} \leq 0.5\text{m}$ 7= $\text{HT} < 0.2\text{m}$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:		<10		10 - 24		25 - 50		>50
-----------------	---	-----	---	---------	---	---------	---	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: <i>Green Ash cultural woodland</i>	CODE: <i>CWL-3*</i>
---	---------------------

	COMPLEX	CODE:
--	----------------	--------------

Evidence of Disturbance / Notes:

(10 m tall)

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒.

Signature:

(Project Manager)

ELC Polygon: #33-1 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seal; SI=other sign; TK=track; VO=vocalization



Coll. Tile 33; Roadside ELC,
Poly 2 Woodland & Wildlife Habitat
Assessment Form

Field Personnel: N. Charlton

Weather Conditions:	TEMP (°C): 22	WIND: 2-3	CLOUD: 90	PPT: —	PPT (in last 24 hrs): ✓
---------------------	------------------	--------------	--------------	-----------	----------------------------

ELC

COMMUNITY DESCRIPTION & CLASSIFICATION

END TIME:

TOPOGRAPHIC FEATURE		HISTORY
☐ LACUSTRINE	☐ TALUS	☐ NATURAL
☐ RIVERINE	☐ CREVICE / CAVE	☒ CULTURAL
☐ BOTTOMLAND	☐ ALVAR	
☐ TERRACE	☐ ROCKLAND	
☐ VALLEY SLOPE	☐ BEACH / BAR	
☐ TABLELAND	☐ SAND DUNE	
☐ ROLL. UPLAND	☐ BLUFF	
☐ CLIFF		

CANOPY

HT

HT

HT

SPECIES IN ORDER OF DECREASING DOMINANCE
(>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)

1	CANOPY			
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER	5-7	4	GRASSES = CLOVER

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: <i>Bushy</i>	CODE: <i>111A</i>
-------------------------------	-------------------

	COMPLEX		CODE:
--	---------	--	-------

Evidence of Disturbance / Notes:

- pasture/hay
- was cut this season

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒.

Signature:

(Project Manager)

ELC Polygon: # _____ Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED						
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature	

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Coll. Title 83; Roadside ELC,
Poly 3 Woodland & Wildlife Habitat
Assessment Form

Field Personnel: N. Charlton

Weather Conditions:	TEMP (°C): 22	WIND: 2-3	CLOUD: 90	PPT: —	PPT (in last 24 hrs): —
---------------------	------------------	--------------	--------------	--------	----------------------------

TOPOGRAPHIC FEATURE	HISTORY
---------------------	---------

COMMUNITY DESCRIPTION & CLASSIFICATION

END TIME:

☐ LACUSTRINE	☐ TALUS	☒ NATURAL
☐ RIVERINE	☐ CREVICE / CAVE	☐ CULTURAL
☒ BOTTOMLAND	☐ ALVAR	
☐ TERRACE	☐ ROCKLAND	
☐ VALLEY SLOPE	☐ BEACH / BAR	
☐ TABLELAND	☐ SAND DUNE	
☐ ROLL. UPLAND	☐ BLUFF	
☐ CLIFF		

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	4	FRAPENN >> QUERUBR
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER	5-7	4	ARTTRIF > PHAARUN

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
------------------------	---------	-------	---------	--------	------------

VEGETATION TYPE: <i>Green ash mineral deciduous swamp</i>		CODE: <i>SWD2-2</i>
COMPLEX		CODE:

can only see edge species

[illegible]

Signature: W. L. Chen
(Field Personnel)

ol: This form is complete ☒ & legible ☒.

Signature: *M. Katsikis*
(Project Manager)

Extent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (*indicate on map*)

Contains potential reptile hibernacula features?

[i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Contains potential bat roosting features?

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Contains large stick nests?

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Contains seeps/springs/vernal pools?

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)


CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization

V:\016084\active\160950269\planning\drawing\mxd\20120423_NHA_Fieldmaps\160950269_Release_17_ELC_Collector_Map_Book_20120613.mxd
Revised: 2012-06-14 by bcowper



Legend

- Proposed T Line Route
- Proposed Collector 120m Buffer
- Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - Potential Turbine Locations
- Turbines in Unsigned Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
- Proposed Collector Cable
- Alternate Collector Cable Route
- Preliminary Study Area
- Signed Property
- Signed Property - Outside Study Area
- Potential Signed Property
- Potential Signed Property - Outside Study Area
- ELC Boundary
- Provincially Significant Wetland
- Other/Locally Significant Wetland
- Property Boundary



Notes

- Coordinate System: NAD 1983 UTM Zone 17N.
- Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2012.



Stantec

June, 2012
160950269

Client/Project
Niagara Region Wind Corporation
Amphibian Field Maps

Figure No.
33

Title
Proposed Collector Route
Map 33

Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Stantec

Project Number: 160950269 Project Name: NRWC
Date: July 13/12 Field Personnel: M. R. 55

Weather Conditions: TEMP (°C): 28 WIND: 3 CLOUD: hazy PPT: None PPT (in last 24 hrs): None

ELC COMMUNITY DESCRIPTION & CLASSIFICATION

POLYGON: 34-1
START TIME: 10:50
END TIME: 11:15

POLYGON DESCRIPTION

TOPOGRAPHIC FEATURE	HISTORY
☐ LACUSTRINE	☐ TALUS
☐ RIVERINE	☐ CREVICE / CAVE
☐ BOTTOMLAND	☐ ALVAR
☐ TERRACE	☐ ROCKLAND
☐ VALLEY SLOPE	☐ BEACH / BAR
☐ TABLELAND	☐ SAND DUNE
☐ ROLL UPLAND	☐ BLUFF
☐ CLIFF	

☒ NATURAL
☐ CULTURAL

STAND DESCRIPTION:

LAYER	HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1 CANOPY	2	4	FRAPENN = QUERUBR = ULMAMER > ACERUB
2 SUB-CANOPY	3	4	QUERUBR = ACERUB = ULMAMER = QUERUBR
3 UNDERSTOREY	4	3	Grass Dogwood & Hawthorn
4 GRD. LAYER	5-7	3	PRAARUN & TYPLAT

HT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS: ☒ <10 ☐ 10-24 ☐ 25-50 ☒ >50

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY: ☒ PIONEER ☐ YOUNG ☒ MID-AGE ☐ MATURE ☐ OLD GROWTH

VEGETATION TYPE: F-M Oak-Maple Dec Forest CODE: FOD 9-2
Red Cherry Grass Mire CODE: MAM 2-2
Marsh

Evidence of Disturbance / Notes:

SOSP HOWR
GRFR
AMCR
COYE
BHVI
Calling from
MAM
that extends
into field

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

SPECIES CODE	LAYER				DISTANCE FROM RD.		COLL.
	1	2	3	4	≤5 m	>5 m	
TREES:							
QUERUBR	O	O					
FRAPENN	A						
ULMAMER	A	O					
W. Pine	R	O					
ACERUBR	O	O					
QUERUBR	A	O					
SHRUBS:							
Grass Dogwood			R				
Hawthorn			R				
GROUND:							
PRAARUN				A			
TYPLAT				O			
Meadowsweet				O			

Signature: _____

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐.

Signature: _____

(Project Manager)

ELC Polygon: # 37 - / Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED


UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)


(Left side of observation table)	(Right side of observation table)
----------------------------------	-----------------------------------

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization

V:\01609\Activel\60950269\planning\drawing\mxd\20120423_NHA_Fieldmaps\160950269_Release_17_ELC_Collector_Map_Book_20120613.mxd
Revised: 2012-06-14 by bbowper



- ### Legend
- Proposed T Line Route
 - Proposed Collector 120m Buffer
 - Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - Potential Turbine Locations
 - Turbines in Unsigned Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
 - Proposed Collector Cable
 - Alternate Collector Cable Route
 - Preliminary Study Area
 - Signed Property
 - Signed Property - Outside Study Area
 - Potential Signed Property
 - Potential Signed Property - Outside Study Area
 - ELC Boundary
 - Provincially Significant Wetland
 - Other/Locally Significant Wetland
 - Property Boundary



- ### Notes
- Coordinate System: NAD 1983 UTM Zone 17N.
 - Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2012.



Client/Project
Niagara Region Wind Corporation
Amphibian Field Maps

Figure No.
34

Title
Proposed Collector Route
Map 34



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

td. Coll. Tile 35; Roadside ELC,
Poly 35-1 Woodland & Wildlife Habitat
Assessment Form

Project Number: 160950269
Date: July 12/12

Project Name: NRWC
Field Personnel: M. Bass

Weather Conditions:	TEMP (°C): 23	WIND: 2	CLOUD: 	PPT: none	PPT (in last 24 hrs): none
---------------------	------------------	------------	---	--------------	-------------------------------

POLYGON DESCRIPTION

TOPOGRAPHIC FEATURE

HISTORY

☐ LACUSTRINE	☐ TALUS
☐ RIVERINE	☐ CREVICE / CAVE
☐ BOTTOMLAND	☐ ALVAR
☐ TERRACE	☐ ROCKLAND
☐ VALLEY SLOPE	☐ BEACH / BAR
☒ TABLELAND	☐ SAND DUNE
☐ ROLL. UPLAND	☐ BLUFF
☐ CLIFF	

☒ NATURAL
☐ CULTURAL

ELC

COMMUNITY DESCRIPTION & CLASSIFICATION

POLYGON: 35-1

START TIME:

END TIME:

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	3	FRAPENN
2	SUB-CANOPY	3	2	FRAPENN > ULMANER
3	UNDERSTOREY	4	3	Gray Dogwood > UTRIPA
4	GRD. LAYER	5-7	3	Solidano > TIMOTHY

IT CODES: 1= $\geq 25\text{m}$ 2= $10 < \text{HT} \leq 25\text{m}$ 3= $2 < \text{HT} \leq 10\text{m}$ 4= $1 < \text{HT} \leq 2\text{m}$ 5= $0.5 < \text{HT} \leq 1\text{m}$ 6= $0.2 < \text{HT} \leq 0.5\text{m}$ 7= $\text{HT} < 0.2\text{m}$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	R	<10	R	10 - 24	N	25 - 50	N	>50
-----------------	---	-----	---	---------	---	---------	---	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: <i>Green Ash Cultural Woodland</i>		CODE: <i>CUW1-4x</i>
COMPLEX		CODE:

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐.

Signature:

(Project Manager)

ELC Polygon: # 35-1 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

Empty space for species and habitat observations
--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



Coll. Title 35; Roadside ELC,
Poly35-2 Woodland & Wildlife Habitat
Assessment Form

Project Number: 16095026a Project Name: NREnc
Date: July 12/12 Field Personnel: M. Ross

Weather Conditions:

TEMP (°C):	WIND:	CLOUD:	PPT:	PPT (in last 24 hrs):
<u>25</u>	<u>2</u>	<u>0</u>	<u>Nine</u>	<u>None</u>

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON:	TOPOGRAPHIC FEATURE		HISTORY
	35-2	☐ LACUSTRINE ☐ RIVERINE ☒ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☐ TABLELAND ☐ ROLL UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☐ CULTURAL
	START TIME:	10:50		
	END TIME:	11:10		

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	4	FRAPENN >> SOLIV
2	SUB-CANOPY	3	3	FRAPENN > UCMAMEK
3	UNDERSTOREY	4	3	VITRIPA = Gray, Daywood
4	GRD. LAYER			N/D

HT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	---	---	---	---

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	☒ MATURE	OLD GROWTH
-----------------	---------	-------	---------	--	------------

VEGETATION TYPE: *Acid forestland Dec Forest* CODE: *FOD 7-2*

COMPLEX	Call Mike (Shallow)	CODE: MAS 2-1
---------	---------------------	---------------

Evidence of Disturbance / Notes:

BBCC
AM 60
SOSP

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐

Signature:

(Project Manager)

ELC Polygon: # 35-2 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--	--

CA=carcass; DP=distinctive parts; FE=feeding evidence; EY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Coll. Tile 35; Roadside ELC,
Poly 35-3 Woodland & Wildlife Habitat
Assessment Form

Project Number: 160950269 Project Name: NKWC
Date: July 12 12 Field Personnel: McRiss

Weather Conditions:

TEMP (°C):	WIND:	CLOUD:	PPT:	PPT (in last 24 hrs):
<u>25</u>	<u>2</u>	<u>0</u>	<u>None</u>	<u>None</u>

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: 35-3		TOPOGRAPHIC FEATURE		HISTORY
	START TIME: 11:10		☐ LACUSTRINE	☐ TALUS	☒ NATURAL
	END TIME: 11:15		☐ RIVERINE	☐ CREVICE / CAVE	☐ CULTURAL
	☒ BOTTOMLAND	☐ ALVAR			
☐ TERRACE	☐ ROCKLAND				
☐ VALLEY SLOPE	☐ BEACH / BAR				
☐ TABLELAND	☐ SAND DUNE				
☐ ROLL. UPLAND	☐ BLUFF				
☐ CLIFF					

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	3	FRAPENN = ULMAMEX
2	SUB-CANOPY	3	2	JUGN 1GR
3	UNDERSTOREY	4	2	SALIX = 6cm Dogwood = VITRIPA
4	GRD. LAYER	4-7	4	PHALARIS

HT CODES: 1= $\geq 25m$ 2= $10 < HT \leq 25m$ 3= $2 < HT \leq 10m$ 4= $1 < HT \leq 2m$ 5= $0.5 < HT \leq 1m$ 6= $0.2 < HT \leq 0.5m$ 7= $HT < 0.2m$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: <i>Green Ash Cultural Wetland</i>		CODE: <i>CuW1-4*</i>
COMPLEX		CODE:

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐

Signature:

(Project Manager)

ELC Polygon: # 35-3 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



Coll. Tile 35; Roadside ELC,
Poly 35-4 Woodland & Wildlife Habitat
Assessment Form

Project Number: 160950269 Project Name: NRWC
Date: July 12/12 Field Personnel: M. Ross

Weather Conditions:	TEMP (°C):	WIND:	CLOUD:	PPT:	PPT (in last 24 hrs).
	<u>25</u>	<u>2</u>	<u>0</u>	<u>None</u>	<u>None</u>

TOPOGRAPHIC FEATURE		HISTORY
☐ LACUSTRINE	☐ TALUS	☐ NATURAL
☐ RIVERINE	☐ CREVICE / CAVE	
☒ BOTTOMLAND	☐ ALVAR	☐ CULTURAL
☐ TERRACE	☐ ROCKLAND	
☐ VALLEY SLOPE	☐ BEACH / BAR	
☐ TABLELAND	☐ SAND DUNE	
☐ ROLL. UPLAND	☐ BLUFF	
☐ CLIFF		

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	2	
2	SUB-CANOPY	2	2	
3	UNDERSTOREY			N/O
4	GRD. LAYER	5-7	4	

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	☐	<10	☐	10 - 24	☐	25 - 50	☒	>50
-----------------	-----------------------	-----	-----------------------	---------	-----------------------	---------	----------------------------------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: Green ash Mineral Dec Swamp CODE: SW02-2

COMPLEX	Boeg Canyon Grass Min	CODE: MAM 2-2
---------	-----------------------	---------------

Evidence of Disturbance / Notes:

S, SP
AM 60
AMR0
Painted Turtle

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐.

Signature:

(Project Manager)

ELC Polygon: #35-4 Assessment Type: ☒ Visual; no access / ☐ Walk through feature

Extent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features:

Contains potential reptile hibernacula features?

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

[i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

[i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features:

Contains potential bat roosting features?

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests:

Contains large stick nests?

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools:

Contains seeps/springs/vernal pools?

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

X
--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Coll. Tile 35; Roadside ELC,
Poly 35-5 Woodland & Wildlife Habitat
Assessment Form

Project Number: 160950269 Project Name: NRWC
Date: 5/6/13 Field Personnel: M. B. S.

Date: July 12/12

Field Personnel: M. R. S.

Weather Conditions:	TEMP (°C): 25	WIND: 2	CLOUD: 0	PPT: None	PPT (in last 24 hrs): None
---------------------	------------------	------------	-------------	--------------	-------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: 35-5		TOPOGRAPHIC FEATURE		HISTORY
	START TIME: 1130	END TIME: 1140	☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☒ TABLELAND ☐ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☐ NATURAL ☒ CULTURAL

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	3	ULMAMEL > FRAPENN
2	SUB-CANOPY	3	3	ULMAMEL = FRAPENN
3	UNDERSTOREY	4	2	GRAN. dogwood - 1 Macaranga
4	GRD. LAYER	5-7	4	Shi. tree & R. ds. foot tree: 1 = Ficus. 1 = PHARON

IT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS: <10 10-24 25-50 >50

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	✓ MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	-----------	--------	------------

VEGETATION TYPE: Aspen CODE: 1

COMPLEX	CODE:
---------	-------

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature: _____
(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒.

Signature: _____

(Project Manager)

ELC Polygon: # 35-5 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED					
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization

Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Stantec

Project Number: 160950269

Project Name: NRWC

Date: 26/12/11

Field Personnel: M Rcc

Weather Conditions:	TEMP (°C): 29	WIND: 3	CLOUD: 15	PPT: None	PPT (in last 24 hrs): None
---------------------	------------------	------------	--------------	--------------	-------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON:	TOPOGRAPHIC FEATURE		HISTORY
	35-6	☐ LACUSTRINE	☐ TALUS	☐ NATURAL
	START TIME:	☐ RIVERINE	☐ CREVICE / CAVE	☒ CULTURAL
	2:40	☐ BOTTOMLAND	☐ ALVAR	
END TIME:	☐ TERRACE	☐ ROCKLAND		
	2:50	☐ VALLEY SLOPE	☐ BEACH / BAR	
		☒ TABLELAND	☐ SAND DUNE	
		☐ ROLL. UPLAND	☐ BLUFF	
		☐ CLIFF		

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	2	FRAPENN = ULMAMER
2	SUB-CANOPY	3	3	ULMAMER > FRAPENN
3	UNDERSTOREY	4	4	Gray Dogwood > Hawthorn
4	GRD. LAYER	5-7	4	Solidago > Knopweed > Teasel = Wild Cornfl

HT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:		<10		10 - 24		25 - 50		>50
-----------------	---	-----	---	---------	---	---------	---	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	☒ MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---	--------	------------

VEGETATION TYPE: 6 D 1 C 1 1 T 1 k CODE: 5 1 T 1 1

Day Logwood Wetland Thicket LOT 1-4

	COMPLEX	CODE:
--	---------	-------

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐

Signature:

(Project Manager)

ELC Polygon: # 35-6 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



Ltd. Coll. Tile 35; Roadside ELC,
ve Poly 35-7 Woodland & Wildlife Habitat
Assessment Form

Stantec

Project Number: 160950265

Project Name: MRWC

Date: July 12/12

Field Personnel: M. R. Scott

Weather Conditions:	TEMP (°C): 79°	WIND: 3	CLOUD: 20	PPT: None	PPT (in last 24 hrs): None
---------------------	-------------------	------------	--------------	--------------	-------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: 35-7	TOPOGRAPHIC FEATURE		HISTORY
		☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☐ TABLELAND ☐ ROLL, UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☐ CULTURAL
	START TIME: 2:50			
	END TIME: 3:00			

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	5	ULMAMER < FRAPENN >> Salix
2	SUB-CANOPY	3	3	ULMAMER = FRAPENN >> Salix
3	UNDERSTOREY	4	3	Gray Birchwood > ULMAMER = FRAPENN
4	GRD. LAYER	5-7	3	PHYLARON = Solid as so

HT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS: 11 <10 0 10-24 12 25-50 1 >50

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	☒ MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---	--------	------------

VEGETATION TYPE: Ad. lowland Dec. Forest CODE: FOD 7-2

	COMPLEX	CODE:
--	---------	-------

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

(Project Manager)

Extent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (*indicate on map*)

[i.e. karst topography, abandoned mines or caves]

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

1. The first part of the report discusses the importance of maintaining accurate records of all transactions, including sales, purchases, and expenses. It emphasizes the need for a systematic approach to record-keeping, such as using a ledger or accounting software, to ensure that all financial data is properly documented and organized.

2. The second part of the report focuses on the importance of regular reconciliation of accounts. It explains how reconciling accounts helps to identify discrepancies, such as errors in recording or unauthorized transactions, and ensures that the company's financial statements are accurate and reliable.

3. The third part of the report discusses the importance of budgeting and financial forecasting. It explains how creating a budget helps to plan for future financial needs, allocate resources effectively, and monitor the company's financial performance against its goals.

4. The fourth part of the report discusses the importance of maintaining proper documentation for all financial transactions. It explains how keeping accurate records of receipts, invoices, and other financial documents is essential for tax purposes, legal compliance, and internal control.

5. The fifth part of the report discusses the importance of regular financial reporting. It explains how preparing financial statements, such as the balance sheet, income statement, and cash flow statement, provides management with the information needed to make informed decisions about the company's financial health and future prospects.

REV: 2012-01-03



Coll. Tile 35;
Bly 35-8 Wood

SS, Roadside ELC, Woodland & Wildlife Habitat Assessment Form

Stantec

Project Number: 160950269

Project Name: NKWC

Date: July 12/10

Field Personnel: M. R. ET

Weather Conditions:	TEMP (°C): 29	WIND: 3	CLOUD: 20	PPT: None	PPT (in last 24 hrs): None
---------------------	------------------	------------	--------------	--------------	-------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON:	TOPOGRAPHIC FEATURE		HISTORY
	START TIME:	☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☒ TABLELAND ☐ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☐ CULTURAL

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY			
2	SUB-CANOPY	3	2	SALIX sp
3	UNDERSTOREY	4	2	SALIX sp
4	GRD. LAYER	5-7	4	PIAURUN > TYCAN/5u > Teard

HT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	---	---	---	---

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	☒ YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	---	---------	--------	------------

VEGETATION TYPE: Reed Canary Grass Mtn Meadow		CODE: MAM 2-2
COMPLEX	Mud	CODE:

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒.

Signature:

(Project Manager)

ELC Polygon: # 308 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)**Reptile / Bat Hibernacula Features:**

Contains potential reptile hibernacula features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features:

Contains potential bat roosting features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests:

Contains large stick nests?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)**STICK NEST(S) IDENTIFIED**

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools:

Contains seeps/springs/vernal pools?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)**SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED**

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--	---

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Coll. Title 35; Roadside ELC,
Poly 35-9 Woodland & Wildlife Habitat
Assessment Form

Project Number: 160950269 Project Name: NWAC
Date: Jul 4/12 Field Personnel: _____

Weather Conditions:

TEMP (°C)	WIND	CLOUD	PPT	PPT (in last 24 hrs)
<u>26°</u>	<u>5</u>	<u>Hazy</u>	<u>None</u>	<u>None</u>

ELC

COMMUNITY DESCRIPTION & CLASSIFICATION

POLYGON:	35-9	☐ LACUSTRINE	☐ TALUS	☒ NATURAL
START TIME:	9:30	☐ RIVERINE	☐ CREVICE / CAVE	☐ CULTURAL
END TIME:	9:35	☐ BOTTOMLAND	☐ ALVAR	
		☐ TERRACE	☐ ROCKLAND	
		☐ VALLEY SLOPE	☐ BEACH / BAR	
		☐ TABLELAND	☐ SAND DUNE	
		☐ ROLL, UPLAND	☐ BLUFF	
		☐ CLIFF		

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	1	ULMAMEER = FRAPENN
2	SUB-CANOPY	3	1	ULMAMEER = FRAPENN
3	UNDERSTOREY	4	3	Dogwood &
4	GRD. LAYER	4-7	4	PIAARUN > TYPLATI > Carex &

HT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	 <10	 10 - 24	 25 - 50	 >50
-----------------	---	---	---	---

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	☒ YOUNG	☐ MID-AGE	☐ MATURE	☐ OLD GROWTH
-----------------	---------	---	----------------------------------	---------------------------------	-------------------------------------

VEGETATION TYPE: Cattail Mine Shallow Marsh	CODE: MAS 2-1
---	---------------

	COMPLEX	Reed Canary Grass Mch.	CODE: MAM 2-2
--	---------	------------------------	---------------

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒.

Signature:

(Project Manager)

ELC Polygon: # 35-9 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED						
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature	

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐ -Y* / ☐ -N / ☒ -Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



id. Coll. Tie 35; Roadside ELC,
Poly 35-10 Woodland & Wildlife Habitat
Assessment Form

Project Number: 160950264 Project Name: MRWC
 Date: July 13/12 Field Personnel: M. Ross

TEMP (°C):	WIND:	CLOUD:	PPT:	PPT (in last 24 hrs):
<u>26°</u>	<u>3</u>	<u>Hazy</u>	<u>None</u>	<u>None</u>

TOPOGRAPHIC FEATURE		HISTORY
☐ LACUSTRINE	☐ TALUS	☐ NATURAL
☐ RIVERINE	☐ CREVICE / CAVE	☒ CULTURAL
☐ BOTTOMLAND	☐ ALVAR	
☐ TERRACE	☐ ROCKLAND	
☐ VALLEY SLOPE	☐ BEACH / BAR	
☒ TABLELAND	☐ SAND DUNE	
☐ ROLL UPLAND	☐ BLUFF	
☐ CLIFF		

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)			
1	CANOPY	2	1	FRAPENN = ULMAMER			
2	SUB-CANOPY	3	1	FRAPENN = ULMAMER			
3	UNDERSTOREY			N/A			
4	GRD. LAYER	5-7	4	PHEARUN = WILD CARROT > Sol. linkage = knapweed			
HT CODES:		1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m					
CVR CODES:		0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed					
STANDING SNAGS:		N		<10	N		10 - 24
		N		25 - 50	N		>50
ABUNDANCE CODES:		N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed					
STAND MATURITY:		PIONEER		YOUNG		MID-AGE	
						MATURE	
						OLD GROWTH	
VEGETATION TYPE:				D-M old field Meadow			
				CODE: CUM 1-1			
COMPLEX				CODE:			

Evidence of Disturbance / Notes:

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐

Signature:

(Project Manager)

ELC Polygon: #35-10 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

(Left side of observation area)	(Right side of observation area)
---------------------------------	----------------------------------

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Roadside ELC, Woodland & Wildlife Habitat Assessment Form

Project Name: NRWC

Field Personnel: C. P. ...

Weather Conditions:	TEMP (°C): 33	WIND: 3-4	CLOUD: 0%	PPT: none	PPT (in last 24 hrs): none
---------------------	------------------	--------------	--------------	--------------	-------------------------------

ELC

COMMUNITY DESCRIPTION & CLASSIFICATION

36-2

START TIME:

END TIME:

TOPOGRAPHIC FEATURE

HISTORY

☐ LACUSTRINE	☐ TALUS
☐ RIVERINE	☐ CREVICE / CAVE
☐ BOTTOMLAND	☐ ALVAR
☐ TERRACE	☐ ROCKLAND
☐ VALLEY SLOPE	☐ BEACH / BAR
☐ TABLELAND	☐ SAND DUNE
☐ ROLL. UPLAND	☐ BLUFF
☐ CLIFF	

☐ NATURAL
☐ CULTURAL

LAYER

HT

CVR

SPECIES IN ORDER OF DECREASING DOMINANCE
 (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)

Red oak > Bur oak > green oak = Sugar maple

1	CANOPY			Red oak > Bur oak > green ash = Sugar maple
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER			

HT CODES: 1= $\geq 25\text{m}$ 2= $10 < \text{HT} \leq 25\text{m}$ 3= $2 < \text{HT} \leq 10\text{m}$ 4= $1 < \text{HT} \leq 2\text{m}$ 5= $0.5 < \text{HT} \leq 1\text{m}$ 6= $0.2 < \text{HT} \leq 0.5\text{m}$ 7= $\text{HT} < 0.2\text{m}$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
------------------------	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 10

CODE: FGD9-1

COMPLEX

CODE:**Evidence of Disturbance / Notes:**

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Quality Control: This form is complete ☐ & legible ☐.

Signature:

(Field Personnel)

Signature:

(Project Manager)

ELC Polygon: # 36-2 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED					
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

Empty space for species and habitat observations
--

CA=carcass; DI*=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seal; SI=other sign; TK=track; VO=vocalization



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel. (519) 836-6050
Fax: (519) 836-2493

Roadside ELC, Woodland & Wildlife Habitat Assessment Form

Project Number: 160950269

Project Name: NRWC

Date: June 29, 2012

Field Personnel: C. Paul He

Weather Conditions:	TEMP (°C): 33	WIND: 3-4	CLOUD: 0%	PPT: none	PPT (in last 24 hrs) none
---------------------	------------------	--------------	--------------	--------------	------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	TOPOGRAPHIC FEATURE		HISTORY
	POLYGON: 36-1	☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☐ TABLELAND ☐ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF ☐ CLIFF
	START TIME:		
	END TIME:		

STAND DESCRIPTION:

STAND DESCRIPTION:			
LAYER	HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY		green ash > shagbark hickory > burr oak
2	SUB-CANOPY		
3	UNDERSTOREY		
4	GRD. LAYER		

HT CODES: 1= $\geq 25m$ 2= $10 < HT \leq 25m$ 3= $2 < HT \leq 10m$ 4= $1 < HT \leq 2m$ 5= $0.5 < HT \leq 1m$ 6= $0.2 < HT \leq 0.5m$ 7= $HT < 0.2m$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: green ash swamp	CODE: SWD2-2
----------------------------------	--------------

	COMPLEX	CODE:
--	----------------	--------------

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Quality Control: This form is complete ☐ & legible ☐.

Signature:

(Field Personnel)

Signature:

(Project Manager)

ELC Polygon: # 36-1 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED						
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature	

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Coll. Tile 37; Roadside ELC,
Poly I Woodland & Wildlife Habitat
Assessment Form

Project Number: 160950267

Project Name: NRWC

Date: June 28

Field Personnel: N. Charbon

Weather Conditions:	TEMP (°C): 30	WIND: 2-3	CLOUD: 50	PPT: —	PPT (in last 24 hrs): rain
---------------------	------------------	--------------	--------------	-----------	-------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: 37-1		TOPOGRAPHIC FEATURE		HISTORY
	START TIME: 5:50		☐ LACUSTRINE	☐ TALUS	☒ NATURAL
	END TIME:		☐ RIVERINE	☐ CREVICE / CAVE	☐ CULTURAL
			☐ BOTTOMLAND	☐ ALVAR	
			☐ TERRACE	☐ ROCKLAND	
			☐ VALLEY SLOPE	☐ BEACH / BAR	
			☐ TABLELAND	☐ SAND DUNE	
			☐ ROLL UPLAND	☐ BLUFF	
			☐ CLIFF		

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	4	CAROVAT > FRAX = QUERUBR > TILAMER
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER	5-7	4	Grass

HT CODES: 1= $\geq 25m$ 2= $10 < HT \leq 25m$ 3= $2 < HT \leq 10m$ 4= $1 < HT \leq 2m$ 5= $0.5 < HT \leq 1m$ 6= $0.2 < HT \leq 0.5m$ 7= $HT < 0.2m$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
------------------------	---------	-------	---------	--------	------------

VEGETATION TYPE: F-m Oak-Hickory-maple deciduous forest		CODE: FOD9
COMPLEX		CODE:

Evidence of Disturbance / Notes:

- could not ID other ground veg

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☐

Signature:

(Project Manager)

ELC Polygon: #37-1 Assessment Type: ☒-Visual; no access / ☐-Walk through feature

Extent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED					
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Coll. Title 37; Roadside ELC,
Poly 2 Woodland & Wildlife Habitat
Assessment Form

Field Personnel: N. Charlton

Her

HISTORY

☐ NATURAL
☒ CULTURAL

- young trees ~ 10 m tall
- can't see inside far, ground veg doubtful

(Project Manager)

ELC Polygon: #37-2 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED


UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)


--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



Coll. Tile 37;
Poly 3 Wood

84. Roadside ELC, Woodland & Wildlife Habitat Assessment Form

Project Number: 160950269
Date: June 28, 2012

Project Name: NKWC
Field Personnel: N. Charlton

Weather Conditions:	TEMP (°C): 30	WIND: 2-3	CLOUD: 50	PPT: —	PPT (in last 24 hrs): rain
---------------------	------------------	--------------	--------------	-----------	-------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: START TIME: END TIME:	TOPOGRAPHIC FEATURE		HISTORY
		☐ LACUSTRINE ☒ RIVERINE ☒ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☐ TABLELAND ☐ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☐ CULTURAL

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY			
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER	5-7	4	PHALARIS

HT CODES: 1= $\geq 25\text{m}$ 2= $10 < \text{HT} \leq 25\text{m}$ 3= $2 < \text{HT} \leq 10\text{m}$ 4= $1 < \text{HT} \leq 2\text{m}$ 5= $0.5 < \text{HT} \leq 1\text{m}$ 6= $0.2 < \text{HT} \leq 0.5\text{m}$ 7= $\text{HT} < 0.2\text{m}$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<i>W9142</i>	<i><10</i>	<i>0</i>	<i>10-24</i>	<i>25-50</i>	<i>>50</i>
-----------------	--------------	---------------	----------	--------------	--------------	---------------

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: reed canary grass mineral meadow marsh		CODE: MAMZ-2
COMPLEX		CODE:

Evidence of Disturbance / Notes:

- depressional area along watercourse/channel
- polygon on east side of road is a strip ~ 4 m wide

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

(Project Manager)

Extent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (*indicate on map*)

[i.e. karst topography, abandoned mines or caves]

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



d. Coll. Tile 37; Roadside ELC,
Poly 4 Woodland & Wildlife Habitat
Assessment Form

Project Name: NRWC
Field Personnel: N. Charlton

Weather Conditions:	TEMP (°C): 30	WIND: 2-3	CLOUD: 50	PPT: —	PPT (in last 24 hrs): rain
---------------------	------------------	--------------	--------------	-----------	-------------------------------

TOPOGRAPHIC FEATURE		HISTORY
☐ LACUSTRINE	☐ TALUS	☐ NATURAL
☐ RIVERINE	☐ CREVICE / CAVE	☒ CULTURAL
☐ BOTTOMLAND	☐ ALVAR	
☐ TERRACE	☐ ROCKLAND	
☐ VALLEY SLOPE	☐ BEACH / BAR	
☐ TABLELAND	☐ SAND DUNE	
☒ ROLL UPLAND	☐ BLUFF	
☐ CLIFF		

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2-3	3	ULMAMER
2	SUB-CANOPY			
3	UNDERSTOREY	4	4	Cornus
4	GRD. LAYER	1-2	4	SOLID AGG > GRASS

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: <i>ELm cultural woodland</i>		CODE: <i>CUN1-54</i>
	COMPLEX	CODE:

Evidence of Disturbance / Notes:

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☐

Signature

(Project Manager

Extent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (*indicate on map*)

Reptile / Bat Hibernacula Features:	Contains potential reptile hibernacula features? ☐ -Y* / ☐ -N / ☒ -Unknown, no access (<i>*if yes, describe in table below</i>) [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
	Contains potential bat hibernacula features? ☐ -Y* / ☐ -N / ☒ -Unknown, no access (<i>*if yes, describe in table below</i>) [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED					
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



Coll. Tile 37; Roadside ELC,
Poly S Woodland & Wildlife Habitat
Assessment Form

Field Personnel: N. Charlton

rain

HISTORY

☐ NATURAL
☒ CULTURAL**CODE:**

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

(Project Manager

ELC Polygon: #37-5 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization

ELC Polygon: #37-b Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐ -Y* / ☒ -N / ☐ Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐ -Y* / ☒ -N / ☐ Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--	--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



Coll. Title 37;
Poly 7 Wood

54. Roadside ELC, Woodland & Wildlife Habitat Assessment Form

Field Personnel: N. Chavlin

van

POLYGON DESCRIPTION

TOPOGRAPHIC FEATURE		HISTORY
☐ LACUSTRINE	☐ TALUS	☐ NATURAL
☐ RIVERINE	☐ CREVICE / CAVE	
☐ BOTTOMLAND	☐ ALVAR	☒ CULTURAL
☐ TERRACE	☐ ROCKLAND	
☐ VALLEY SLOPE	☐ BEACH / BAR	
☐ TABLELAND	☐ SAND DUNE	
☒ ROLL UPLAND	☐ BLUFF	
☐ CLIFF		

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	3	4	ELM >> A. FREE
2	SUB-CANOPY	4	2	ELM > THORNI > CAROVAT
3	UNDERSTOREY	4-5	3	Dogwood
4	GRD. LAYER	5-7	4	Solidare > Grass

HT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:		<10		10 - 24		25 - 50		>50
-----------------	---	-----	---	---------	---	---------	---	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	☒ YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	---	---------	--------	------------

VEGETATION TYPE: *slm cultural woodland* CODE: *C1W1-5**

	COMPLEX		CODE:
--	---------	--	-------

Evidence of Disturbance / Notes:

- thin strip in front of #8

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

This form is complete ☒ & legible

Nataheana
(Project Manager)

Extent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (*indicate on map*)

[i.e. karst topography, abandoned mines or caves]

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

REV: 2012-01-03



Coll. Tile 37; Roadside ELC,
Poly 8 Woodland & Wildlife Habitat
Assessment Form

Field Personnel: N. Chachon

Weather Conditions:	TEMP (°C): 30	WIND: 2-3	CLOUD: 50	PPT: —	PPT (in last 24 hrs): rain
---------------------	------------------	--------------	--------------	-----------	-------------------------------

HISTORY

ELC

COMMUNITY DESCRIPTION & CLASSIFICATION

END TIME:

☐ LACUSTRINE
☐ RIVERINE
☐ BOTTOMLAND
☐ TERRACE
☐ VALLEY SLOPE
☐ TABLELAND
☒ ROLL. UPLAND
☐ CLIFF

☐ TALUS
☐ CREVICE / CAVE
☐ ALVAR
☐ ROCKLAND
☐ BEACH / BAR
☐ SAND DUNE
☐ BLUFF

☐ NATURAL
☒ CULTURAL

LAYER

HT

CVR

SPECIES IN ORDER OF DECREASING DOMINANCE
 (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)

1	CANOPY	3	4	PINSTR()
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER			

HT CODES: 1= $\geq 25\text{m}$ 2= $10 < \text{HT} \leq 25\text{m}$ 3= $2 < \text{HT} \leq 10\text{m}$ 4= $1 < \text{HT} \leq 2\text{m}$ 5= $0.5 < \text{HT} \leq 1\text{m}$ 6= $0.2 < \text{HT} \leq 0.5\text{m}$ 7= $\text{HT} < 0.2\text{m}$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	N/A	<10	10 - 24	25 - 50	>50
-----------------	-----	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE:	C	CODE:	GUR-7
------------------	---	-------	-------

CODE: CUP 3-2

	COMPLEX		CODE:
--	---------	--	-------

Evidence of Disturbance / Notes:

can't see well from road at all
cup ~~o cup~~

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

(Project Manager)

ELC Polygon: #37-8 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)**Reptile / Bat Hibernacula Features:**

Contains potential reptile hibernacula features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features:

Contains potential bat roosting features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests:

Contains large stick nests?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)**STICK NEST(S) IDENTIFIED**

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools:

Contains seeps/springs/vernal pools?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)**SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED**

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)


--	--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization

V:\01609\Active\160950269\planning\drawing\map\20120423_NHA_Fldmap\160950269_Release_17_ELC_Collector_Map_Book_20120613.mxd
Revised 2012-06-14 by bowper



- ### Legend
- Proposed T Line Route
 - Proposed Collector 120m Buffer
 - Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - Potential Turbine Locations
 - Turbines in Unsigned Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
 - Proposed Collector Cable
 - Alternate Collector Cable Route
 - Preliminary Study Area
 - Signed Property
 - Signed Property - Outside Study Area
 - Potential Signed Property
 - Potential Signed Property - Outside Study Area
 - ELC Boundary
 - Provincially Significant Wetland
 - Other/Locally Significant Wetland
 - Property Boundary



- ### Notes
- Coordinate System: NAD 1983 UTM Zone 17N.
 - Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2012.

June, 2012
160950269

Client/Project
Niagara Region Wind Corporation
Amphibian Field Maps

Figure No.
37

Title
Proposed Collector Route
Map 37

ELC Polygon: # 38 - [Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)**Reptile / Bat Hibernacula Features:**

Contains potential reptile hibernacula features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features:

Contains potential bat roosting features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests:

Contains large stick nests?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)**STICK NEST(S) IDENTIFIED**

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools:

Contains seeps/springs/vernal pools?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)**SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED**

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

Content for Species & Habitat Observations
--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Stantec

Project Number: 160950269

Project Name: NPWC

Date: July 12/12

Field Personnel: M. Ross

Weather Conditions: TEMP (°C): 22 WIND: 2-3 CLOUD: 0 PPT: None PPT (in last 24 hrs): None

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: <u>38-2</u>	☐ LACUSTRINE	☐ TALUS	☒ NATURAL
	START TIME: <u>12:05</u>	☐ RIVERINE	☐ CREVICE / CAVE	☐ CULTURAL
	END TIME:	☐ BOTTOMLAND	☐ ALVAR	
		☐ TERRACE	☐ ROCKLAND	
		☐ VALLEY SLOPE	☐ BEACH / BAR	
		☐ TABLELAND	☐ SAND DUNE	
		☐ ROLL UPLAND	☐ BLUFF	
		☐ CLIFF		

STAND DESCRIPTION:

LAYER	HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (> MUCH GREATER THAN; > GREATER THAN; = ABOUT EQUAL TO)
1 CANOPY	<u>2</u>	<u>3</u>	<u>FRAPENN = ULMAMER > ACERUBR > POPTREM</u>
2 SUB-CANOPY	<u>3</u>	<u>4</u>	<u>ULMAMER = FRAPENN > ACERUBR > TILAMER</u>
3 UNDERSTOREY	<u>4</u>	<u>3</u>	<u>Gray Dogwood > Hawthorn</u>
4 GRD. LAYER	<u>5-7</u>	<u>2</u>	<u>PHARUN = Solidago sp</u>

HT CODES: 1=>25m 2=10<HT<25m 3=2<HT<10m 4=1<HT<2m 5=0.5<HT<1m 6=0.2<HT<0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR<10% 2=10<CVR<25% 3=25<CVR<60% 4=CVR>60% N/O=not observed

STANDING SNAGS: ☒ <10 ☐ 10-24 ☒ 25-50 ☒ >50

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY: ☒ PIONEER ☐ YOUNG ☒ MID-AGE ☐ MATURE ☐ OLD GROWTH

VEGETATION TYPE: Ash lowland Deciduous Forest CODE: FOD7-2

COMPLEX: Reed Canopy Grass Msh. Meadow Marsh CODE: MIAM2-2

Evidence of Disturbance / Notes:

Difficult to see understory

COYE AMRE
SOSP TUVV
AMRO GRCA
GRFR
EAKI
NOCA
WOTH

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

SPECIES CODE	LAYER				DISTANCE FROM RD.		COLL.
	1	2	3	4	≤5 m	>5 m	
TREES:							
ACERUBR	O	O					
FRAPENN	A	A					
W. Pine	R						
ULMAMER	A	A					
POPTREM	R-O						
TILAMER		R					
JUGNIGR			R				
SHRUBS:							
Gray Dogwood			A	A			
Hawthorn			O				
GROUND:							
PHARUN				O			
Solidago				O			

Signature: _____

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐.

Signature: _____

(Project Manager)

Extent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (*indicate on map*)

[i.e. karst topography, abandoned mines or caves]

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

REV: 2012-01-03



Coll. Tile 38; Roadside ELC,
Poly 38-3 Woodland & Wildlife Habitat
Assessment Form

Stantec

Project Number: 160950269

Project Name: MEWR

Date: July 12/12

Field Personnel: M. Pass

Weather Conditions:	TEMP (°C): 29	WIND: 3	CLOUD: 15	PPT: None	PPT (in last 24 hrs): None
---------------------	------------------	------------	--------------	--------------	-------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON:	TOPOGRAPHIC FEATURE		HISTORY
	38-3	☐ LACUSTRINE	☐ TALUS	☒ NATURAL
	START TIME:	☐ RIVERINE	☐ CREVICE / CAVE	☐ CULTURAL
	2:00	☐ BOTTOMLAND	☐ ALVAR	
	END TIME:	☐ TERRACE	☐ ROCKLAND	
		☐ VALLEY SLOPE	☐ BEACH / BAR	
		☒ TABLELAND	☐ SAND DUNE	
		☐ ROLL. UPLAND	☐ BLUFF	
	☐ CLIFF			

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	4	QUERUBR = FRAPIN = ULMAMETC > QUERMAC
2	SUB-CANOPY	3	3	
3	UNDERSTOREY	4	2	Gray Dogwood
4	GRD. LAYER			N/D

HT CODES: 1= $\geq 25\text{m}$ 2= $10 < \text{HT} \leq 25\text{m}$ 3= $2 < \text{HT} \leq 10\text{m}$ 4= $1 < \text{HT} \leq 2\text{m}$ 5= $0.5 < \text{HT} \leq 1\text{m}$ 6= $0.2 < \text{HT} \leq 0.5\text{m}$ 7= $\text{HT} < 0.2\text{m}$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:		<10		10 - 24		25 - 50		>50
-----------------	---	-----	---	---------	---	---------	---	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	✓ MID-AGE	✓ MATURE	OLD GROWTH
-----------------	---------	-------	-----------	----------	------------

VEGETATION TYPE: D-F Oak-Hickory Dec. Forest	CODE: FOD2-2
--	--------------

	COMPLEX		CODE: SWD
--	---------	--	-----------

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature

(Project Manager)

ELC Polygon: #38-3 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (**if yes, describe in table below*)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (**if yes, describe in table below*)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒-Unknown, no access (**if yes, describe in table below*)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (**if yes, describe in table below*)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (**if yes, describe in table below*)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



Coll. Tile 38;
Poly 38-4 Wood

86, Roadside ELC, Woodland & Wildlife Habitat Assessment Form

Stantec

Project Number: 160950269
Date: July 12/12

Project Name: NRWC
Field Personnel: M. Ross

Weather Conditions:	TEMP (°C): 29	WIND: 3	CLOUD: 15	PPT: None	PPT (in last 24 hrs): None
---------------------	------------------	------------	--------------	--------------	-------------------------------

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: START TIME: END TIME:	TOPOGRAPHIC FEATURE		HISTORY
		☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☐ TABLELAND ☐ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☐ CULTURAL

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY			
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER	4-7	4	PHOARUN = TYPLAT1 > Wild Carrot

HT CODES: 1= $\geq 25\text{m}$ 2= $10 < \text{HT} \leq 25\text{m}$ 3= $2 < \text{HT} \leq 10\text{m}$ 4= $1 < \text{HT} \leq 2\text{m}$ 5= $0.5 < \text{HT} \leq 1\text{m}$ 6= $0.2 < \text{HT} \leq 0.5\text{m}$ 7= $\text{HT} < 0.2\text{m}$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS: ☒ <10 ☒ 10-24 ☒ 25-50 ☒ >50

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	☒ YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	---	---------	--------	------------

VEGETATION TYPE: <i>Cattail / Emergent / Shallow Marsh</i>		CODE: <i>MAS 2-1</i>
COMPLEX		CODE:

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

(Project Manager)

ELC Polygon: # 38-4 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED


UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)


--


CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization

V:\160950269\Planning\drawing\20120423_NHA_Fieldmaps\160950269_Release_17_ELC_Collector_Map_Book_20120613.mxd
Revised: 2012-06-14 By: bcowper



Legend

- Proposed T Line Route
- Proposed Collector 120m Buffer
- Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - Potential Turbine Locations
- Turbines in Unsigned Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
- Proposed Collector Cable
- Alternate Collector Cable Route
- Preliminary Study Area
- Signed Property
- Signed Property - Outside Study Area
- Potential Signed Property
- Potential Signed Property - Outside Study Area
- ELC Boundary
- Provincially Significant Wetland
- Other/Locally Significant Wetland
- Property Boundary



Notes

- Coordinate System: NAD 1983 UTM Zone 17N.
- Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2012.



Stantec

June, 2012
160950269

Client/Project

Niagara Region Wind Corporation
Amphibian Field Maps

Figure No.
38

Title

Proposed Collector Route
Map 38



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Stantec

Project Number: 160150269 Project Name: N2WC
Date: July 13/12 Field Personnel: MRSS
Weather Conditions: TEMP (°C): 30 WIND: 3-4 CLOUD: 15 PPT: None PPT (in last 24 hrs): None

**Coll. Tile 39; Roadside ELC,
Poly 1 Woodland & Wildlife Habitat
Assessment Form**

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: <u>39-1</u>	☐ LACUSTRINE	☐ TALUS	☒ NATURAL
	START TIME: <u>2:15</u>	☐ RIVERINE	☐ CREVICE / CAVE	☐ CULTURAL
	END TIME: <u>2:30</u>	☐ BOTTOMLAND	☐ ALVAR	
		☐ TERRACE	☐ ROCKLAND	
		☐ VALLEY SLOPE	☐ BEACH / BAR	
		☐ TABLELAND	☐ SAND DUNE	
		☐ ROLL UPLAND	☐ BLUFF	
		☐ CLIFF		

STAND DESCRIPTION:

LAYER	HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1 CANOPY	2	3	FRAXINUS = QUERCUS > ACESASA = ACERULX
2 SUB-CANOPY	3	4	QUERCUS = FAGGRAN
3 UNDERSTOREY	4	3	FRAXINUS 2 ACESASA > Hawthorn
4 GRD. LAYER	5-7	3	Avers sp = Rubus sp = RUBALLEG > Grass sp

HT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS: 11 <10 11 10-24 11 25-50 11 >50

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY: 11 PIONEER 11 YOUNG 11 MID-AGE 11 MATURE 11 OLD GROWTH

VEGETATION TYPE: F-M Oak-Sugar Maple Dec CODE: FOD 9-1
COMPLEX: Forest CODE:

Evidence of Disturbance / Notes:

AMPO BCCH
GRCA
WOTH
GCFL

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

SPECIES CODE	LAYER				DISTANCE FROM RD.		COLL.
	1	2	3	4	≤5 m	>5 m	
TREES:							
ULMAMEX	R-O						
FRAXINUS	A		O				
ACESASA	O		O				
ACERULX	O						
QUERCUS	A						
QUERCUS		R-O					
FAGGRAN		R-O					
W. Pine	R						
SHRUBS:							
Hawthorn sp			R				
GROUND:							
Avers sp				O			
Silphago				R-O			
Grass sp				O			
RUBALLEG				R			
PHARUN							

Signature: _____

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐.

Signature: _____

(Project Manager)

ELC Polygon: # 39-1 Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)


SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization

V:\01609\Activet160950269\planning\drawing\mxd\20120423_NHA_Fieldmaps160950269_Release_17_ELC_Collector_Map_Book_20120613.mxd
Revised: 2012-06-14 By: bowper



Legend

- Proposed T Line Route
- Proposed Collector 120m Buffer
- Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - Potential Turbine Locations
- Turbines in Unsigned Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
- Proposed Collector Cable
- Alternate Collector Cable Route
- Preliminary Study Area
- Signed Property
- Signed Property - Outside Study Area
- Potential Signed Property
- Potential Signed Property - Outside Study Area
- ELC Boundary
- Provincially Significant Wetland
- Other/Locally Significant Wetland
- Property Boundary

Notes

- Coordinate System: NAD 1983 UTM Zone 17N.
- Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2012.

June, 2012
160950269

Client/Project

Niagara Region Wind Corporation
Amphibian Field Maps

Figure No.

39

Title

Proposed Collector Route
Map 39



Coll. Tile 40; Roadside ELC,
Poly 40-1 Woodland & Wildlife Habitat
Assessment Form

Weather Conditions:	TEMP (°C): 28	WIND: 3	CLOUD: Hazy	PPT: None	PPT (in last 24 hrs): None
---------------------	------------------	------------	----------------	--------------	-------------------------------

ELC

POLYGON:	40-1	☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☒ TABLELAND ☐ ROLL UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☐ CULTURAL
START TIME:	11:45			
END TIME:	11:55			

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY	2	2	FRAPENN > ULMANER >> SALIX
2	SUB-CANOPY	3	3	FRAPENN > ULMANER = ACENEGU > AC
3	UNDERSTOREY	4	4	Silky Dogwood = Gray Dogwood = VITRIPA
4	GRD. LAYER	5-2		SHADOWN

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	0	<10	0	10 - 24		25 - 50		>50
-----------------	---	-----	---	---------	--	---------	--	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	☒ MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---	--------	------------

VEGETATION TYPE: Ash, birch, & Dec. Forest CODE: EOD 7-2

	COMPLEX		CODE:
--	---------	--	-------

Evidence of Disturbance / Notes:

COYE
SOSP
NORL
BLJA
GRCA
AM60

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

Signature:

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☐.

Signature:

(Project Manager)

ELC Polygon: # 40 / Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒ Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization

V:\01609\Activel\60950269\planning\drawing\mxd\20120423_NHA_Fieldmaps\160950269_Release_17_ELC_Collector_Map_Book_20120613.mxd
Revised: 2012-06-14 By: bowper



Legend

- Proposed T Line Route
- Proposed Collector 120m Buffer
- Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - Potential Turbine Locations
- Turbines in Unsigned Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
- Proposed Collector Cable
- Alternate Collector Cable Route
- Preliminary Study Area
- Signed Property
- Signed Property - Outside Study Area
- Potential Signed Property
- Potential Signed Property - Outside Study Area
- ELC Boundary
- Provincially Significant Wetland
- Other/Locally Significant Wetland
- Property Boundary

Notes


- Coordinate System: NAD 1983 UTM Zone 17N.
- Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2012.

June, 2012
160950269

Client/Project
Niagara Region Wind Corporation
Amphibian Field Maps

Figure No.
40

Title
Proposed Collector Route
Map 40





Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Coll. Title 42; Roadside ELC,
Poly 1 Woodland & Wildlife Habitat
Assessment Form

Project Number: 160950269 Project Name: NKWC
Date: July 13/12 Field Personnel: M. Rossi

Weather Conditions:

TEMP (°C):	WIND:	CLOUD:	PPT:	PPT (in last 24 hrs):
<u>29</u>	<u>3</u>	<u>Hazy</u>	<u>None</u>	<u>None</u>

POLYGON DESCRIPTION

		TOPOGRAPHIC FEATURE		HISTORY
ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON:	42-1	☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☒ TABLELAND ☐ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF
	START TIME:	12:25		☒ NATURAL ☐ CULTURAL
	END TIME:	12:30		

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY		1	U. MAMEY = FRAPENUN
2	SUB-CANOPY			ACERUOK
3	UNDERSTOREY	4	2	Gray Dogwood > Hawthorn > ACERUOK
4	GRD. LAYER	5-7	4	PHAKUN = BROVIN = Amps = Solidago

IT CODES: 1= $\geq 25\text{m}$ 2= $10 < \text{HT} \leq 25\text{m}$ 3= $2 < \text{HT} \leq 10\text{m}$ 4= $1 < \text{HT} \leq 2\text{m}$ 5= $0.5 < \text{HT} \leq 1\text{m}$ 6= $0.2 < \text{HT} \leq 0.5\text{m}$ 7= $\text{HT} < 0.2\text{m}$

SVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS: ☒ N ☐ <10 ☒ 1 ☐ 10-24 ☒ N ☐ 25-50 ☒ 1 ☐ >50

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	------------------	---------	--------	------------

VEGETATION TYPE: D-M old Field Meadow		CODE: CUM 1-1
COMPLEX		CODE:

Evidence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒.

Signature

(Project Manager)

ELC Polygon: #42-1 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED					
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization

V:\01609\0160950269\planning\drawing\mxd\20120423_NHA_Fieldmaps\160950269_Release_17_ELC_Collector_Map_Book_20120613.mxd
Revised: 2012-06-14 By: bawper



Legend

- Proposed T Line Route
- Proposed Collector 120m Buffer
- Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - Potential Turbine Locations
- Turbines in Unsigned Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
- Proposed Collector Cable
- Alternate Collector Cable Route
- Preliminary Study Area
- Signed Property
- Signed Property - Outside Study Area
- Potential Signed Property
- Potential Signed Property - Outside Study Area
- ELC Boundary
- Provincially Significant Wetland
- Other/Locally Significant Wetland
- Property Boundary

ELC done

Notes

- Coordinate System: NAD 1983 UTM Zone 17N.
- Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2012.

Client/Project
Niagara Region Wind Corporation
Amphibian Field Maps


Figure No.
42

Title
Proposed Collector Route
Map 42

June, 2012
160950269

6244
COP
MOKIN

!





d. Coll. Tile 44; Roadside ELC,
Poly 1 Woodland & Wildlife Habitat
Assessment Form

Project Name: NRWC

Field Personnel: N. Charlton

rain

TOPOGRAPHIC FEATURE

COMMUNITY DESCRIPTION & CLASSIFICATION

END TIME:

CVR

SPECIES IN ORDER OF DECREASING DOMINANCE
(>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)

1	CANOPY			
2	SUB-CANOPY	3-4	3	LILAC > ACESASA

3	UNDERSTOREY			
4	GRD. LAYER	S-7	4	Grasses > DIPFULL = SOLID AGRO

HT CODES: 1>=25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1= $0\% < \text{CVR} \leq 10\%$ 2= $10 < \text{CVR} \leq 25\%$ 3= $25 < \text{CVR} \leq 60\%$ 4= $\text{CVR} > 60\%$ N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
-----------------	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: LILAC Cultural Thicket CODE: CUT1-8*

COMPLEX

CODE:

Evidence of Disturbance / Notes:

35% woody cover

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒.

Signature:

(Project Manager)

ELC Polygon: # 44-1 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED			
UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED							
UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED						
UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature	

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED						
UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

Empty space for observations

CA=carcass; DI=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Stantec Consulting Ltd.
1 – 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Coll. Title 44; ~~Project~~ ELC,
Poly 2 Woodland & Wildlife Habitat
Assessment Form

Project Number: 160950269

Project Name: NRWC

Date: June 27

Field Personnel: AL Charlton

Weather Conditions:

TEMP (°C):

WIND:

CLOUD:

PPT:

PPT (in last 24 hrs):

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: 44-2	☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☐ TABLELAND ☒ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☐ CULTURAL
	START TIME: 5:00 pm			
END TIME:				

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY			
2	SUB-CANOPY			
3	UNDERSTOREY	3-4	2	SPIALBA > ROSA SP > SAMRACE
4	GRD. LAYER	4-7	4	TYPLATI > PHAARUN > Juncus sp

HT CODES: 1= $\geq 25\text{m}$ 2= $10 < \text{HT} \leq 25\text{m}$ 3= $2 < \text{HT} \leq 10\text{m}$ 4= $1 < \text{HT} \leq 2\text{m}$ 5= $0.5 < \text{HT} \leq 1\text{m}$ 6= $0.2 < \text{HT} \leq 0.5\text{m}$ 7= $\text{HT} < 0.2\text{m}$

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

STANDING SNAGS:	<10	A	10 - 24	25 - 50	>50
-----------------	-----	---	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: <i>cattail/mineral shallow marsh</i>		CODE: <i>MAJ2-1</i>
COMPLEX		CODE:

Evidence of Disturbance / Notes:

- snags abound at edges
- moist, but no H_2O
- ring of SPIALBA

- adjacent FOD is almost pure elm (<10-24 PPH)
+ JUNIPER [young]

+ avenus
ALLPETI
Solidago } 2 category

Form used because it is an edge assessment

Edge of proper

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

(Project Manager)

ELC Polygon: #44-2 Assessment Type: ☐-Visual; no access / ☒-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains/potential reptile hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains/potential bat hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains/potential bat roosting features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains/potential large stick nests?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains/potential seeps/springs/vernal pools?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--	--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HQ=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



44, Roadside ELC,
Woodland & Wildlife Habitat
Assessment Form

Project Name: NRWC
Field Personnel: N. Charlton

Weather Conditions:	TEMP (°C): 30	WIND: 2-3	CLOUD: 90	PPT: —	PPT (in last 24 hrs): Rain
---------------------	------------------	--------------	--------------	-----------	-------------------------------

TOPOGRAPHIC FEATURE		HISTORY
☐ LACUSTRINE	☐ TALUS	☒ NATURAL
☐ RIVERINE	☐ CREVICE / CAVE	
☐ BOTTOMLAND	☐ ALVAR	☐ CULTURAL
☐ TERRACE	☐ ROCKLAND	
☐ VALLEY SLOPE	☐ BEACH / BAR	
☐ TABLELAND	☐ SAND DUNE	
☒ ROLL UPLAND	☐ BLUFF	
☐ CLIFF		

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY			
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER	47	4	TYPANGU

STANDING SNAGS:	<i>N</i>	☐	☒ <10	☐ 10 - 24	☐ 25 - 50	☐ >50
-----------------	----------	--------------------------	---	----------------------------------	----------------------------------	--------------------------------

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: <i>Cattail mineral shallow marsh</i>		CODE: <i>MA52-1</i>
COMPLEX		CODE:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

(Project Manager)

ELC Polygon: #44-3 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

(This area is for listing species and types of observations.)	(This area is for indicating observations on a map.)
---	--

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization

ELC Polygon: #44-4 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)

Reptile / Bat Hibernacula Features: Contains potential reptile hibernacula features?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)
 [i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]
 Contains potential bat hibernacula features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features: Contains potential bat roosting features?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)
 [i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests: Contains large stick nests?
☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

STICK NEST(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools: Contains seeps/springs/vernal pools?
☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

(Left side of observation table)	(Right side of observation table)
----------------------------------	-----------------------------------

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



**44, Roadside ELC,
Woodland & Wildlife Habitat
Assessment Form**

Coll. Tile 44;
Poly S Wood

Field Personnel: N. Charlton

ms ✓

HISTORY

ELC

COMMUNITY DESCRIPTION & CLASSIFICATION

END TIME:

SPECIES IN ORDER OF DECREASING DOMINANCE
 (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)

4	GRD. LAYER
---	------------

CVR CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/O=not observed

>50

served

OLD GROW

CODE:

CUM 1-1

COMPLEX

CODE:

Evidence of Disturbance / Notes:

almost cut (dogwood < 1m tall)

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☐ & legible ☒

Signature:

(Project Manager)

ELC Polygon: # 44-5 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)**Reptile / Bat Hibernacula Features:**

Contains potential reptile hibernacula features?

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

[i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

[i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features:

Contains potential bat roosting features?

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests:

Contains large stick nests?

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)**STICK NEST(S) IDENTIFIED**

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools:

Contains seeps/springs/vernal pools?


☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)**SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED**

UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--	--


CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=scat; SI=other sign; TK=track; VO=vocalization



Legend

- Proposed T Line Route
- Proposed Collector 120m Buffer
- Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - Potential Turbine Locations
- Turbines in Unsigned Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
- Proposed Collector Cable
- Alternate Collector Cable Route
- Preliminary Study Area
- Signed Property
- Signed Property - Outside Study Area
- Potential Signed Property
- Potential Signed Property - Outside Study Area
- ELC Boundary
- Provincially Significant Wetland
- Other/Locally Significant Wetland
- Property Boundary

ELC done



Notes

1. Coordinate System: NAD 1983 UTM Zone 17N.
2. Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2012.



Stantec

June, 2012
100950269

Client/Project

Niagara Region Wind Corporation
Amphibian Field Maps

Figure No.

45

Title

Proposed Collector Route
Map 45



ELC Polygon: # 46- / Assessment Type: ☒ Visual; no access / ☐ Walk through featureExtent of Physical Investigation of Feature: ☐ Entire / ☐ Partial, walk through polygon (indicate on map)**Reptile / Bat Hibernacula Features:**

Contains potential reptile hibernacula features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features:

Contains potential bat roosting features?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests:

Contains large stick nests?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)**STICK NEST(S) IDENTIFIED**

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools:

Contains seeps/springs/vernal pools?

☐ -Y* / ☐ -N / ☒ Unknown, no access (*if yes, describe in table below)**SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED**


UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

--	--


CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization

V:\01609\Map\160950269\planning\drawing\mxd\20120423_NHA_Fieldmaps\160950269_Release_17_ELC_Collector_Map_Book_20120613.mxd
Revised: 2012-06-14 by: bawpwr



Legend

- Proposed T Line Route
- Proposed Collector 120m Buffer
- Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - Potential Turbine Locations
- Turbines in Unsigned Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
- Proposed Collector Cable
- Alternate Collector Cable Route
- Preliminary Study Area
- Signed Property
- Signed Property - Outside Study Area
- Potential Signed Property
- Potential Signed Property - Outside Study Area
- ELC Boundary
- Provincially Significant Wetland
- Other/Locally Significant Wetland
- Property Boundary



Notes

- Coordinate System: NAD 1983 UTM Zone 17N.
- Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2012.



Stantec

June, 2012
160950269

Client/Project

Niagara Region Wind Corporation
Amphibian Field Maps

Figure No.

46

Title

Proposed Collector Route
Map 46

0 100 200 m
1:5,000



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel: (519) 836-6050
Fax: (519) 836-2493

Woodland & Wildlife Habitat Assessment Form

Project Number: 16 04 50269

Project Name: N RWC

Date: Aug 15, 2012

Field Personnel: NC, AO

Weather Conditions:

TEMP (°C):

25

WIND:

3-4

CLOUD:

40 %

DDT:

111.

PRT (in last 24 hrs)

—

POLYGON DESCRIPTION

		TOPOGRAPHIC FEATURE		HISTORY	
ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON:	47-1	☐ LACUSTRINE	☐ TALUS	☐ NATURAL
	START TIME:		☐ RIVERINE	☐ CREVICE / CAVE	☐ CULTURAL
	END TIME:		☐ BOTTOMLAND	☐ ALVAR	
			☐ TERRACE	☐ ROCKLAND	
			☐ VALLEY SLOPE	☐ BEACH / BAR	
			☐ TABLELAND	☐ SAND DUNE	
			☐ ROLL. UPLAND	☐ BLUFF	
		☐ CLIFF			

NAME AND DESCRIPTION:

LAYER	HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
CANOPY			
SUB-CANOPY			
UNDERSTOREY			
GRD. LAYER	5-7	4	PHARAEUS >> DAURUS = DIPUS

* CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m
/R CODES: 0=NONE 1=0%<CVR≤10% 2=10<CVR≤25% 3=25<CVR≤60% 4=CVR>60% N/A=not observed

ANDING SNAGS:		<10	10 - 24	25 - 50	>50
---------------	---	-----	---------	---------	-----

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

AND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
---------------	---------	-------	---------	--------	------------

VEGETATION TYPE: Barro Colorado Island CODE: 110310-2

COMPLEX	CODE:
---------	-------

idence of Disturbance / Notes:

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒.

Signature:

(Project Manager

ELC Polygon: #47-1 Assessment Type: ☒-Visual; no access / ☐-Walk through featureExtent of Physical Investigation of Feature: ☐-Entire / ☐-Partial, walk through polygon (indicate on map)**Reptile / Bat Hibernacula Features:**

Contains potential reptile hibernacula features?

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

[i.e. features that would provide a route underground, including buried concrete or rock (e.g. foundations, bridge abutments or culverts with cracks/entry points, exposed rock crevices or inactive animal burrows)]

Contains potential bat hibernacula features?

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)

[i.e. karst topography, abandoned mines or caves]

POTENTIAL HIBERNACULA FEATURE(S) IDENTIFIED

UTM	Feature Description	Photo No.	Spp. Observed Using Feature

Bat Roosting Features:

Contains potential bat roosting features?

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)

[i.e. tall trees with open surroundings, DBH >25cm, side-facing cavities ~10m high in tree]

POTENTIAL BAT ROOSTING FEATURE(S) IDENTIFIED

UTM	Tree ID	Tree Spp.	DBH	Photo No.	Decay Class (1-5)	No. of Cavities	Height and Type of Cavities

Stick Nests:

Contains large stick nests?

☐-Y* / ☒-N / ☐-Unknown, no access (*if yes, describe in table below)**STICK NEST(S) IDENTIFIED**

UTM	Tree ID	Tree Spp.	Nest Size	Photo No.	Spp. Observed Using Feature

Seeps/Springs/Vernal Pools:


Contains seeps/springs/vernal pools?

☐-Y* / ☐-N / ☒-Unknown, no access (*if yes, describe in table below)**SEEP / SPRING / VERNAL POOL FEATURE(S) IDENTIFIED**


UTM	Feature No. & Type	Feature Size (Diameter)	Water Depth	Photo No.	Sub/Emergent Veg. Spp. Present?	Shrubs/ Logs at Edge Present?

SPECIES & HABITAT OBSERVATIONS (list species and type of observation & indicate on map)

CA=carcass; DP=distinctive parts; FE=feeding evidence; FY=eggs/nest; HO=house/den; OB=observed; SC=seat; SI=other sign; TK=track; VO=vocalization



- ### Legend
- Turbines in Signed Lands
 - Standard Turbine (105 dBA)
 - 51 m Turbine Setback
 - Non-Participating Receptor
 - Participating Receptor
 - Proposed Collector Cable
 - Preliminary Study Area
 - Signed Property
 - Signed Property - Outside Study Area
 - Potential Signed Property
 - Potential Signed Property - Outside Study Area
 - ELC Boundary
 - Provincially Significant Wetland
 - Other/Locally Significant Wetland
 - Property Boundary
 - Non-Participating Receptors 550m Setback
 - Turbine and Access Road 150m buffer



- ### Notes
- Coordinate System: NAD 1983 UTM Zone 17N.
 - Base features produced under license with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2011.



Client/Project
Niagara Region Wind Corporation
ELC Delineation

Figure No.
47
Title
Transmission and Collector Line Map: 47

MEM
Community



Stantec Consulting Ltd.
1 - 70 Southgate Drive
Guelph, ON
Canada N1G 4P5
Tel. (519) 836-6050
Fax: (519) 836-2493

Coll. Tile 48;
Qty 1 Wo

Roadside ELC, Woodland & Wildlife Habitat Assessment Form

Project Number: 160950269

Project Name: NRWC

Date: June 28

Field Personnel: N. Charlton

Weather Conditions:

TEMP (°C):

30

WIND:

2-3

CLOUD:

70

PPT:

PPT (in last 24 hrs):

rain

POLYGON DESCRIPTION

ELC COMMUNITY DESCRIPTION & CLASSIFICATION	POLYGON: 48-1	☐ LACUSTRINE ☐ RIVERINE ☐ BOTTOMLAND ☐ TERRACE ☐ VALLEY SLOPE ☐ TABLELAND ☒ ROLL. UPLAND ☐ CLIFF	☐ TALUS ☐ CREVICE / CAVE ☐ ALVAR ☐ ROCKLAND ☐ BEACH / BAR ☐ SAND DUNE ☐ BLUFF	☒ NATURAL ☒ CULTURAL
	START TIME: 2:35			
	END TIME:			

STAND DESCRIPTION:

LAYER		HT	CVR	SPECIES IN ORDER OF DECREASING DOMINANCE (>>MUCH GREATER THAN; >GREATER THAN; = ABOUT EQUAL TO)
1	CANOPY			
2	SUB-CANOPY			
3	UNDERSTOREY			
4	GRD. LAYER	5-7	4	Grasses > ASCSYRI > PIPFULL = ERIGERON

HT CODES: 1=>25m 2=10<HT≤25m 3=2<HT≤10m 4=1<HT≤2m 5=0.5<HT≤1m 6=0.2<HT≤0.5m 7=HT<0.2m

CVR CODES: 0=NONE 1= $0\% < \text{CVR} \leq 10\%$ 2= $10 < \text{CVR} \leq 25\%$ 3= $25 < \text{CVR} \leq 60\%$ 4= $\text{CVR} > 60\%$ N/O=not observed

STANDING SNAGS:	<10	10 - 24	25 - 50	>50
61				

ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT N/O=Not observed

STAND MATURITY:	PIONEER	YOUNG	MID-AGE	MATURE	OLD GROWTH
-----------------	---------	-------	---------	--------	------------

VEGETATION TYPE: 4200 1 CODE: CHM1-1

dry-moist old field meadow		CHN 1-1
COMPLEX	reed-canary grass mineral	CODE: MA M2-2

Evidence of Disturbance / Notes:

RWBB using MAM, which is mainly confined to western half

LAYERS: 1=CANOPY >10m 2=SUB-CANOPY 3=UNDERSTOREY 4=GROUND (GRD.) LAYER
ABUNDANCE CODES: N=NONE R=RARE O=OCCASIONAL A=ABUNDANT D=DOMINANT N/O=Not observed

[illegible]

Signature:

e: Wahle
(Field Personnel)

Quality Control: This form is complete ☒ & legible ☒

Signature:

This form is complete ☒ & legible ☒.

Nataheana
(Project Manager)